November 2018 CBA10677 v11

English Heritage

ARBORICULTURAL DEVELOPMENT STATEMENT

Site: Marble Hill House and Park



East Lodge, Leylands Business Park, Colden Common, Winchester, SO21 1TH Tel: 023 8098 6229 Email: info@cbatrees.co.uk www: cbatrees.co.uk The Complete Arboricultural Consultancy



ARBORICULTURAL DEVELOPMENT STATEMENT

Arboricultural Implications Assessment and Method Statement guided by recommendations within BS5837:2012

Client:	English Heritage
Site:	Marble Hill House and Park
Arboricultural Consultant:	Stefan Rose BSc (Hons), TechCert (Arbor.A), TechArborA
Date:	November 2018

SUMMARY

There are development proposals to improve the existing café facilities at the park within the stable block area, improve the play facilities adjacent to the stable block and reinstate the landscaping around Marble Hill House and down towards the River Thames. The proposals aim to balance the historic significance of the site with the environmental potential of the park and an enhanced offer for a broader audience of park users; together these themes will enable a sustainable future for Marble Hill House Park to be developed. The impact of these works have been assessed broadly in accordance with BS5837:2012 *"Trees in Relation to Design, Demolition and Construction – Recommendations"*.

This Arboricultural Development Statement (ADS) will demonstrate the protection measures for the trees and should be read in association with the Tree Protection Plans CBA10677.02G TPP and CBA10677.03B TPP and the Tree Retention and Removal Plan CBA10677.04I TRP that identifies tree protection, removal and retention measures. It follows the initial tree survey and implications assessment.

The emphasis of the report is predominantly that of preservation and tree protection. It identifies methodologies to provide protection for trees, to ensure their healthy and safe retention during and post development, as guided by BS5837:2012 and current best practice.

The tree survey exercise identified 66 (sixty six) individual trees and 24 (twenty four) groups of trees. Within these groups, 234 (two hundred and thirty four) trees were considered worthy of note. The development works focus on three areas of the park; improving the existing café facilities within the stable block area; improving the play facilities adjacent to the stable block and reinstating the landscaping around Marble Hill House and down to the River Thames.

Improvements to the café facilities at the stable block will require the removal of 5 (five) noted trees within Group 3 (G3.48, G3.49, G3.50, G3.51 and G3.53).

Improvements to the play area adjacent to the stable block do not require any trees to be removed as a direct result of the works. One poor quality tree (T21) will be removed due to its condition.

The landscape reinstatement works to the four quarters around Marble Hill House and part of the grounds down towards the River Thames will require the management of these areas through the removal of a number of trees, the coppicing of trees, the retention of trees and the replanting of trees.

The south-east quadrant (Group 7) will require the removal of 69 (sixty nine) trees, the retention of 126 (one hundred and twenty six) trees and the coppicing of 10 (ten) trees.

The north-east quadrant (Group 8) will require the removal of 55 (fifty five) trees, the retention of 41 (forty one) trees and the coppicing of 6 (six) trees. (One tree has been removed since the original survey).

The north-west quadrant (Group 9) will require the removal of 73 (seventy three) trees, the retention of 67 (sixty seven) trees and the coppicing of 16 (sixteen) trees. (One tree has been removed since the original survey and one was a duplicate tree).

The south-west quadrant (Group 10) will require the removal of 80 (eighty) trees, the retention of 53 (fifty three) trees and the coppicing of 13 (thirteen) trees.

Tree 14 (already noted by English Heritage for removal) and Trees 21, 46, G3.28 and G3.30 are recommended for removal for reasons of sound arboricultural management regardless of any development proposals. Therefore the removal of these poor quality trees should not have a bearing on this development proposal. If the client wishes, G3.28 and G3.30 could be made safe and retained for habitat value as they stand within a group, subject to the acceptance of risk associated with the trees' health and condition.

CBA Trees believes that the trees highlighted for retention within this report can be retained without undue stress on their long-term health.

CONTENTS

Section Title

Page No.

PART 1

ARBORICULTURAL IMPLICATIONS ASSESSMENT

1.0	INTRODUCTION	5
2.0	CLIENT'S BRIEF	5
3.0	DESCRIPTION OF THE SITE	6
4.0	THE TREE STOCK	6
5.0	TREE PRESERVATION ORDER/CONSERVATION AREA	7
6.0	PROPOSED TREE RETENTION AND TREE LOSS	7
7.0	SUMMARY OF ARBORICULTURAL IMPLICATIONS	8

PART 2

ARBORICULTURAL / CONSTRUCTION METHOD STATEMENTS

8.0	PRE-COMMENCEMENT SITE MEETINGS	33
9.0	ADDITIONAL ARBORICULTURAL ADVICE FOR SITE PERSONNEL	33
10.0	PRE-DEVELOPMENT TREE WORKS	33
11.0	TREE PROTECTION MEASURES	35
12.0	DEMOLITION, REMOVAL OF BUILT FORM AND HARD SURFACES IN	
	CLOSE PROXIMITY TO RETAINED TREES	39
13.0	EXISTING SERVICES	
14.0	AVOIDING DAMAGE TO STEMS AND BRANCHES	40
15.0	VEHICULAR MOVEMENTS	41
16.0	SITING OF TEMPORARY OFFICES, TOILETS AND MATERIAL STORAGE	
	COMPOUNDS	41
17.0	GENERAL CONSIDERATIONS WITHIN AND OUTSIDE THE	
	CONSTRUCTION EXCLUSION ZONE (CEZ)	42
18.0	UTILITY SERVICE CONNECTIONS	43
19.0	FOUNDATION DESIGN AND CONSTRUCTION	-
20.0	GROUND LEVEL ALTERATIONS	45
21.0	INSTALLATION OF HARD SURFACING IN CLOSE PROXIMITY TO	
	RETAINED TREES	45
22.0	INSTALLATION OF BOUNDARY FENCES	47
23.0	SOFT LANDSCAPING WORKS	
24.0	SITE MONITORING AND SUPERVISION	49
25.0	REPORT DAMAGE TO TREES AND TREE PROTECTION BARRIERS	51
26.0	REMOVAL OF PROTECTIVE BARRIERS	
27.0	COMPLETION MEETING	51
28.0	CONCLUSIONS	51
29.0	CONTACT LIST	53
30.0	BIBLIOGRAPHY	53

SUPPORTING INFORMATION/APPENDICES:

- CB1 Tree Survey Schedule including Root Protection Area Schedule
- CB2 Tree Survey Plan CBA10677.01B TSP
- CB3 Tree Protection Plan CBA10677.02G TPP Tree Protection Plan CBA10677.03B TPP Tree Detection and Demourl Plan CBA10677.04L3
 - Tree Retention and Removal Plan CBA10677.04I TRP
- CB4 Tree Works Schedule
- CB5 CBA Trees Woodland Quarter Tree Retention and Removal Plans: CBA10677.05 NW WQ TRRP CBA10677.06 NE WQ TRRP CBA10677.07 SW WQ TRRP CBA10677.08 SE WQ TRRP
- CB6 J&L Gibbons Landscape drawings: 581_PL_L_26_NW Woodland Quarter 581_PL_L_27_NE Woodland Quarter 581_PL_L_28_SW Woodland Quarter 581_PL_L_29_SE Woodland Quarter

GUIDING PRINCIPLES/APPENDICES:

- CB7 Tree Protection Guidance Leaflet Construction Exclusion Zone Site Notice Common Causes of Damage During Construction Works
- CB8 Qualifications and Experience

1.0 INTRODUCTION

- 1.1 There are development proposals to improve the existing café facilities at the park within the stable block area, improve the play facilities adjacent to the stable block and reinstate the landscaping around Marble Hill House and down towards the River Thames. The proposals aim to balance the historic significance of the site with the environmental potential of the park and an enhanced offer for a broader audience of park users; together these themes will enable a sustainable future for Marble Hill House Park to be developed. The impact of these works have been assessed broadly in accordance with BS5837:2012 *"Trees in Relation to Design, Demolition and Construction Recommendations"*.
- 1.2 Document disclosure provided:
 - Landscape Proposals by J&L Gibbons
 - Stable Block café Proposals by Van Heyningen and Haward Architects
- 1.3 The client and project architects and landscape architects provided the original site plans and locations of the trees, and these have been the basis for the production of subsequent plans. Whilst CBA Trees has had a limited input in defining the contents of the development plan, it broadly conforms to the requirements of BS5837:2012 *"Trees in Relation to Design, Demolition and Construction Recommendations"* and current best practice advice.
- 1.4 Our advice has been sought on the principles of the development and landscape improvement works in relation to the potential impact on the existing tree stock, to inform and to facilitate the development layout.

2.0 CLIENT'S BRIEF

- 2.1 In line with our written quotation and verbal instructions, information has been compiled in accordance with BS5837:2012 and current best practice advice.
 - To undertake a Tree Survey (schedule including Root Protection Areas appended at CB1).
 - To produce an AutoCAD compliant Tree Survey Plan that relies on the accuracy of the topographical survey provided by the client. (Plan CBA10677.01B TSP appended at CB2).
 - To undertake an Arboricultural Implications Assessment (AIA) of the proposed development provided by the client to identify which trees will be lost, which can be retained and suggest mitigating build techniques in order to retain trees.
 - Based on the above and further on-going discussions, to provide an Arboricultural Development Statement detailing the methodologies for the retention of the tree stock where feasible, in relation to the approved development layout including Tree Protection Plans (CBA10677.02G TPP and CBA10677.03B TPP and Tree Retention and Removal Plan (CBA10677.04I TRP) appended at CB3.

2.2 The advice provided has been formulated without discussion with the contractors, who at this stage have not been appointed. Once the main contractors are appointed, amendments to this statement may be required for construction purposes. All amendments will be assessed by the retained arboricultural consultant and approved in writing by London Borough of Richmond Council.

3.0 DESCRIPTION OF THE SITE

- 3.1 Marble Hill House is an 18th century house and garden; the house itself is a Grade I listed building and the landscape is Grade II listed. The house stands relatively central to its immediately surrounding grounds. The overall site is accessed from Richmond Road that defines the northern boundary, with the River Thames defining the southern boundary.
- 3.2 Numerous trees and groups of trees grow across the site. Some of these trees may date back to when the Georgian house was built but many are planted or self-set trees that have since grown.
- 3.3 The site is mainly formed by large open spaces that are currently used as various sports fields with trees providing separation to these areas. The open space between the House and the river is currently a lawned garden area
- 3.4 The stable block café is located on the western boundary with the play area located to the south east of this.

4.0 THE TREE STOCK

- 4.1 CBA Trees undertook a tree survey on 25th, 27th October, 2nd November 2016 and 9th May 2017. The tree survey exercise identified 66 (sixty six) individual trees and 24 (twenty four) groups of trees; within these groups a further 821 (eight hundred and twenty one) trees were noted and of these, 612 (six hundred and twelve) are within the four woodland quarters, namely Groups 7-10). The Tree Survey Schedule and Tree Survey Plan (CBA10677.01B TSP) are appended at CB1.
- 4.2 Since the initial surveys English Heritage have removed several trees. These are T13, T14, T46, G8.8 and G9.18. Therefore the tree numbers are as follows:
 - 63 individual trees
 - 819 noted trees within groups
 - 610 noted trees within the woodland quarters

4.3 Tree Categorisation Method

Category U = Trees in such a condition that any value would be lost within 10 years, or should be removed for reasons of sound arboricultural management.

Note: BS5837:2012 states -

"Category U trees are those in such a condition that they cannot realistically be retained as living trees in the context of the current land use for longer than 10 years."

- Category A = Trees of high quality and value: in such a condition as to make a substantial contribution, (40 years or more is recommended).
- Category B = Trees of moderate quality and value, capable of making a significant contribution for in excess of 20 years.
- Category C = Trees of low quality and value which might remain for a minimum of 10 years or young trees with stems of less than 150mm diameter.

Note:

Trees under these categories are trees that should be a material consideration in the development process; the subcategories are intended to reflect arboricultural, landscape and cultural values respectively.

4.4 For more details of the existing tree stock, refer to the Tree Survey Schedule (appended at CB1).

5.0 TREE PRESERVATION ORDER/CONSERVATION AREA

- 5.1 The London Borough of Richmond Council has confirmed that the site lies within the CA8 Twickenham Riverside Conservation Area but there are no Tree Preservation Orders protecting trees on the site at this time.
- 5.2 As trees can be legally protected at any time, checks with the London Borough of Richmond Council should be made prior to carrying out any tree works to see if a Tree Preservation Order has been served.

6.0 PROPOSED TREE RETENTION AND TREE LOSS

- 6.1 In accordance with the recommendations contained within BS5837:2012, an experienced arboriculturist has assessed the requirements for tree protection and the Root Protection Area (RPA). The implications of the proposed development are detailed below, along with any mitigating measures to ensure the retention of these trees.
- 6.2 As part of the assessment, dimensions have been scaled from the proposed Stable Block Café drawing no. 533-L-2010 Rev B by Van Heyningen and Haward Architects and drawing no. 581_180821_JLG_Landscape Base provided by J&L Gibbons prepared and modified, to include the relevant Tree Survey data appended at CB3.

7.0 SUMMARY OF ARBORICULTURAL IMPLICATIONS

7.1 The following is a summary of arboricultural implications as indicated on Tree Protection Plans CBA10677.02G TPP and CBA10677.03B TPP along with the trees detailed for works or potentially implicated by works for the reinstatement landscaping works.

Table 1: Arboricultural Implications for the stable block café works

Tree	Species	BS	Potential cause of harm	Implication	Mitigation
No.	Species	вз 5837:2012	Potential cause of harm	Implication	Mitigation
		Cat			
6	Sweet Chestnut	B1+2	Damage to roots	Retained	Tree is set away from
			 General site activities and movements 		development
12	Horse Chestnut	B1+2	Damage to roots	Retained	New footpath on perimeter of
			 Damage to crown 		root protection area
			 General site activities and movements 		compromising <5%To be protected as detailed
			Construction of new		in Section 2 of this report
			footpath		
15	Flowering Cherry	B1+2	Damage to roots	Retained	Tree is set away from development
			 Damage to crown General site activities and 		development
			movements		
			 Landscaping works 		
16	Common Yew	A1+2	 Damage to roots General site activities and 	Retained	Removal of raised bed area containing rubble on
			 General site activities and movements 		perimeter of root protection
			 Landscaping works 		potentially compromises
					<6% To be protected as detailed
					in Section 2 of this report
50	Common Elder	C1	Damage to rests	Retained	To be protected as detailed
50			Damage to rootsDamage to crown	- Netained	in Section 2 of this report
			 General site activities and 		
			movements		
			 Existing yard resurfacing work 		
51	Common Yew	B1+2	 Damage to roots 	Retained	To be protected as detailed
			Damage to crown Concrete site activities and		in Section 2 of this report
			 General site activities and movements 		
52	Sycamore	C1+2	Damage to roots	Retained	To be protected as detailed
		Interim	Damage to crown Concrete site activities and		in Section 2 of this report
			 General site activities and movements 		
53	Common	C1+2	 Damage to roots 	Retained	To be protected as detailed
	Hornbeam		Damage to crown Concrete site activities and		in Section 2 of this reportRoot spread restricted by
			 General site activities and movements 		existing wall and built form
			Construction of new		-
			footpath		
			 Air handling unit located on existing hard surface 		
			area		
54	Common	B1+2	Damage to roots	Retained	 To be protected as detailed in Section 2 of this report
	Hornbeam		 Damage to crown General site activities and 		in Section 2 of this reportRoot spread restricted by
			movements		existing wall and built form
			 Part removal of existing 		
			wall and foundationRemoval of existing wall		
			and patio area		
			Construction of new		
			footpathAir handling unit located		
			on existing hard surface		
			area		

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
55	Common Hornbeam	B1+2	 Damage to roots Damage to crown General site activities and movements Removal of existing patio area Construction of new footpath 	Retained	 To be protected as detailed in Section 2 of this report
56	Common Hornbeam	C1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	To be protected as detailed in Section 2 of this report
57	Common Hornbeam	B1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
59	Horse Chestnut	C1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
G1.70	Common Lime	A1+2	 Damage to roots Damage to crown New access to eastern side of existing driveway General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
Grp 3	Holly Cherry Laurel Sycamore Horse Chestnut Yew Elder	B1+2	 Damage to roots Damage to crown Construction of new service yard access Construction of new sub station General site activities and movements 	Removed in part (see below)	 Retained section to be protected as detailed in Section 2 of this report Section of group to be removed as indicated on CBA10677.02G TPP
G3.29	Horse Chestnut	C1+2	 Damage to roots Damage to crown Installation of new driveway area on an existing compacted ground area General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
G3.31	Horse Chestnut	C1	 Damage to roots Damage to crown General site activities and movements Construction of new footpath 	Retained	 New footpath on perimeter of root protection area compromising <6% Tree has already been topped and therefore a full protection area is not needed to support the tree To be protected as detailed in Section 2 of this report
G3.39	Irish Yew	С	 Damage to roots Damage to crown Construction of new service yard access General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
G3.44	Acacia	С	 Damage to roots Damage to crown Construction of new service yard access General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
G3.45	Yew	С	 Damage to roots Damage to crown Construction of new service yard access General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report

PART 1
ARBORICULTURAL IMPLICATIONS ASSESSMENT

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G3.46	Acacia	С	Under footprint of new service yard access	Retained	To be protected as detailed in Section 2 of this report
G3.47	Acacia	С	Under footprint of new service yard access	Retained	To be protected as detailed in Section 2 of this report
G3.48	Acacia	С	 Under footprint of new bin store area 	Removed	Replacement planting
G3.49	Hemlock	С	 Damage to roots Damage to crown Construction of new bin store area General site activities and movements 	Removed	Replacement planting
G3.50	Cherry	С	 Damage to roots Damage to crown Construction of new bin store area General site activities and movements 	Removed	Replacement planting
G3.51	Yew	С	 Damage to roots Damage to crown Construction of new bin store area General site activities and movements 	Removed	Replacement planting
G3.52	Yew	С	 Damage to roots Damage to crown Construction of new service yard access General site activities and movements 	Retained	To be protected as detailed in Section 2 of this report
G3.53	Cypress	С	 Under footprint of new bin store area 	Removed	Replacement planting

Table 2: Arboricultural Implications for the play area works

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
6	Sweet Chestnut	B1+2	 Damage to roots General site activities and movements 	Retained	Tree is set away from development
15	Flowering Cherry	B1+2	 Damage to roots General site activities and movements 	Retained	Tree is set away from development
16	Common Yew	A1+2	 Damage to roots General site activities and movements 	Retained	To be protected as detailed in Section 2 of this report
17	Common Lime	B1+2	 Damage to roots Damage to crown General site activities and movements Landscaping works to install play equipment/benches 	Retained	 To be protected as detailed in Section 2 of this report
18	Common Lime	C1+2	 Damage to roots Damage to crown General site activities and movements Landscaping works to install play equipment/benches 	Retained	 To be protected as detailed in Section 2 of this report

Tree	Species	BS	Potential cause of harm	Implication	Mitigation
No.		5837:2012 Cat			
19	Flowering Cherry	C1	 Damage to roots Damage to crown General site activities and movements 	Retained	To be protected as detailed in Section 2 of this report
20	Flowering Cherry	C1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
22	Sycamore	C1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
23	Pedunculate Oak	B1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
24	Common Ash	B1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
25	Flowering Cherry	C1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	 To be protected as detailed in Section 2 of this report
26	Holm Oak	B1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	Tree is set away from development
27	Red Oak	A1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	Tree is set away from development
28	Common Walnut	B1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	Tree is set away from development
29	London Plane	A1+2	 Damage to roots Damage to crown General site activities and movements 	Retained	 Tree is set away from development
30	London Plane	B1+2 Interim	 Damage to roots Damage to crown General site activities and movements 	Retained	Tree is set away from development
57	Common Hornbeam <i>Carpinus betulus</i>	B1+2	 Damage to roots Damage to crown General site activities and movements Landscaping works to install fence 	Retained	 To be protected as detailed in Section 2 of this report
58	Common Horse Chestnut <i>Aesculus</i> <i>hippocastanum</i>	B1+2	 Damage to roots Damage to crown General site activities and movements Landscaping works to install fence 	Retained	 To be protected as detailed in Section 2 of this report

Table 3: Arboricultural Implications for the landscape reinstatement works

Tree No.	Species	BS 5837:2012	Potential cause of harm	Implication	Mitigation
8	Pedunculate Oak	Cat B1+2 Interim	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	To be protected as detailed in Section 2 of this report
9	Robinia	C1+2	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	To be protected as detailed in Section 2 of this report
10	Robinia	C1+2	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	To be protected as detailed in Section 2 of this report
11	Atlas Cedar	B1	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	To be protected as detailed in Section 2 of this report
30	London Plane	B1+2 Interim	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	To be protected as detailed in Section 2 of this report
32	Turkey Oak	B1+2	General site activities and movements damaging roots, trunk and or crown Landscaping works	Retained	To be protected as detailed in Section 2 of this report
33	London Plane	A1+2	General site activities and movements damaging roots, trunk and or crown Landscaping works	Retained	To be protected as detailed in Section 2 of this report
34	London Plane	B1+2	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	To be protected as detailed in Section 2 of this report
35	Common Ash	B1+2	General site activities and movements damaging roots, trunk and or crown Landscaping works	Retained	To be protected as detailed in Section 2 of this report
36	London Plane	A1+2	General site activities and movements damaging roots, trunk and or crown Landscaping works	Retained	To be protected as detailed in Section 2 of this report
37	Silver Maple	B1+2 Interim	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	To be protected as detailed in Section 2 of this report

Tree	Species	BS	Potential cause of	Implication	Mitigation
No.		5837:2012 Cat	harm		
38	London Plane	A1+2	General site activities and movements damaging roots, trunk and or crown Landscaping works	Retained	To be protected as detailed in Section 2 of this report
40	Common Lime	C1+2	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	 To be protected as detailed in Section 2 of this report
41	Common Lime	B1+2	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	 To be protected as detailed in Section 2 of this report
42	Common Lime	B1+2	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	 To be protected as detailed in Section 2 of this report
43	Pedunculate Oak	A1 Interim	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	 To be protected as detailed in Section 2 of this report
44	Common Lime	B1+2	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	 To be protected as detailed in Section 2 of this report
45	Common Ash	B1+2	 General site activities and movements damaging roots, trunk and or crown Landscaping works 	Retained	To be protected as detailed in Section 2 of this report
47	Common Yew	C1+2	Reinstatement landscaping works	Removed	Replacement planting
48	Holm Oak	B1	 Reinstatement landscaping works 	Removed	Replacement planting
49	Birch 'Youngii'	C1	 Reinstatement landscaping works 	Removed	Replacement planting
Grp 4	Poplar Oak Willow Sycamore Horse Chestnut Box Elder Tree of Heaven	B1+2	Reinstatement landscaping works	 Management works 	Replacement planting
G4.1	Hybrid Black Poplar	C1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.2	Turkey Oak	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.3	Common Beech	B1+2	Reinstatement landscaping works	Retained	 Nine Pin Alley compromises approximately 14% of the root protection area Alley is constructed to a no dig design To be protected as detailed in Section 2 of this report
G4.4	Pedunculate Oak	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.5 G4.6	Pedunculate Oak	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report To be protected as detailed in
G4.6	Pedunculate Oak	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G4.7	Common Lime	B1+2	Reinstatement landscaping works	Retained	 Nine Pin Alley compromises approximately 25% of the root protection area Alley is constructed to a no dig design To be protected as detailed in Section 2 of this report
G4.8	Common Horse Chestnut	B1+2	Reinstatement landscaping works	Retained	 Nine Pin Alley compromises approximately 7% of the root protection area Alley is constructed to a no dig design To be protected as detailed in Section 2 of this report
G4.9	Common Horse Chestnut	C1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.10	Common Horse Chestnut	C1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.11	Hybrid Black Poplar	C1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.12	Ashleaf Maple	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.13	Swedish Whitebeam	C1+2	Reinstatement landscaping works	Removed	Replacement planting
G4.14	Common Horse Chestnut	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.15	Ashleaf Maple	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.16	Ashleaf Maple	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.17	Common Horse Chestnut	U	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.18	Hybrid Black Poplar	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.19	Common Lime	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.20	Mountain Ash	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.21	Western Balsam Poplar	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.22	Western Balsam Poplar	C1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.23	Common Lime	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.24	Western Balsam Poplar	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.25	Common Lime	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.26	Crack Willow	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.27	Lombardy Poplar	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.28	Common Lime	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.29	Common Lime	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.30	Lombardy Poplar	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.31	Lombardy Poplar	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.32	Lombardy Poplar	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.33	Lombardy Poplar	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.34	Lombardy Poplar	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.35	Common Lime	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.36	Tree of Heaven	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.37	Crack Willow	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.38	Crack Willow	C1+2 Interim	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G4.39	Crack Willow	C1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G4.40*	Crack Willow	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.41	Sycamore	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.42	Common Ash	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G4.43	Sycamore	C1+2	 Reinstatement 	Retained	To be protected as detailed in Section 2 of this report
G4.44	Sycamore	C1+2	Iandscaping works Reinstatement	Retained	To be protected as detailed in Section 2 of this report
Grp 5	Elder Sycamore Ash Holly	C1+2	 Iandscaping works Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G5.1	Common Ash	C1+2	 Reinstatement landscaping works 	Removed	Replacement planting
G5.2	Common Ash	C1+2	Reinstatement landscaping works	Removed	Replacement planting
G5.3	Common Ash	C1+2	Reinstatement landscaping works	Removed	Replacement planting
G5.4	Common Ash	C1+2	Reinstatement landscaping works	Removed	Replacement planting
G5.5	Sycamore	C1+2	Reinstatement landscaping works	Removed	Replacement planting
G5.6	Common Ash	C1+2	Reinstatement landscaping works	Removed	Replacement planting
G5.7	Common Ash	U	Reinstatement landscaping works	Removed	Replacement planting
G5.8	Sycamore	C1+2	Reinstatement landscaping works	Removed	Replacement planting
Grp 6	Sycamore Turkish Hazel Common Walnut Common Lime Common Ash Common Yew Norway Maple	B2	 Reinstatement landscaping works 	 Management works 	 Replacement planting Specimen trees to be retained Yew, Holly and understorey species to be coppiced To be protected as detailed in Section 2 of this report
G6.1	Sycamore	B1+2 Interim	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G6.2	Turkish Hazel	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G6.3	Common Walnut	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G6.4	Common Lime	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G6.5	Common Lime	B1+2	 Reinstatement 	Retained	To be protected as detailed in Section 2 of this report
G6.6	Common Lime	B1+2	Iandscaping works Reinstatement	Retained	To be protected as detailed in
G6.7	Common Lime	B1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G6.8	Common Lime	B1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.9	Common Lime	B1+2	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.10	Common Lime	B1+2	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.11	Common Lime	B1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.12	Common Lime	B1+2	Iandscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.13	Common Lime	B1+2	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.14	Turkish Hazel	B1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.15	Common Lime	B1+2	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.16	Common Lime	B1+2	Iandscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.17	Common Ash	B1+2	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.18	Common Lime	B1+2	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.19	Common Lime	C1+2	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.20	Common Lime	B1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
			landscaping works		Section 2 of this report

CBA10677_2018-11-06 v11 ADS

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G6.21	Common Lime	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G6.22	Common Lime	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G6.23	Common Lime	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G6.24	Common Lime	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G6.25	Common Yew	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G6.26	Common Lime	B1+2 Interim	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G6.27	Common Lime	B1+2	 Reinstatement 	Retained	To be protected as detailed in Section 2 of this report
G6.28	Common Lime	B1+2	landscaping works Reinstatement	Retained	To be protected as detailed in
G6.29	Common Ash	B1+2	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G6.30	Norway Maple	B1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
Grp 7	Pedunculate Oak Ash Yew Robinia Field Maple Sycamore Holm Oak Hawthorn Dogwood Holly Cherry Laurel Portugal Laurel Spotted Laurel Elm Snowberry Norway Maple	B1+2	 Iandscaping works Reinstatement landscaping works 	Management works	 Replacement planting Specimen trees to be retained Yew, Holly and understorey species to be coppiced Retained trees to be protected as detailed in Section 2 of this report
G7.1	Common Yew	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.2	Common Ash	B1+2	 Reinstatement 	Retained	To be protected as detailed in Section 2 of this report
G7.3	Common Ash	B1+2	landscaping works Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G7.4	Wild Cherry	C1+2	landscaping works Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G7.5	Sycamore	C1+2	Iandscaping works Reinstatement	Retained	To be protected as detailed in
G7.6	Sycamore	C1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.7	Common Ash	B1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.8	Common Lime	U	landscaping works -	Removed	Section 2 of this report Removed due to poor health
G7.9	Common Yew	U	-	Removed	Removed due to poor health
G7.10	Common Ash	B1+2	Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G7.11	Common Ash	B1+2	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.12*	Common Yew	C1+2	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.13	Common Ash	B1+2	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.14	Pedunculate Oak	B1+2	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.15	Common Ash	B1+2	Iandscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.16	Common Lime	B1+2	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.17	Common Yew	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.18	English Elm	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.19	Field Maple	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.20	Field Maple	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.21*	Field Maple	C1	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
~···E			landscaping works	. tetumou	Section 2 of this report

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G7.22	Field Maple	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.23*	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.24	Common Hawthorn	C1	Reinstatement	Retained	To be protected as detailed in
G7.25	Norway Maple	C1	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.26	Sycamore	C1	landscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.27	Privet	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.28	Field Maple	C1	landscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.20		C1	landscaping works	Retained	Section 2 of this report To be protected as detailed in
	Field Maple	_	 Reinstatement landscaping works 		Section 2 of this report
G7.30	Field Maple	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.31	Common Ash	C1	 Reinstatement landscaping works 	Retained	 To be protected as detailed in Section 2 of this report
G7.32	Sweet Chestnut	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.33	Sycamore	C1	Reinstatement	Retained	To be protected as detailed in
G7.34	Sweet Chestnut	C1	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.35	Common Hawthorn	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.36	Common Holly	U	landscaping works	Retained	Section 2 of this report To be protected as detailed in
G7.37	Field Maple	C1	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
		_	 Reinstatement landscaping works 		Section 2 of this report
G7.38	Common Holly	U	-	Retained	To be protected as detailed in Section 2 of this report
G7.39	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.40	Field Maple	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.41	Field Maple	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.42	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.43	Field Maple	C1	Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G7.44*	Common Hawthorn	C1	Iandscaping works Reinstatement	Retained	To be protected as detailed in
G7.45	Pedunculate Oak	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.46	Pedunculate Oak	C1	landscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.47	Field Maple	C1	 landscaping works Reinstatement 	Retained	Section 2 of this report To be protected as detailed in
G7.48	Field Maple	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.40	Common Ash	C1	landscaping works		Section 2 of this report
			 Reinstatement landscaping works 		Section 2 of this report
G7.50	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.51	Field Maple	C1	 Reinstatement landscaping works 	Retained	 To be protected as detailed in Section 2 of this report
G7.52	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.53*	Common Ash	C1	Reinstatement	Retained	To be protected as detailed in
G7.54	English Elm	C1	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.55	Common Ash	C1	landscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.56	Field Maple	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.57	Common Hawthorn	C1	landscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.58	Pedunculate Oak	C1	landscaping works	Retained	Section 2 of this report To be protected as detailed in
			Reinstatement landscaping works		Section 2 of this report
G7.59	Field Maple	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.60	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.61	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report

CBA10677_2018-11-06 v11 ADS

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G7.62*	Field Maple	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.63	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.64	Common Ash	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.65	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.66	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.67	Pedunculate Oak	C1	 Reinstatement 	Retained	To be protected as detailed in Section 2 of this report
G7.68	Field Maple	C1	landscaping works Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G7.69	Field Maple	C1	landscaping works Reinstatement	Retained	To be protected as detailed in
G7.70	Holm Oak	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.71	Holm Oak	C1	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.72	Pedunculate Oak	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.73	Common Ash	C1	Iandscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.74	Holm Oak	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.75	Holm Oak	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.76	Holm Oak	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.77	Holm Oak	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.78	Holm Oak	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.79	Holm Oak	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.80	Holm Oak	C1	Reinstatement Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.81		_	landscaping works		Section 2 of this report To be protected as detailed in
	English Elm	C1	Reinstatement landscaping works	Retained	Section 2 of this report
G7.82	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.83	Holm Oak	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G7.84	Holm Oak	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.85	Holm Oak	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.86	Holm Oak	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.87	Holm Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.88	Holm Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.89	Holm Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.90	Common Hawthorn	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.91	Holm Oak	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G7.92	English Elm	C1	Reinstatement	Retained	To be protected as detailed in
G7.93	Dogwood	C1	landscaping works Reinstatement	Removed	Section 2 of this report Replacement planting
G7.94	Holm Oak	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G7.95	Robinia	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G7.96	Robinia	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G7.97	Robinia	C1	landscaping worksReinstatement	Removed	Replacement planting
G7.98	Robinia	C1	landscaping worksReinstatement	Removed	Replacement planting
G7.99	Robinia	C1	landscaping worksReinstatement	Removed	Replacement planting
G7.100	Common Hawthorn	C1	landscaping worksReinstatement	Removed	Replacement planting
			landscaping works		

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G7.101	English Elm	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.102	Common Holly	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.103	Field Maple	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.104	Field Maple	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G7.105	Wild Cherry	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.106	Field Maple	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.107	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.108	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.109	Field Maple	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.110	Common Ash	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.111	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.112	Common Lime	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.113	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.114	Field Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.115	Common Yew	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.116	Common Lime	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.117	Common Ash	C1	 Reinstatement 	Retained	To be protected as detailed in Section 2 of this report
G7.118	Field Maple	C1	Iandscaping works Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G7.119	Common Lime	C1	Iandscaping works Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G7.120	Common Lime	C1	Iandscaping works Reinstatement	Retained	To be protected as detailed in
G7.121	Wild Cherry	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G7.122	Common Hawthorn	C1	landscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G7.123	Common Hornbeam	C1	Iandscaping works Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G7.124	Wild Cherry	C1	landscaping works Reinstatement	Retained	To be protected as detailed in
G7.125	Common Hawthorn	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G7.126	Common Hawthorn	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in Castian 2 of this appart
G7.127	Common Holly	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.128	Common Holly	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.129*	Whitebeam	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.130*	English Elm	C1	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.131*	Common Holly	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.132*	Common Holly	С	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G7.133	English Elm	C1	Iandscaping works Reinstatement	Retained as	Section 2 of this report To be protected as detailed in Section 2 of this report to
G7.134	English Flag	01	landscaping works	coppice	Section 2 of this report to preserve rooting environment
	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.135	Common Hawthorn	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G7.136	Common Ash	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.137	Norway Maple	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.138	Common Holly	U	-	Removed	Removed due to poor health

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G7.139	Cherry Laurel	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.140*	Cherry Laurel	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.141	Cherry Laurel	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.142*	Cherry Laurel	C1	Reinstatement	Retained	To be protected as detailed in
G7.143	Common Hawthorn	U	landscaping works -	Removed	Section 2 of this report Removed due to poor health
G7.144	Portugal Laurel	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.145	Common Holly	C1	Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G7.146	Common Holly	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G7.147	Common Holly	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G7.148	Common Ash	C1	Reinstatement	Removed	Replacement planting
G7.149	Norway Maple	U	landscaping works -	Removed	Removed due to poor health
G7.150	Common Holly	C1	Reinstatement	Removed	Replacement planting
G7.151	Robinia	C1	Reinstatement	Retained	To be protected as detailed in
G7.152*	English Elm	С	landscaping works Reinstatement	Retained as	Section 2 of this report To be protected as detailed in
			landscaping works	coppice	Section 2 of this report to preserve rooting environment
G7.153	Wild Cherry	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.154	Wild Cherry	C1	 Reinstatement landscaping works 	Removed	Replacement planting
37.155	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.156	Common Hawthorn	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.157	Common Holly	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G7.158	English Elm	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G7.159	Common Holly	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.160	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.161	Holm Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.162	Norway Maple	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.163	Common Horse Chestnut	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.164	Field Maple	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.165	Robinia	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.166	Robinia	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.167	Norway Maple	C1	Reinstatement	Removed	Replacement planting
G7.168	Common Holly	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G7.169	Common Holly	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G7.170	English Elm	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G7.171	English Elm	C1	 Iandscaping works Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G7.172	Common Holly	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G7.173	Common Holly	C1	Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G7.174	Common Holly	C1	Iandscaping works Reinstatement	Retained	To be protected as detailed in
G7.175	Common Holly	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G7.176	Norway Maple	C1	Iandscaping works Reinstatement	Removed	Section 2 of this report Replacement planting

CBA10677_2018-11-06 v11 ADS

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G7.177	Sycamore	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.178	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.179	Norway Maple	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.180	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.181	Field Maple	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.182	Field Maple	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.183	Common Holly	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.184	Common Hawthorn	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G7.185	Robinia	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G7.186	Wild Cherry	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.187	Robinia	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.188	Common Hawthorn	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.189	Common Hawthorn	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.190	Holm Oak	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.191	Robinia	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.192	Cherry Laurel	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.193	Wild Cherry	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.194	Holm Oak	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.195	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.196	Holm Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.197	Holm Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.198	Pedunculate Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.199	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.200	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.201	Wild Cherry	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.202	Common Yew	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G7.203	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.204	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G7.205	Wild Cherry	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
Grp 8	Yew Sycamore Ash Oak Hornbeam Elm, Hazel, Laurel, Ivy, Butchers Broom	B2	Reinstatement landscaping works	Management works	 Replacement planting Specimen trees to be retained Yew, Holly and understorey species to be coppiced Retained trees to be protected as detailed in Section 2 of this report
G8.1	Common Hornbeam	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G8.2	Common Yew	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.3	Common Yew	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.4	Common Yew	C2+1	Reinstatement landscaping works	Removed	Replacement planting
G8.5	Sycamore	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.6	Common Ash	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G8.7	Common Lime	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G8.9	Common Yew	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.10	Common Yew	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.11	Common Yew	C1+2	Reinstatement landscaping works	Removed	Replacement planting
G8.12	Common Holly	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.13	Common Yew	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.14	Common Lime	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.15	Common Hawthorn	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.16*	Common Ash	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G8.17	English Elm	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G8.18	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.19	Common Box	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.20*	Common Box	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.21*	Common Hawthorn	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.22	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.23	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.24	Common Hornbeam	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.25	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.26	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.27	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.28	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.29	Common Ash	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.30	Common Holly	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.31	Wild Cherry	U	-	Removed	Removed due to poor health
G8.32	English Elm	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G8.33	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.34	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.35*	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.36	Field Maple	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.37*	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.38	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.39	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.40	Common Ash	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.41	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.42*	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.43	Common Ash	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.44*	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.45*	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.46*	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G8.47*	English Elm	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G8.48*	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.49	Griselinia littoralis	C1	 Reinstatement 	Removed	Replacement planting
G8.50	English Elm	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G8.51	Common Ash	C1	Reinstatement	Removed	Replacement planting
G8.52*	English Elm	C1	Reinstatement	Removed	Replacement planting
G8.53	Sycamore	U	landscaping works -	Removed	Removed due to poor health
G8.54*	Sycamore	C1	Reinstatement	Removed	Replacement planting
G8.55	Common Holly	C1	landscaping works Reinstatement	Removed	Replacement planting
G8.56	Common Holly	C1	landscaping works Reinstatement	Removed	Replacement planting
G8.57	Common Elder	C1	landscaping works Reinstatement	Removed	Replacement planting
G8.58	Common Holly	C1	landscaping worksReinstatement	Removed	Replacement planting
G8.59	Common Beech	C1	landscaping works Reinstatement	Retained	To be protected as detailed in
G8.60	Common Yew	C1	Iandscaping works Reinstatement	Removed	Section 2 of this report Replacement planting
G8.61	Highclere Holly	C1	Reinstatement Iandscaping works Reinstatement	Removed	Replacement planting
	Common Elder	C1 C1	landscaping works		Replacement planting
G8.62*			Reinstatement landscaping works	Removed	
G8.63	English Elm	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G8.64*	Common Ash	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G8.65	Common Holly	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G8.66	Common Holly	U	-	Removed	Removed due to poor health
G8.67	Common Holly	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G8.68*	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.69	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.70	Holm Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.71*	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G8.72	Griselinia littoralis	C1	Reinstatement	Removed	Replacement planting
G8.73	Common Holly	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G8.74	Common Holly	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G8.75*	Sycamore	C1	Reinstatement	Removed	Replacement planting
G8.76*	English Elm	C1	landscaping works Reinstatement	Removed	Replacement planting
G8.77	Common Holly	C1	landscaping worksReinstatement	Removed	Replacement planting
G8.78	Common Holly	C1	landscaping works Reinstatement	Removed	Replacement planting
G8.79	English Elm	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G8.80	English Elm	C1	landscaping worksReinstatement	Removed	Replacement planting
G8.81	Common Yew	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G8.82	English Elm	C1	Reinstatement Reinstatement	Retained	To be protected as detailed in
G8.83	English Elm	C1	Reinstatement landscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G8.84	Common Yew	C1	landscaping works	Retained Retained	To be protected as detailed in Section 2 of this report To be protected as detailed in
			Reinstatement landscaping works		Section 2 of this report
G8.85*	Common Ash	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G8.86	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G8.87	Common Lime	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.88	Common Holly	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.89	English Elm	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G8.90	Sycamore	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G8.91	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.92	English Elm	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G8.93*	English Elm	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G8.94*	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.95*	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.96	Common Holly	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.97	Common Holly	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.98	Common Hornbeam	C1	 Reinstatement 	Retained	To be protected as detailed in
G8.99	Common Ash	C1	Iandscaping works Reinstatement Iandscaping works	Retained as coppice	Section 2 of this report To be protected as detailed in Section 2 of this report to
G8.100	Pedunculate Oak	C1	 Reinstatement landscaping works 	Retained as coppice	preserve rooting environment To be protected as detailed in Section 2 of this report to preserve rooting environment
G8.101	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G8.102	Common Lime	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G8.103	Common Holly	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
Grp 9	Sycamore Lime Oak Yew Holly Cherry Laurel Elder Ash Rhododendron Portugal Laurel Snowberry Hornbeam	B1+2	Reinstatement landscaping works	Management works	 Replacement planting Specimen trees to be retained Yew, Holly and understorey species to be coppiced Retained trees to be protected as detailed in Section 2 of this report
G9.1	Common Lime	C1+2	Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G9.2	Common Ash	B1+2	Iandscaping works Reinstatement Iandacaping works	Retained	To be protected as detailed in
G9.3	Common Yew	B1+2	Iandscaping works Reinstatement Iandscaping works	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.4	Common Yew	C1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.5	Pedunculate Oak	C1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.6	Common Beech	C1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.7	Pedunculate Oak	U	landscaping works -	Retained*	Section 2 of this report Removed due to poor health
G9.8	Pedunculate Oak	C1+2	Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G9.9	Pedunculate Oak	C1+2	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.10	Pedunculate Oak	U	landscaping works -	Retained*	Section 2 of this report Removed due to poor health
G9.11	Pedunculate Oak	C1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.12	Common Horse Chestnut	C1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report

Tree No.	Species	BS 5837:2012	Potential cause of harm	Implication	Mitigation
G9.14	Common Ash	Cat U	-	Removed	Removed due to poor health
G9.15*	Common Lime	C1+2	Reinstatement	Retained	To be protected as detailed in
G9.16	Sycamore	C1+2	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G9.17	Common Lime	U	landscaping works -	Removed	Section 2 of this report Removed due to poor health
G9.19	Common Holly	C1	Reinstatement	Retained	To be protected as detailed in
G9.20	Common Holly	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G9.21	Common Ash	C1	 landscaping works Reinstatement 	Retained	Section 2 of this report To be protected as detailed in
G9.22	Common Ash	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G9.23	Robinia	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G9.24		C1	landscaping works	Retained	Section 2 of this report To be protected as detailed in
	Common Holly		Reinstatement landscaping works		Section 2 of this report
G9.25	Common Holly	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G9.26	Robinia	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.27	Common Holly	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.28	Common Hawthorn	C1	 Reinstatement 	Retained	To be protected as detailed in Section 2 of this report
G9.29*	Common Holly	C1	Iandscaping works Reinstatement Iandscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to
G9.30	Sycamore	C1	Reinstatement landscaping works	Retained as coppice	preserve rooting environment To be protected as detailed in Section 2 of this report to
G9.31	Sycamore	C1	 Reinstatement landscaping works 	Retained as coppice	preserve rooting environment To be protected as detailed in Section 2 of this report to
G9.32	Common Lime	C1	Reinstatement	Retained	Preserve rooting environment To be protected as detailed in Constant 0 of this assert
G9.33	Common Lime	C1	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G9.34	Common Ash	C1	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G9.35	Cherry Laurel	C1	Iandscaping worksReinstatement	Removed	Section 2 of this report Replacement planting
G9.36	Common Holly	C1	 Iandscaping works Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to
G9.37	Common Holly	C1	Reinstatement	Retained	preserve rooting environment To be protected as detailed in
G9.38	Common Holly	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G9.39	Common Yew	C1	landscaping worksReinstatement	Removed	Section 2 of this report Replacement planting
G9.40	Common Holly	C1	Iandscaping works Reinstatement	Retained	To be protected as detailed in
G9.41	Common Hornbeam	C1	Reinstatement Iandscaping works Reinstatement	Removed	Section 2 of this report Replacement planting
			landscaping works		
G9.42	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.43	Common Hawthorn	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.44	Common Yew	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.45	Common Ash	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.46	Common Yew	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.47	Common Holly	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.48	Common Holly	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.49	Common Elder	C1	 Reinstatement 	Retained	To be protected as detailed in
G9.50	Common Ash	C1	landscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.51	Common Ash	C1	 Reinstatement landscaping works 	Retained as coppice	Section 2 of this report To be protected as detailed in Section 2 of this report to
					preserve rooting environment

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G9.52	Common Holly	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.53	Common Ash	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G9.54	Common Holly	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.55	Sycamore	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.56	Pedunculate Oak	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.57	Common Holly	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G9.58	Common Lime	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.59	Common Hornbeam	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.60	Common Beech	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.61	Common Yew	C1	 Reinstatement 	Retained	To be protected as detailed in Section 2 of this report
G9.62	Common Ash	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G9.63	Common Lime	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G9.64	Sycamore	С	Iandscaping works Reinstatement Iandscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to
G9.65	Common Ash	C1	Reinstatement landscaping works	Retained as coppice	preserve rooting environment To be protected as detailed in Section 2 of this report to preserve rooting environment
G9.66	Sycamore	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.67	Common Lime	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.68	Common Ash	C1	 Reinstatement 	Retained	To be protected as detailed in Section 2 of this report
G9.69*	English Elm	C1	landscaping works Reinstatement	Retained	To be protected as detailed in
G9.70*	English Elm	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.71*	Common Ash	C1	 Iandscaping works Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G9.72	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.73	Common Hawthorn	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G9.74	Common Hawthorn	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G9.75	Common Yew	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.76	Common Yew	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.77	Common Ash	C1	 Reinstatement 	Retained	To be protected as detailed in Section 2 of this report
G9.78	Common Ash	C1	landscaping works Reinstatement	Retained	To be protected as detailed in
G9.79	Common Ash	C1	landscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.80	Common Ash	C1	landscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.81	Holm Oak	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.82	Common Ash	C1	Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G9.83	Common Horse Chestnut	C1	Iandscaping works Reinstatement Iandscaping works	Retained	Section 2 of this report To be protected as detailed in Section 2 of this report
G9.84	Common Yew	C1	Reinstatement	Removed	Replacement planting
G9.85	Common Yew	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G9.86	Common Yew	C1	Iandscaping works Reinstatement	Removed	Replacement planting
	1		landscaping works		

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G9.88	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.89	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.90	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.91	Holm Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.92	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.93	Common Yew	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G9.94	English Elm	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.95	Sycamore	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G9.96	Common Ash	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G9.97	Common Yew	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.98	Common Yew	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G9.99	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.100	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.101	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.102 G9.103	Duplicate tree Common Ash	- C1	Reinstatement	- • Retained	To be protected as detailed in
G9.104	Common Ash	C1	Iandscaping works Reinstatement	Removed	Section 2 of this report Replacement planting
G9.105	Pedunculate Oak	C1	Iandscaping works Reinstatement	Retained	To be protected as detailed in
G9.106	Pedunculate Oak	C1	Reinstatement Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G9.107	Pedunculate Oak	C1 C1	landscaping works	Removed	Section 2 of this report
G9.107		C1 C1	Reinstatement landscaping works	Removed Removed	· · · · · · · · · · · · · · · · · · ·
G9.108	English Elm		Reinstatement landscaping works		· · · · · · · · · · · · · · · · · · ·
	Pedunculate Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.110	Pedunculate Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.111	Pedunculate Oak	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.112	Pedunculate Oak	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G9.113	Pedunculate Oak	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.114	Sycamore	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.115	Common Yew	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.116	Common Hawthorn	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.117	Common Hawthorn	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.118	Pedunculate Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.119	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.120	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.121	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.122	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.123	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.124	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.125	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.126	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting

Tree No.	Species	BS 5837:2012	Potential cause of harm	Implication	Mitigation
G9.127	Sycamore	Cat C1	Reinstatement	Removed	Replacement planting
G9.128	Common Yew	C1	landscaping worksReinstatement	Removed	Replacement planting
G9.129	Common Yew	C1	Iandscaping worksReinstatement	Removed	Replacement planting
G9.130	Holm Oak	C1	Iandscaping worksReinstatement	Removed	Replacement planting
G9.131	Holm Oak	C1	landscaping worksReinstatement	Removed	Replacement planting
G9.132	Common Yew	C1	landscaping worksReinstatement	Removed	Replacement planting
G9.133	Common Yew	C1	landscaping worksReinstatement	Removed	Replacement planting
G9.134	Common Hornbeam	C1	landscaping works Reinstatement	Removed	Replacement planting
G9.135	Holm Oak	C1	Reinstatement Reinstatement	Removed	Replacement planting
G9.136	Common Hawthorn	C1	landscaping works	Removed	Replacement planting
G9.130		-	Reinstatement landscaping works		
	Pedunculate Oak	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.138	Common Yew	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.139	Common Holly	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.140	Common Hornbeam	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.141	Common Holly	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G9.142	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.143	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.144	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.145	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G9.146	Common Holly	C1	 Reinstatement 	Removed	Replacement planting
G9.147	Common Yew	C1	landscaping works Reinstatement	Removed	Replacement planting
G9.148	Common Yew	C1	landscaping works Reinstatement	Removed	Replacement planting
G9.149	Common Holly	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G9.150	Common Hawthorn	C1	Reinstatement	Removed	Replacement planting
G9.151	Sycamore	C1	Reinstatement	Removed	Replacement planting
G9.152	Sycamore	C1	landscaping worksReinstatement	Removed	Replacement planting
G9.153	Sycamore	C1	landscaping worksReinstatement	Removed	Replacement planting
G9.154	Common Holly	C1	Iandscaping worksReinstatement	Removed	Replacement planting
G9.155	Common Holly	C1	landscaping worksReinstatement	Removed	Replacement planting
G9.156	Common Yew	C1	landscaping worksReinstatement	Removed	Replacement planting
G9.157*	Cherry Laurel	C1	landscaping works Reinstatement	Removed	Replacement planting
	x4		landscaping works		
G9.158	Sycamore x3 Holly x4 Ash x2	C1	 Reinstatement landscaping works 	Removed	Replacement planting
Crn 10	Elder x2	PO	Deineteterent	. Monogomont	Poplocoment planting
Grp 10	Ash Sycamore Yew Beech Laurel Elm	B2	 Reinstatement landscaping works 	Management works	 Replacement planting Specimen trees to be retained Yew, Holly and understorey species to be coppiced Retained trees to be protected as detailed in Section 2 of this report
G10.1	Common Ash	B1+2	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.2	Common Ash	B1+2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G10.3	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.4	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.5	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.6	Sycamore	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.7	Sycamore	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.8	Pedunculate Oak	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.9	Common Ash	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.10	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.11	Common Ash	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.12	Common Ash	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.13	Common Ash	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.14	Holm Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.15	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.16	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.17	Common Lime	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.18	Sycamore	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.19*	Elm x1 Yew x3 Holly x1 Holm Oak x1 Sycamore x4	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.20	Common Holly	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.21	Holm Oak	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.22	Common Holly	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.23	Common Holly	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.24	Common Holly	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.25	Common Yew	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.26	Common Holly	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.27	Common Hawthorn	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.28	Sycamore	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.29	Common Holly	U	-	Retained	To be protected as detailed in Section 2 of this report
G10.30	Common Beech	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.31*	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.32	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.33	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.34	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.35	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.36	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.37	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.38	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.39*	Common Ash	C1	 Reinstatement landscaping works 	Retained	 To be protected as detailed in Section 2 of this report

CBA10677_2018-11-06 v11 ADS

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G10.40	Common Ash	U	-	Retained	To be protected as detailed in Section 2 of this report
G10.41	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.42	Common Holly	C1	Reinstatement	Retained	To be protected as detailed in Section 2 of this report
G10.43	Common Holly	U	landscaping works -	Retained	To be protected as detailed in Section 2 of this report
G10.44	Ash Sycamore Elm x12	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.45	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.46	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.47	Common Ash	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.48	Common Yew	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.49	Common Yew	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.50	Stump	U	-	Removed	Removed due to poor health
G10.51	Common Yew	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.52	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.53	Common Ash	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.54	Common Ash	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.55*	Cherry Laurel	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.56*	Common Elder	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.57	Portugal Laurel	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.58	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.59	Common Beech	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.60	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.61	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.62	Sycamore	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.63	Sycamore	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.64	Sycamore	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.65*	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.66*	Common Holly Ilex aquifolium	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.67	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.68	Common Ash	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.69	Common Hawthorn	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.70	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.71	Common Yew	C2	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.72	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.73	Common Yew	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.74	English Elm	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.75	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.76	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.77	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.78	Field Maple	C1	Reinstatement	Removed	Replacement planting

Tree No.	Species	BS 5837:2012 Cat	Potential cause of harm	Implication	Mitigation
G10.79	Common Ash	C1	Reinstatement	Removed	Replacement planting
G10.80	English Elm	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G10.81	Common Ash	C1	Iandscaping works Reinstatement landscaping works	Removed	Replacement planting
G10.82	Common Ash	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.83	Common Ash	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.84	Field Maple	C1	 Reinstatement 	Removed	Replacement planting
G10.85	Field Maple	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G10.86	Common Ash	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G10.87	Common Ash	C1	Iandscaping works Reinstatement	Removed	Replacement planting
G10.88	Common Ash	U	landscaping works -	Removed	Removed due to poor health
G10.89	Common Ash	C1	Reinstatement	Removed	Replacement planting
G10.90	Field Maple	C1	Reinstatement	Removed	Replacement planting
G10.91	Field Maple	C1	Iandscaping works Reinstatement	Retained	To be protected as detailed in
G10.92*	Common Ash	C1	Iandscaping works Reinstatement	Removed	Section 2 of this report Replacement planting
G10.93	Common Ash	C1	Iandscaping works Reinstatement	Retained	To be protected as detailed in
G10.94	Common Yew	C1	Iandscaping works Reinstatement	Retained	Section 2 of this report To be protected as detailed in
G10.95	Common Ash	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G10.96	Holm Oak	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G10.97	Common Beech	C1	landscaping worksReinstatement	Retained	Section 2 of this report To be protected as detailed in
G10.98	Common Ash	C1	Iandscaping works Reinstatement	Removed	Section 2 of this report Replacement planting
G10.99	English Elm	C1	Reinstatement Reinstatement	Removed	Replacement planting
G10.100	Common Ash	C1	Reinstatement Addresser	Removed	Replacement planting
G10.101	English Elm	C1	Reinstatement Additional and scaping works Reinstatement	Removed	Replacement planting
G10.102	English Elm	C1 C1	landscaping works	Removed	
			Reinstatement landscaping works		
G10.103	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.104	English Elm	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.105	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.106	Holm Oak	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.107	English Elm	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.108	English Elm	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.109 *	English Elm	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.110	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.111 *	Holm Oak	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.112	Common Ash	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.113	Common Ash	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.114	English Elm	C1	Reinstatement landscaping works	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.115	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.116	Field Maple	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.117	Field Maple	С	Reinstatement landscaping works	Removed	Replacement planting

Tree No.	Species	BS 5837:2012	Potential cause of harm	Implication	Mitigation
		Cat			
G10.118	Field Maple	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.119	Common Ash	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.120	Field Maple	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.121	Common Hornbeam	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.122	Field Maple	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.123 *	English Elm	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.124	English Elm	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.125	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.126	Holm Oak	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.127	English Elm	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.128	Pedunculate Oak	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.129	Common Ash	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.130	Sycamore	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.131	Sycamore	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.132	English Elm	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.133	Sycamore	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.134	Sycamore	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.135 *	Common Holly	C1	 Reinstatement landscaping works 	Retained as coppice	To be protected as detailed in Section 2 of this report to preserve rooting environment
G10.136	Common Holly	C1	 Reinstatement landscaping works 	Retained	To be protected as detailed in Section 2 of this report
G10.137	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.138	English Elm	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.139	Common Holly	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.140	Common Horse Chestnut	C1	Reinstatement landscaping works	Retained	To be protected as detailed in Section 2 of this report
G10.141	English Elm	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.142	Common Hawthorn	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.143	Sycamore	C1	 Reinstatement landscaping works 	Removed	Replacement planting
G10.144	Common Hawthorn	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.145	Sycamore	C1	Reinstatement landscaping works	Removed	Replacement planting
G10.146	Sycamore	C1	 Reinstatement landscaping works 	Removed	Replacement planting

* U grade trees to be retained for ecological reasons

8.0 PRE-COMMENCEMENT SITE MEETINGS

- 8.1 It is recommended that a pre-commencement site meeting is held prior to any works commencing on site to agree all approved processes with the arboricultural consultant, the construction personnel and London Borough of Richmond Council Tree Officer. This meeting could be used to formally agree the methods of work, position of site offices, material storage, compounds, parking and tree protection measures prior to commencement of the development and the associated clearance work.
- 8.2 In addition to the above it is advised that a pre-commencement meeting is held prior to the start of each phase of works; the stable block café development, the improvement to the play area adjacent to the stable café, works to demolish built form, works to construct the Nine Pin Alley and prior to the landscape restoration works.

9.0 ADDITIONAL ARBORICULTURAL ADVICE FOR SITE PERSONNEL

- 9.1 To provide site personnel with additional information regarding the requirements of Tree Protection, a leaflet (appended at CB7) shall be issued to all staff at the time of their site induction. Spare copies of this leaflet shall be available in the site office as replacements.
- 9.2 In order to inform site personnel of the purpose of the barriers, information notices shall be fixed to the barriers at 5m intervals. These notices shall be of all-weather construction and shall be in the form of the specimen provided at appendix CB7 and replaced as and when necessary.

10.0 PRE-DEVELOPMENT TREE WORKS

- 10.1 All tree works will be undertaken prior to the commencement of site preparation and construction works.
- 10.2 <u>All permitted or approved tree work</u> should be carried out in accordance with the British Standard *"Recommendations for Tree Work"* BS3998:2010, by suitably qualified and experienced professional arborists. Under no circumstances shall site personnel undertake any tree pruning operations. All tree surgery works should be carried out prior to the development of the site, and erection of protective barriers.
- 10.3 If additional tree works are required during the development works around the café or as part of the landscape improvement works, a written notification must be made prior to the works being programmed/commenced and are subject to the Council considering the works and allowing the tree works before the works are carried out.
- 10.4 Consideration should be given to the timing of any tree works to avoid the active growing period of trees. Therefore, all tree work should ideally be carried out during

PART 2 ARBORICULTURAL/CONSTRUCTION METHOD STATEMENTS

the dormant period from November through to February and then again from June to August.

- 10.5 Due to the bird-nesting season, considered to be from 1st March through to the 31st July (Natural England) depending on weather conditions, consideration must also be given to the potential for nesting birds. Therefore, where tree work is to be carried out within these months the project ecologist must be consulted to:
 - Complete or advise on a pre-works survey that needs to be carried out by a suitably competent person. As a general rule, it should be assumed that birds will be nesting in trees, and it is down to contactors to assess, record and confirm that any works carried out in the management of trees and other vegetation has not disturbed actively nesting birds.
 - Ground vegetation, and therefore ground nesting birds, can often be overlooked by tree workers so additional care and controls should be taken when access and egress to the work site may also cause disturbance or damage to a nesting site. This is also true for retained trees on site as the removal of adjacent trees or remedial works on a tree may lead to an established nest being abandoned, exposed to the elements or predation. This action is also a breach of the Act and therefore could lead to prosecution due to the infringement of the Wildlife and Countryside Act 1981 and breaching the Conservation of Habitats and Species Regulations 2010 (as amended).
- 10.6 Although not apparent at the time of the site visit, consideration should also be given to the presence of bats, and a full visual assessment should be undertaken before any works are carried out on the trees. Where bats are identified as a serious concern, a bat survey should be undertaken by qualified and trained personnel to identify the needs of the bats (roosts, resting place etc) and no tree works can be carried out until the 'all clear' is given, or a programme of recommendations is received in writing.
- 10.7 Should additional tree works become apparent during the construction process; written consent will be required from London Borough of Richmond Council prior to these additional works being undertaken.
- 10.8 All tree works that are required to facilitate the development and landscape restoration works are detailed within the Tree Works Schedule appended at CB4.
- 10.9 All tree work will be completed in accordance with the ecological constraints of the site such as badger setts and trees identified as potential for, or recorded as, having bat activity. This will be completed under the guidance of the project ecologist and as such led by their requirements.
- 10.10 All tree work within the woodland quarters will only be completed once a site specific method statement for the removal of trees, stumps and brash has been approved by the council and the client.

PART 2 ARBORICULTURAL/CONSTRUCTION METHOD STATEMENTS

- 10.11 Stumps WILL NOT be chemically treated. Where stumps are to be removed, they will either be grubbed out by hand held tools, cut to below ground level or ground out using a stump grinder (only where considered absolutely essential) and working from ground protection such as ground guards to avoid excessive damage to the woodland floor and disturbance/damage to the ecological habitat.
- 10.12 Ecological log and brash piles may be retained on site within the woodland quarters where they are not imposing on the proposed landscape improvement works. It is proposed that these piles should be no larger than 1.5m in length and 1.0m in height so that they do not become a significant feature of the woodlands. There should be no more than 7 piles per quarter.
- 10.13 The size and number of the ecological piles should be led by the landscape and ecological disciplines for the project and secured through planning conditions along with a method statement detailing how the works will be carried out. This will ensure compliance with ecological constraints and concerns from the Local Planning Authority regarding how the works will be completed.

11.0 TREE PROTECTION MEASURES

- 11.1 All site operations will be planned, implemented and supervised to prevent the following unless otherwise agreed within this report:
 - Root severance
 - Damage to the bark, branches and trunks
 - Compaction of the soil within the Construction Exclusion Zone
 - Alterations in soil level
 - Soil contamination by phytotoxic materials such as herbicides, petrol, oils, diesel, cement and concrete washings or other construction additives
- 11.2 Before starting any site demolition, ground or construction works in relation to this development proposal tree protection will be installed in accordance with Tree Protection Plans CBA10677.02G TPP for works relating to the stable block café, CBA10677.03B TPP for works relating to the play area adjacent to the stable block café and CBA10677.04I TRP for the tree removal and retention for the landscape restoration works around Marble Hill House and down to the River Thames (all three plans appended at CB3). This will occur immediately following the completion of tree works for each phase of the site works and prior to any site preparation works starting.


A copy of the Tree Protection Plans will be displayed in the site office and canteen as a point of reference for all site operatives.

11.3 Standard Protective Barrier

Installing the following protective barrier as indicated on Tree Protection Plans CBA10677.02G TPP and CBA10677.03B TPP will protect retained trees. The barrier is to comprise of a vertical and horizontal framework, well braced to resist impacts,

with vertical tubes spaced at a maximum interval of 3m. Onto this, weldmesh panels should be securely fixed with wire or scaffold clamps.

Figure 1: Protective Barrier



- 1. Standard scaffold poles
- 2. Uprights to be driven into the ground
- 3. Panels secured to uprights with wire ties and where necessary standard scaffold clamps
- 4. Weldmesh wired to the uprights and horizontals
- 5. Standard clamps
- 6. Wire twisted and secured on inside face of barriers to avoid easy dismantling
- 7. Ground level
- 8. Approximately 0.6m driven into the ground

Example of protective barrier:



11.4 Ground Protection


11.4.1 Pedestrian movements

11.4.2 Trees 54, 55 and 56 require construction activity within the identified Construction Exclusion Zone (CEZ); ground protection will be implemented for these trees as per the Tree Protection Plan CBA10677.02G TPP.

PART 2 ARBORICULTURAL/CONSTRUCTION METHOD STATEMENTS


11.4.3 Ground protection will be constructed in accordance with Figure 2 below for pedestrian movements, and consist of a suspended walkway decked with 20mm exterior grade Plyboard supported on 75 x 50mm bearers. The specification provides for pedestrian access only.

Figure 2: Pedestrian walkway within the Root Protection Area



11.4.4 An alternative approach is provided in Figure 3 below; the method will allow for construction and working space within the CEZ of trees. This method will consist of a single thickness of butt jointed scaffold boards supported on a 150mm thick layer of composted woodchip that is prevented from mixing with the underlying soil by geotextile separation layer.

Figure 3: Ground Protection Specification (shown on next page)



- 11.4.5 Ground protection within the woodland quarters will provide a main pedestrian contractor and light weight plant machinery (<1.5 tonne) access route to enable tree works to be completed together with the landscape improvement works.
- 11.4.6 The fit for purpose ground protection within the woodland quarters will consist of either of the following (unless otherwise agreed in writing by the Tree Officer of London Borough of Richmond Council):
 - A compressible layer of woodchip finished with butt jointed scaffold boards, 18mm robust wooden sheets such as plyboard or OSB
 - A compressible layer of woodchip with ground guards or track mats pinned in place
- 11.4.7 The location of ground protection within the woodland quarters will be determined by the tree contractors and their working practices to enable the extraction of the trees to be removed and coppiced as detailed within their method statement.

11.5 Site and Machinery Access within Construction Exclusion Zone

11.5.1 At this stage no information has been provided as to the type, weight or ground pressure of the equipment to be deployed for the landscaping reinstatement works, and therefore the exact type of ground protection is yet to be specified if it is indeed required. The method of ground protection will be engineer designed and fit for purpose. Prior to the commencement of works, ground protection will be assessed

by the retained arboricultural consultant and approved in writing by the London Borough of Richmond Council Tree Officer.

- 11.5.2 As a guide, a compressible layer will be incorporated into the design to minimise compaction of the rooting environment. This layer could consist of a thick layer of composted wood chip or preparatory neoprene mats.
- 11.6 Once the barriers and ground protection are in place it must remain *in-situ* throughout the following list:
 - Contractor occupancy
 - Plant and materials delivery
 - Construction works
 - Installation of porous surfacing
 - Utility installation
 - Completion of development
 - Landscaping
- 11.7 The areas protected by barriers, fencing and ground protection will be regarded as **sacrosanct**, and the tree protective barriers shall not be taken down or relocated at any time without the written approval of London Borough of Richmond Council. An example of a CEZ notice is appended at CB7.

12.0 DEMOLITION, REMOVAL OF BUILT FORM AND HARD SURFACES IN CLOSE PROXIMITY TO RETAINED TREES

- 12.1 The demolition and removal of any built form such as the toilet block within the north west woodland quarter, the Chinese shelter, the raised grassed areas at the frontage of the stable block or removal of any hard surfacing (and its foundations where appropriate) will be carried out so as to prevent damage to existing retained trees.
- 12.2 Demolition of existing built form in close proximity to the retained trees must be undertaken with due care and attention and in line with the tree protection details as set out in Section 11 above, throughout this report and in accordance with any specific working method statements, in order to adequately respect roots, rooting environments, trunks or overhanging crowns of all retained trees. To this end, the following rules will apply:
 - Site personnel are to undergo an induction session prior to being allowed to work on site. The induction will introduce the contractors to the requirements of the Protection Method Statement. A copy of the Method Statement will be made available as a point of reference in respect of tree protection requirements. In addition, a copy of the Tree Protection Plan will be provided or pinned up in the site hut. During the induction, trees that are to be retained and protected will be highlighted to the demolition personnel and they will be physically shown which trees are to be protected on site. In this way, it is hoped that unnecessary

damage, by root disturbance and collision of machinery booms and operating arms with tree crowns can be avoided.

- All walls, foundations and basements are to be pulled in on themselves towards the centre of the site and away from retained trees. This will be done in a direction away from the tree protective barriers and all large machinery to be operated at least 2.5-3.0 metres outside the line of the tree protective fence line from where it is erected for the site preparation works.
- Any machinery used for this purpose is to stand and operate over existing hard surfaces wherever possible, but always outside the CEZ as defined by the protective barriers.
- Lightweight structures will be demolished and removed by hand. Work will be carried out from existing hard surface. If the structure is not served by existing hard surface, ground protection will be laid in accordance with Plan CBA10677.02G TPP.
- Where dust is created and deposited on adjacent retained trees, provision will be made to wash down the crowns of retained trees weekly to prevent excessive dust affecting the photosynthetic capacity of retained trees.
- 12.3 Any removal of hard surfacing, built form or other excavations in close proximity to trees will be undertaken by working only from the existing hard surface or protected ground area. The required work should then be completed with hand operated tools or appropriate machinery, but under the supervision of an arboriculturist. Any machinery or equipment to be used will need to be lightweight and run on additional ground protection, or working from the existing hard standing only.

13.0 EXISTING SERVICES

- 13.1 No information has been provided on the location and size of existing services. However, if there are any existing services within the RPA and CEZ of retained trees will not be chased out, but cut at the edge of any structure and left *in- situ*.
- 13.2 Cabling will only be recovered from beneath a CEZ where it is located in ducting, and can be removed by winching from an existing service manhole beyond the CEZ.
- 13.3 Service pipes and ducts, where they are located within the CEZ or RPA of retained trees, will be made redundant either by pipe bursting or by filling with an inert material such a foamed concrete.

14.0 AVOIDING DAMAGE TO STEMS AND BRANCHES

14.1 Care shall be taken when planning site operations, to ensure that wide or tall loads or plant with booms, jibs and counterweights can operate without coming into contact with retained trees. Such contact could result in serious damage to them, and might make their safe retention impossible. Consequently, any transit or traverse of plant

in close proximity to trees, will be conducted under the supervision of a banksman, in order to ensure adequate clearance from trees is maintained at all times.

15.0 VEHICULAR MOVEMENTS

- 15.1 There should be minimal vehicular movement in the potential rooting zone and outside the CEZ identified on plans CBA10677.02G TPP and CBA10677.03B TPP and CBA10677.04I TRP.
- 15.2 It is not anticipated that there will be a need for excess vehicular movement near the retained trees for works relating to the café development given that there is an established vehicle access and areas of hard standing.
- 15.3 For works relating to the improvements to the play area adjacent to the café, the existing boundary fence and additional tree protection measures will limit vehicle movements so that tree roots and their environment are not adversely damaged by vehicles tracking over the soft ground.
- 15.4 Works access within the woodland quarters will operate from fit for purpose ground protection or from existing hard surfacing.
- 15.5 For the landscape restoration works around Marble Hill House and down to the River Thames, all vehicles must remain at least 15m from the trunks of retained trees at all times.

16.0 SITING OF TEMPORARY OFFICES, TOILETS AND MATERIAL STORAGE COMPOUNDS

- 16.1 It is anticipated that all storage materials and deliveries shall make use of the open space outside of the RPAs of retained trees, the existing site compound and areas of existing hard standing in order to avoid unnecessary damage to tree roots.
- 16.2 The locations shall be agreed in writing with London Borough of Richmond Council prior to the commencement of works on site, and will remain in only those agreed locations throughout the construction phases. If an alternative location is required, this must be agreed in writing with London Borough of Richmond Council. This will also include the delivery; storage and movement of all essential facilities, as well as aspects such as temporary contractor vehicle parking and site location of chemical mixing (e.g. concrete). All such locations will be outside of the RPAs, and avoid areas where 'run off' of chemicals may flow into RPAs.

16.3 Site Huts

All site huts that are to be situated on soft ground shall have appropriate footings or be situated on a temporary surface, which will aid in reducing the potential for compaction of the ground, where they are in close proximity to the existing tree protective barrier line. Site huts can be used as part of the protective barrier boundary, and in some cases, can be beneficial where installation does not conflict with the aerial parts of the tree.

If it is proposed that site huts, ground protection or stores are to be located within the RPA of retained trees for more than 3 months, a temporary irrigation and aeration system will be installed to ensure that the rooting environment is maintained in a good condition. The system will include a compressible layer of composted wood chip or forest bark over a geotextile separation layer, on which ground protection or site huts can be placed. Watering will depend on permeability of the soil, weather conditions, and the extent of the area covered, but should include weekly watering from April to September, when no rainfall has occurred for more than four consecutive days.

16.4 Material Storage

This shall be accommodated outside of the CEZ, particularly to avoid harmful spillages of fuel, or phytotoxic substances that may damage the health of retained trees.

17.0 GENERAL CONSIDERATIONS WITHIN AND OUTSIDE THE CONSTRUCTION EXCLUSION ZONE (CEZ)

- 17.1 Inside the CEZ formed by the protective barrier measures, the following prohibitions shall apply:
 - No construction activity will occur within the CEZ unless otherwise stated in this report, or agreed in writing with London Borough of Richmond Council prior to the specific activity taking place.
- 17.2 In addition to the above, further precautions are necessary adjacent to trees outside the CEZ:
 - Materials, which will contaminate the soil e.g. concrete mixing, diesel oil and vehicle washings, shall not be discharged within 10 metres of the tree stem. This should take into consideration the topography of the site and slopes, to avoid materials such as concrete washings running towards trees.
 - Fires shall not be lit in a position where their flames can extend to within 5 metres of foliage, branches or trunk. This will depend on the size of the fire and the wind direction.
 - Notice boards, telephone cables or other services shall not be attached to any part of the tree. (See appendix CB7 Common Causes of Damage During Construction Works)

18.0 UTILITY SERVICE CONNECTIONS

- 18.1 Full details of the service location proposals for the stable block café works have not been forwarded to CBA Trees at the time of compiling this assessment. It is however assumed that, given the location of the trees to be retained and that existing services are present on site that serve the current stable block, any new services will be installed outside the root protection areas of retained trees, and connected to the existing where practicable, this will avoid disturbance of tree roots and ensure their healthy retention.
- 18.2 Where it is not possible to design services to be outside of root protection areas, services will be installed in accordance with the following specification:
- 18.3 All required excavation for service installation within the root protection areas of retained trees must be carried out by hand using non-metallic tools. Preferably, a compressed air lance (Soil Pick) will be used to loosen soil around existing roots. Any large roots greater than 25mm diameter or clusters of smaller roots will be retained and protected using damp Hessian before proceeding with further excavation.

Photograph 1: Compressed Air Lance removing soil from around roots





Photograph 2: Exposed undamaged roots following excavation with soil pick

PART 2 ARBORICULTURAL/CONSTRUCTION METHOD STATEMENTS

18.4 Great care should be taken to preserve and work around roots greater than 25mm in diameter, and clusters of smaller roots avoiding breakage, splitting or damage to the exposed bark. Within the area of excavation, split sections of appropriately sized plastic pipe will be tied around Hessian wrapped roots to prevent impact damage to bark occurring.

Photograph 3:

Exposed roots protected from damage with wet Hessian and split plastic pipe





Photograph 4: Trench sides protected from drying by wet Hessian

- 18.5 If it is absolutely necessary to sever roots greater than 25mm in diameter, arboricultural advice must be sought. Where smaller roots must be severed, they should be cut back cleanly using secateurs or a sharp pruning saw.
- 18.6 No trenches containing exposed tree roots must be left open overnight. If the trench is to remain open for any period of time during the day, and/or the weather is hot, Hessian wrappings will be kept moist to prevent the roots from drying out and trench sides will be draped with damp Hessian to reduce the potential for root tip death through lack of moisture.
- 18.7 Backfilling of initial trenches should be carried out using the excavated soil, which should be worked in around roots and lightly "tamped" to remove air pockets whilst respecting the original soil profile. Compaction of the material by the use of pneumatic tools or a trench hammer will not be permitted. The backfill should be left proud of surrounding levels to allow for settlement.

18.8 Further advice on the installation of services is set out in NJUG Publication Volume 4 2007, and Section 7.7 of BS5837:2012.

19.0 FOUNDATION DESIGN AND CONSTRUCTION

- 19.1 Proposed footpaths adjacent to T53, 54, 55 and 56 will be arboriculturally supervised during site excavation works with the footpaths having shallow foundations and, where feasible, the foundation and finished levels raised to minimise excavation.
- 19.2 Within the woodland quarters, footpaths will be porous and built up so that minimal excavation is required by removing the loose vegetative layer.
- 19.3 Foundations for seats, benches and play equipment will be designed to minimise the impact on tree roots where they are located within the root protection areas of retained trees. The foundations should be designed to account for tree roots and final positions of these items on site will be determined by the presence of tree roots (or lack thereof), in particular if roots are greater than 25mm in diameter. This will follow on from the setting out and on site supervision/advice from the retained arboricultural consultant.
- 19.4 The Nine Pin Alley will be constructed using a no dig method of construction whereby the alley is built up on existing ground levels to avoid the loss of significant roots.
- 19.5 Any new bench, play equipment or similar will only be installed within root protection areas by working from fit for purpose ground protection as detailed in Section 11.

20.0 GROUND LEVEL ALTERATIONS

20.1 There will be no increases or decreases to the ground levels within the root protection areas of the retained trees other than those that are detailed within this report or footpaths. If levels adjacent to the RPAs are affected, then retaining structures must be designed to account for the retention of ground levels to avoid root loss through battering ground back.

21.0 INSTALLATION OF HARD SURFACING IN CLOSE PROXIMITY TO RETAINED TREES

21.1 The proposed footpaths within the woodland quarters will use Cedec, a self-binding gravel that is permeable. The footpaths will be constructed by only removing the turf/ loose vegetative layer and then will be built up on the existing ground with support edging pegged into place and then a quality top soil to grade down the edges to avoid a trip hazard. All works within the woodland quarters to establish the footpaths will utilise fit for purpose ground protection as set out in Section 11 to ensure that the rooting environment and roots of trees are not damaged by contractors. A plant machine size limit of 1.5 tonnes is advised if used to deliver materials to the woodlands.

- 21.2 There will be localised excavation to allow the new proposed Cedec path to meet with the level of the existing asphalt paths. This is unlikely to have a significant impact upon the trees and will be arboriculturally supervised to ensure that the appointed contractors are mindful of the work they are carrying out and ensure the reduction of any impact on retained trees.
- 21.3 The proposed Nine Pin Alley within the root protection area of trees G4.3, G4.7 and G4.8 will be constructed using a no dig method of construction and be constructed by only removing the turf/loose vegetative layer and then will be built up on the existing ground with support edging pegged into place and then a quality top soil to grade down the edges to avoid a trip hazard.
- 21.4 All footpaths within the four quarters of the woodland groups around Marble Hill House and the Nine Pin Alley construction will follow the principles as set out above and detailed below:
 - The proposed wearing surface will consider site-specific factors and will be designed in accordance with advice from a structural engineer drainage engineer and arboricultural consultant as appropriate. This will result in a design that is fit for purpose, adequate for the task and sympathetic to the biological requirements of the trees.
 - Where the level of the ground requires raising to level out the hollows, this should be achieved with a granular material that does not inhibit gaseous exchange (such as no-fines gravel, washed aggregate or cobbles).
 - Sub-bases will consist of a non-binding, no fines granular material that does not inhibit water percolation or gaseous exchange.
 - If a substantial area of fill is to be installed, provision will be made for the installation of irrigation and aeration system within the RPA of retained trees. Distance between pipes will not exceed 400mm, irrigation pipes will be connected to the surface water drainage system. Aeration pipes will be installed in between and will be protected by paving mounted grills.
 - Depending on the load-bearing capacity of the soil determined through engineering testing, and the expected loads to be exerted on the soil, it may be necessary to incorporate a load suspension layer such as a 3-dimensional cellular confinement system. This layer must allow gaseous exchange both vertically and horizontally. Any load suspension system should only be used in accordance with the manufacturer's guidelines, and its installation should comply with any relevant health and safety guidance. CBA Trees can provide further information relating to appropriate systems on request.
 - Cedec surfacing is a permeable construction and therefore allows for the movement of gases, water and nutrients to any tree roots beneath the surfacing.

- The surfacing allows future growth of the roots and the base of the trunk, and as such should be no closer than 500mm from the trunk base. This will avoid future damage, both to the tree and engineered surface.
- Where edge supports are required, they will be designed to have minimal excavation of the existing soil surface, and be in the form of either wooden, aluminium or other edging materials, approved by a structural engineer and the retained arboriculturist. These edgings should be pinned in place, and the location of the pins should seek to avoid exposed surface or structural roots exceeding 25mm diameter.

22.0 INSTALLATION OF BOUNDARY FENCES

- 22.1 Boundary fences are proposed within the CEZ of Tree 57 and 58 and around the perimeter of the woodland quarters. Tree roots extend well in excess of the RPA of retained trees and are mainly located in the upper 600mm of soil. As such, even minor levelling and excavation can result in extensive damage to the root system. Inappropriate access within the CEZ for fence construction purposes can result in soil compaction and deterioration of the soil structure. Concrete used to support the posts is poisonous to plants and, if not controlled, can leach into the surrounding soil.
- 22.2 Fencing will be constructed in accordance with the following specification:
 - Fencing will be designed so as to minimise the need for excavation and allow minor variations between post spacings to allow repositioning of posts to permit the retention of all roots where possible, that are greater than 25mm, which are discovered during the excavation of postholes within the RPA of retained trees.
 - Fencing will be installed during period of dry weather so as to maintain soil structure and prevent compaction of the rooting environment.
 - Fit for purpose ground protection will be placed along the line of construction within the trees root protection area to prevent compaction of the rooting environment of retained trees. This may take the form of robust plywood boards.
 - New post holes will be carefully excavated by hand to avoid damage to roots greater than 25mm in diameter but where possible existing fence post holes will be utilised.
 - Although postholes lined with heavy gauge polythene to prevent contamination
 of the rooting environment from drying concrete is the best option for the tree. It
 does not allow for the concrete to cure adequately against the surrounding soil.
 It is therefore imperative that fresh concrete is poured as dry as possible to avoid
 excessive leaching into the soil. If tree roots are exposed in post holes then heavy
 gauge polythene must be used to avoid direct contact between root and concrete.
 - Bracing of posts off retained trees will not be permitted under any circumstances

23.0 SOFT LANDSCAPING WORKS

- 23.1 Any soft landscaping works within the development area around the stable café, the play area, wider site tree planting and the landscape improvement works for the grounds around Marble Hill House and down to the River Thames will be in accordance with the approved landscape plans provided by J&L Gibbons, and any specification of such works approved by London Borough of Richmond Council.
- 23.2 Overall the total number of trees to be removed (excluding U grade trees which will be either removed for sound arboricultural reasons or made safe for ecological benefit) is 285. The total number of proposed trees for this planning application is 342 to be planted in the appropriate season or either phase 2, 3 or 4 as fully detailed in the J&L Gibbons documents accompanying this planning application.
- 23.3 Landscaping will accord with the following requirements where in close proximity to retained trees:
 - Landscaping work will be completed outside of the bird breeding season (that is, in the autumn/ winter).
 - Each year prior to any work being carried out, badger and bat surveys will be undertaken, plans and working practices revised, and mitigation undertaken as advised by the project ecological consultants.
 - Due to the size of the tree stock (25-30 / 35-40cm girth) being planted in the NW quadrant there will potentially be the need for equipment such as excavators to dig the planting hole and move the trees into position. Contractors will utilise existing or newly created areas of hard standing for vehicle access. Where plant and/or vehicles are to be used within the root protection areas of trees, fit for purpose ground protection or specific load spreading tyres on light weight vehicles will be used to avoid excessive compaction of the ground.
 - All other new tree planting in the present defined woodland quarters will be standard nursery stock (girth 8-10cm) planted by hand by English Heritage on site staff.
 - Where landscaping works are to be carried out within the CEZ of retained trees after the main phase of construction has been completed. At this stage, it will be necessary to alter the line of/remove protective barriers in order to facilitate the landscaping works.
 - The CEZ will remain off limits for all site plant and machinery unless fit for purpose ground protection is installed. Pedestrian traffic must be kept to an absolute minimum only permitted for the ground preparation and landscape installation works.
 - The landscaping works will need to be undertaken in such a way as to avoid level changes, deep digging or mechanical rotovating. Excavation of planting pits with the RPA can cause serious harm the root system of retained trees. Planting pits within

PART 2 ARBORICULTURAL/CONSTRUCTION METHOD STATEMENTS

the RPA of retained trees will be excavated by hand to avoid roots greater than 25mm and masses of smaller roots.

 If any planting pits are required within the CEZ of retained trees, these will be dug by hand and with care avoiding roots greater than 25mm diameter or masses of smaller roots.



Figure 4: Root severance as a result of planting within RPA

Planting Trees and Shrubs. Watson G. W. and Himelick E. B. 1997

- Where there are stumps of removed trees or shrubs, these will be ground out to 300mm below ground level and resulting holes filled with sharp horticultural sand to provide a stable base for laying of the new turf.
- 23.4 In order to aid establishment and water retention, organic matter will be introduced into the top soil by hand forking and boards will be used to reduce compaction from wheel barrow wheels. Areas where there are significant tree roots will not be forked over but mulched. Any surface mulch will consist of well-composted material such as bark or wood chips. This is necessary to avoid potential nutrient loss from the soil, such as Nitrogen, as the mulch breaks down, as nutrient loss can be detrimental to the health and longevity of retained trees.
- 23.5 Safety surfacing to be installed within the play areas is to consist of a rubber grid that is laid upon the existing ground surface and pinned in situ. No excavations will occur for this installation.

24.0 SITE MONITORING AND SUPERVISION

- 24.1 To ensure that the tree protection measures are maintained correctly and as per the approved documents (subject to any written approval for amendments where required), arboricultural supervision will be completed.
- 24.2 The client will be responsible for ensuring that the tree protection measures are set up and maintained correctly throughout the site works.

PART 2 ARBORICULTURAL/CONSTRUCTION METHOD STATEMENTS

- 24.3 As part of this process, photographic records will be taken and kept by the client. An email copy of the photographs will be sent to the London Borough of Richmond upon Thames Council Tree Team and CBA Trees showing works during each phase and stage of onsite works:
 - This will take the form of the client signing off in a weekly logbook, that the agreed protection measures are in situ and fit for purpose as per the approved documents and as agreed by the representative of London Borough of Richmond upon Thames Council.
 - The tree protection measures will be photographed and emailed to the Tree Team in the planning department with a request to visit site and confirm that the protection measures are acceptable. The London Borough of Richmond upon Thames Council representative will then sign off the protective measures:
 - Pre-commencement of tree works
 - Setting out and erection/establishment of tree protection measures for the café area
 - Removal of the raised bed at the frontage of the Stable block adjacent to T15 and T16
 - Removal of existing hard surface area and resurfacing works adjacent to T54-55
 - Setting out and erection/establishment of tree protection measures for the play area
 - Pre-commencement of the creation and establishment of new landscaping works for each of the four woodland quarters surrounding Marble Hill House
- 24.4 CBA Trees will be retained throughout the project by the client to enable tree related concerns for the site to be discussed and acted upon quickly and efficiently to ensure that any tree related issue that may arise on site during the project can be dealt with, without detriment to the long term health of the trees.

Date	Activity	Checked	Comments/ damage noted	By whom	Signed	Action taken
	Pre-commencement meeting					
	Erection of protective measures					
	Tool box talk with appointed contractors advising on the importance of the protection of the trees					
	Weekly inspection of protective barriers					
	Assessment of foundation excavation adjacent to T51 and T52					
	Supervised removal of existing hard surface and minimal hand dig footpath adjacent to T53-55					
	Arboricultural assessment of any discovered roots >25mm diameter					

Example pro-forma:

by CBA Trees prior to any further			
works commencing to western			
footpath via email and telephone			

25.0 REPORT DAMAGE TO TREES AND TREE PROTECTION BARRIERS

- 25.1 Should any damage be caused to trees noted for retention, either by the above works or as the result of any other action, the damage should be reported to the site supervisor immediately. The site supervisor shall report up the chain of responsibility to the retained consultant arboriculturist, or in the absence of such an appointment, to an appropriately qualified arboriculturist, to enable remedial measures to be implemented as necessary and as agreed with London Borough of Richmond Council Tree Officer.
- 25.2 Should damage occur to a protective barrier to impair its function in protecting trees, all work will cease near the damage, until the barrier has been returned to standard.

26.0 REMOVAL OF PROTECTIVE BARRIERS

- 26.1 When each development phase is complete, all drainage and service runs are in place, all site machinery has been removed and any landscaping for the principal area of the site has been implemented, the protective measures where they have been installed will be dismantled/removed.
- 26.2 This dismantling/removal of the tree protection measures must be undertaken with great care, and will need to be supervised to avoid heavy machinery being used within the Root Protection Areas. Hoarding, scaffolding and other barrier materials will need to be removed from site immediately.

27.0 COMPLETION MEETING

27.1 Upon completion of all the works specified above, and in line with procedures also specified, the retained arboricultural consultant will invite London Borough of Richmond Council Tree Officer to meet on site, to discuss the project and to agree on any remedial works that may be required.

28.0 CONCLUSIONS

28.1 There are development proposals to improve the existing café facilities at the park within the stable block area, improve the play facilities adjacent to the stable block and reinstate the landscaping around Marble Hill House and down towards the River Thames. The proposals aim to balance the historic significance of the site with the environmental potential of the park and an enhanced offer for a broader audience of park users; together these themes will enable a sustainable future for Marble Hill House Park to be developed. The impact of these works have been assessed

broadly in accordance with BS5837:2012 "Trees in Relation to Design, Demolition and Construction – Recommendations".

- 28.2 The development works focus on three areas of the park.
 - To improve the café facilities at the stable block will require the removal of 5 (five) noted trees within the southern end of Group 3 (G3.48, G3.49, G3.50, G3.51 and G3.53, all low grade trees).
 - The improvements to the play area adjacent to the stable block do not require any trees to be removed as a direct result of the works. One poor quality tree (T21) will be removed due to its condition.
 - The landscape reinstatement works to the four quarters around Marble Hill House and part of the grounds down towards the River Thames will require the management of these areas through the removal of a number of trees, the coppicing of trees, the retention of trees and the replanting of trees.
 - The south-east quadrant (Group 7) will require the removal of 69 (sixty nine) trees, the retention of 126 (one hundred and twenty six) trees and the coppicing of 10 (ten) trees.
 - The north-east quadrant (Group 8) will require the removal of 55 (fifty five) trees, the retention of 41 (forty one) trees and the coppicing of 6 (six) trees. (One tree has been removed since the original survey).
 - The north-west quadrant (Group 9) will require the removal of 73 (seventy three) trees, the retention of 67 (sixty seven) trees and the coppicing of 16 (sixteen) trees. (One tree has been removed since the original survey and one was a duplicate tree).
 - The south-west quadrant (Group 10) will require the removal of 80 (eighty) trees, the retention of 53 (fifty three) trees and the coppicing of 13 (thirteen) trees.
- 28.3 Tree 14 (already noted by English Heritage for removal) and Trees 21, 46, G3.28 and G3.30 are recommended for removal for reasons of sound arboricultural management regardless of any development proposals. Therefore the removal of these poor quality trees should not have a bearing on this development proposal. If the client wishes G3.28 and G3.30 could be made safe and retained for habitat value as they stand within a group, subject to the acceptance of risk associated with the trees health and condition.
- 28.4 Overall the total number of trees to be removed (excluding U grade trees which will be either removed for sound arboricultural reasons or made safe for ecological benefit) is 285. The total number of proposed trees for this planning application is 342 to be planted in the appropriate season or either phase 2, 3 or 4 as fully detailed in the J&L Gibbons documents accompanying this planning application.
- 28.5 It is our opinion that the trees identified for retention can be afforded due respect and provided adequate protection throughout each stage and phase of works on site,

ensuring their safe and healthy retention during the development process and have been fully considered throughout the design of the site development.

- 28.6 Whilst there will be short term loss of trees and vegetation through areas being thinned and replanted that will cause some short-term adverse impacts, it is our understanding from the project ecologist that there will be greater gains for wildlife in the medium and long term creating a healthier and more diverse tree stock.
- 28.7 The landscaping reinstatement works will, in time, provide a landscape setting that is more in keeping within the original landscape plans for the House and its grounds. Given the extensive number of trees on site both individually and within groups the loss of the trees as detailed within this report will not have a detrimental impact on the treed nature of the grounds of Marble Hill House when considered with the detailed landscaping proposals that have been proposed by J&L Gibbons.
- 28.8 Provided the recommendations included within this report are strictly adhered to, and appropriate planning conditions are implemented to ensure that working methodologies are agreed, adopted and followed for site specific works by the appointed contractor following planning consent, CBA Trees believes the trees highlighted for retention within this report can be retained without undue stress on their long-term health.

29.0 CONTACT LIST

29.1 It is suggested that points of contact and lines of communication are established prior to commencement of the works on site including:

Client:	07584 591 442
Ndai Halisch, English Heritage	
Ndai.Halisch@english-heritage.org.uk	
Landscape Architects:	020 7226 1345
Neil Davidson, J&L Gibbons	
neil@jlg-london.com	
Project Arboricultural Consultant:	02380 986229
Stefan Rose, CBA Trees	07917 138978
srose@cbatrees.co.uk	
Tree Officer	0208 891 1411
London Borough of Richmond Council	
trees@richmond.gov.uk	
Site foreman/Supervisor	To be appointed

30.0 BIBLIOGRAPHY

- British Standard 5837:2012 –
 "Trees in Relation to Design, Demolition and Construction Recommendations"
- British Standard 3998:2010 -

"Recommendations for Tree Work"

- National Joint Utilities Group Publication Volume 4 "Guidelines for the planning, installation and maintenance of utility services in proximity to trees"
- Wildlife and Countryside Act 1981
- Conservation of Habitats and Species Regulations 2010 (as amended)
- Town and Country Planning Acts







TREE SURVEY NOTES

This Tree Survey has been undertaken within the recommendations of British Standards 5837:2012 and current arboricultural best practice.

- > Each tree has been numbered and, where instructed, for future identification on site, has been tagged using small durable metal or plastic tags.
- > Due to variations of existing ground levels through the site, height dimensions are estimated and are given in metres. Accurate heights, measured with the aid of optical instruments can be provided where instructed.
- Trunk/stem diameters are measured in mm at 1.5 metres above ground level, using a standard measuring tape as defined by British Standards, unless otherwise stated.
- Estimated branch spread is taken in metres from the centre of the trunk, at the four cardinal points of a compass, to achieve an accurate representation of the crown shape which will be recorded on the tree survey plan.
- > An assessment of a tree's age classification is made in terms of its maturity within the site's landscape and defined as:
 - Y = young trees
 - SM = semi-mature trees
 - EM = early mature trees
 - M = mature trees
 - OM = over-mature trees
- > An assessment of a tree's physiological condition is defined as:
 - Good = fully functioning biological system showing average vitality i.e. normal bud growth, leaf size, crown density and wound closure
 - Fair = fully functioning biological system showing below average vitality i.e. reduced bud growth, smaller leaf size, lower crown density and reduced wound closure
 - Poor = a biological system with limited functionality showing significantly below average vitality i.e. limited bud growth, small and chlorotic leaves, low crown density and limited wound closure
 - Dead = dead
- An assessment of a tree's structural condition is defined as:
 - Good = no significant structural defects
 - Fair = structural defects which could be alleviated through remedial tree surgery or management practices
 - Poor = structural defects which cannot be alleviated through tree surgery or management practices
 - Dead = dead

> An assessment of a tree's future life expectancy is defined as: <10, 10+, 20+ or 40+ years.

Categorisation of Trees

The category for each tree is assessed using the recommendations of BS5837:2012. The assessment has not considered any site-specific development proposals, but will have considered any changes on or off-site which may have an effect on the conditions surrounding the surveyed trees.

The trees have been classified into one of the following categories (and one or more sub-categories [this will however not increase the value of the tree]) and are indicated on the associated drawings by colours as indicated.

Category U				Identification colour on plan
Trees in such a condition that they cannot realistically be retained as living trees in the context of the current land use for longer than 10 years	 Trees that have a serious, irremediable, structural d those that will become unviable after removal of oth companion shelter cannot be mitigated by pruning) Trees that are dead or are showing signs of signification. Trees infected with pathogens of significance to the suppressing adjacent trees of better quality 	ner category U trees (e.g. where, for ant, immediate, and irreversible over health and/or safety of other trees n	whatever reason, the loss of all decline earby, or very low quality trees	DARK RED
Category A	1 – Mainly arboricultural values	2 – Mainly landscape values	3 – Mainly cultural values	Identification colour on plan
Trees of high quality with an estimated remaining life expectancy of at least 40 years	Trees that are particularly good examples of their species, especially if rare or unusual; or those that are essential components of groups or formal or semi-formal arboricultural features (e.g. the dominant and/or principal trees within an avenue	Trees, groups or woodlands of particular visual importance as arboricultural and/or landscape features	Trees, groups or woodlands, of significant conservation, historical, commemorative or other value (e.g. veteran trees or wood-pasture)	LIGHT GREEN
Category B	1 – Mainly arboricultural values	2 – Mainly landscape values	3 – Mainly cultural values	Identification colour on plan
Trees of moderate quality with an estimated remaining life expectancy of at least 20 years	Trees that might be included in category A, but are down-graded because of impaired condition (e.g. presence of significant though remediable defects, including unsympathetic past management and storm damage), such that they are unlikely to be suitable for retention for beyond 40 years; or trees lacking the special quality necessary to merit the category A designation	Trees present in numbers, usually growing as groups or woodlands, such that they attract a higher collective rating than they might as individuals; or trees occurring as collectives but situated so as to make little visual contribution to the wider locality	Trees with material conservation value or other cultural value	MID BLUE
Category C	1 – Mainly arboricultural values	2 – Mainly landscape values	3 – Mainly cultural values	Identification colour on plan
Trees of low quality with an estimated remaining life expectancy of at least 10 years, or young trees with a stem diameter below 150mm	Unremarkable trees of very limited merit or such impaired condition that they do not qualify in higher categories	Trees present in groups or woodlands, but without this conferring on them significantly greater collective landscape value; and/or trees offering low or only temporary/transient landscape benefits	Trees with no material conservation or other cultural value	GREY

Clients are advised that Tree Surveys are a basic data collection exercise and record of tree condition at the time of survey. This will identify any visible signs of ill-health or major defects, advising a further detailed investigation where appropriate. This will most often take the form of a request for either "*full ground level inspection*" or "*climbing inspection required*". There may also be a further reference to the need for "*decay detection equipment*" to aid diagnosis. A tree survey does not include a comprehensive schedule or specification of remedial tree works, but may contain a guide to the work which might be undertaken by a prudent tree owner, purely for reasons of health and safety.

A Tree Survey should not be confused with a Tree Inspection or Arboricultural Implication Assessment, which are totally separate exercises.

		BS5837:2012 TREE SURVEY REPORT
	Site:	Marble Hill House and Park
	Date:	25 & 27 October & 02 November 2016 09 May 2017 (Trees G3.31-G3.54; G7.17-G7.205; G8.13-G8.103; G9.19-G9.158)
BA Trees	Consultant:	Stefan Rose BSc (Hons), TechCert (Arbor.A) James Fuller FdSc.Arb, BTEC Nat.Dip.Arb, TechArbor.A
	Tagged:	No

Notes:

- 1. It may be advised that some trees should have the ivy removed to enable a re-survey to be carried out. This would also alleviate the tree from becoming suppressed; carrying additional weight that increases the chance of windthrow due to a larger dense crown area; and only receiving restricted light. Unless otherwise stated, in order to prevent regrowth, it is only necessary to remove a 300mm section of ivy and clear around the base.
- 2. It may be advised that it was only possible to estimate the diameter of some trees because of ivy smothering, dense vegetation, or trees located off-site with no access.
- 3. The estimated remaining contribution in years, and the tree grading category have been calculated for the current situation and may alter where further investigation works are advised.
- 4. Some trees or groups may have been given an interim grade. The reason for the interim grading is addressed in the timescales given as this may have a bearing on health and safety and/or any development proposals.
- 5. Tree Groups have been assessed with estimated and representative data.
- 6. This is not a Tree Works Schedule. Any preliminary management recommendations are listed in the interests of health and safety and should be carried out by a prudent tree owner.
- 7. Any management recommendations are suggested for reasons of health and safety only, regardless of development proposals at this stage. However, the defects requiring remedial tree surgery are by their very nature potential wildlife habitats, including protected species which needs consideration prior to any tree surgery works commencing.
- 8. a) At this stage the Root Protection Area (RPA) information is for your guidance and ongoing discussion purposes only as it assumes that all but the 'U' grade trees will be retained, which may not be the case.

b) For all single stem trees with a stem diameter greater than 1250mm, and multi-stem trees with a stem diameter greater than 1500mm, the calculated RPA has been capped at 707m2 in accordance with Section 4.6.1 of BS5837.2012.

9. Trees marked with * are indicatively plotted on the associated Tree Survey Plan.

TREE PRESERVATION ORDER/CONSERVATION AREA:

CBA Trees has been instructed to investigate whether trees on or adjacent to the site are protected by a Tree Preservation Order or located within a Conservation Area and Richmond Council has confirmed that the site lies within the CA8 Twickenham Riverside Conservation Area but there are no Tree Preservation Orders protecting trees on the site.

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
1	Tree of Heaven Ailanthus altissima	9	S	220	22	2.6	N 4 E 4 S 4 W 3	N 4 E 4 S 4 W 4	Semi- mature	Good	Structural Condition - Fair Developing tree Old pruning wounds Minor deadwood in crown Bark wound on north side of trunk at 1m above ground level occluding	None required at time of survey	20+	C1+2
2	Common Hornbeam <i>Carpinus betulus</i>	5	S	75	3	0.9	N 1 E 1.5 S 1 W 1.5	N 2 E 2 S 2 W 2	Young	Good	Structural Condition - Fair Old pruning wounds Epicormics on trunk Developing tree	None required at time of survey	40+	C2+1
3	Pedunculate Oak <i>Quercus robur</i>	5	S	150	10	1.8	N 3 E 3 S 2.5 W 3	N 1.5 E 1.5 S 1.5 W 1.5	Young	Good	Structural Condition - Fair Bifurcated at 2.5m above ground level Tight forks with included bark Epicormics in crown Developing tree Low hanging branches Minor deadwood in crown Old pruning wounds	Remove secondary leader	40+	B2+1
4	Pedunculate Oak Quercus robur	3	S	80	3	1.0	N 3 E 2.5 S 2.5 W 2.5	N 1 E 1 S 1 W 1	Young	Good	Structural Condition - Good Developing tree Low hanging branches Old pruning wounds	None required at time of survey	40+	C1+2
5	Silver Birch Betula pendula	5	S	100	5	1.2	N 2 E 2 S 2.5 W 2.5	N 1 E 1 S 1 W 1	Young	Good	Structural Condition - Good Developing tree Low hanging branches Good shape and form	None required at time of survey	40+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
6	Sweet Chestnut Castanea sativa	19	S	930	391	11.2	N 8 E 8 S 10 W 8	N 1.5 E 2 S 1.5 W 2	Mature	Good	Structural Condition - Good Epicormics on trunk and in crown Low hanging branches Minor deadwood in crown Old pruning wounds	None required at time of survey	20+	B1+2
7	Pedunculate Oak Quercus robur	18	S	970	426	11.6	N 10 E 9 S 11 W 10	N 1.5 E 2 S 2 W 2	Mature	Good	Structural Condition - Good Large surface roots Exposed surface roots Epicormics in crown Major deadwood in crown	Remove major deadwood	40+	A1
8	Pedunculate Oak <i>Quercus robur</i>	16	S	1000	452	12.0	N 7.5 E 9 S 8 W 9	N 4 E 5 S 5 W 5	Mature	Good	Structural Condition - Fair Bifurcated at 5.0m above ground level Epicormics in crown Major deadwood in crown Old pruning wounds Bark wounds Branch tear out wounds and wildlife holes on main scaffold branches on trunk	Climbing inspection Remove major deadwood	20+	B1+2 Interim
9	Robinia Robinia pseudoacacia	15	S	990	443	11.9	N 9 E 3 S 4 W 6	N 4 E 3 S 6 W 3	Mature	Fair	Structural Condition - Fair Major deadwood in crown Old pruning wounds Previously crown reduced Crown shape distorted due to group pressure Dessicated fungal fruiting body at base Bifurcated at 3m above ground level	None required at time of survey	10+	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
10	Robinia Robinia pseudoacacia	21	S	830	312	10.0	N 5 E 5 S 4 W 4	N 3 E 3 S 3 W 3	Mature	Good	Structural Condition - Fair Previously crown reduced Old pruning wounds Minor deadwood in crown Epicormics on trunk and in crown Crown shape distorted due to group pressure	None required at time of survey	10+	C1+2
11	Atlas Cedar Cedrus atlantica Blue Atlas Cedar	14	S	620	174	7.4	N 8 E 8.5 S 8 W 8	N 1 E 1 S 1 W 1	Early Mature	Good	Structural Condition - Fair Minor deadwood in crown Low hanging branches Numerous branch tears on trunk Upper crown shape distorted due to lost branches	None required at time of survey	20+	B1
12	Common Horse Chestnut <i>Aesculus</i> <i>hippocastanum</i>	21	S	990	443	11.9	N 7 E 7 S 8 W 7	N 5 E 6 S 6 W 6	Mature	Fair	Structural Condition - Fair Epicormics on trunk and in crown Old pruning wounds Previously crown reduced Bifurcated at 13m above ground level Minor deadwood in crown	None required at time of survey	20+	B1+2
13	Sycamore Acer pseudoplatanus	-	-	-	-	-	-	-	-	-	Tree has been removed since original survey	-	-	-
14	Robinia Robinia pseudoacacia	-	-	-	-	-	-	-	-	-	Tree has been removed since original survey	-	-	-

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
15	Flowering Cherry Prunus sp.	4	S	200 140	18	2.4	N 3.5 E 3 S 3 W 3	N 2 E 2 S 2 W 2	Early Mature	Good	Structural Condition - Fair Bifurcated at 1.2m above ground level Bark wounds Low hanging branches Minor deadwood in crown Old pruning wounds Grafted at 1.0m above ground level	None required at time of survey	20+	B1+2
16	Common Yew Taxus baccata	11	S	910	375	10.9	N 6.5 E 6 S 6.5 W 6	N 3 E 2.5 S 2.5 W 2.5	Mature	Good	Structural Condition - Good Epicormics in crown Minor deadwood in crown Ground compaction around base	None required at time of survey	40+	A1+2
17	Common Lime <i>Tilia europaea</i>	19	S	980	434	11.8	N 6 E 4 S 8 W 7	N 2 E 3 S 1.5 W 1.5	Mature	Good	Structural Condition - Good Large buttress roots Minor deadwood in crown Low hanging branches Crown shape distorted due to group pressure	None required at time of survey	20+	B1+2
18	Common Lime <i>Tilia europaea</i>	16	S	970	426	11.6	N 5 E 9 S 9 W 2	N 2 E 2 S 1 W 2	Mature	Good	Structural Condition - Fair Bifurcated at 2.0m above ground level Basal suckers Epicormics on trunk and in crown Low hanging branches Minor deadwood in crown Old pruning wounds Trunk shape distorted due to group pressure Previously crown reduced Leans east	None required at time of survey	10+	C1+2
19	Flowering Cherry Prunus sp.	4	S	190	16	2.3	N 3 E 3 S 3 W 3	N 2 E 2 S 2 W 2	Semi- mature	Good	Structural Condition - Good Multi-stemmed at 2m above ground level	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
20	Flowering Cherry Prunus sp.	6	S	180	15	2.2	N 3 E 2 S 3 W 2	N 2 E 2 S 2 W 2	Semi- mature	Good	Structural Condition - Fair Minor deadwood in crown Tight forks with included bark Multi-stemmed at 1.75m above ground level	None required at time of survey	20+	C1+2
21	Common Elder Sambucas nigra	6	MS x 6	120	-	-	N 4 E 0.5 S 3 W 1.5	N 2 E 2 S 2 W 2	Semi- mature	Fair	Structural Condition - Poor Multi-stemmed at ground level Bark necrosis on stems	Advise removal	<10	U
22	Sycamore Acer pseudoplatanus	11	MS	240 250	54	4.2	N 5 E 3.5 S 4.5 W 2	N 2 E 2 S 2 W 2	Semi- mature	Good	Structural Condition - Fair Bifurcated at 1.0m above ground level Crown shape distorted due to group pressure Epicormics in crown Low hanging branches Minor deadwood in crown Weighted east	None required at time of survey	10+	C1+2
23	Pedunculate Oak <i>Quercus robur</i>	8	S	350	55	4.2	N 5.5 E 5.5 S 5.5 W 1	N 2 E 1.5 S 1.5 W 2	Semi- mature	Good	Structural Condition - Good Crown shape distorted due to group pressure Minor deadwood in crown Multi-stemmed at 2m above ground level	None required at time of survey	40+	B1+2
24	Common Ash Fraxinus excelsior	13	S	330	49	4.0	N 6 E 4 S 5 W 5	N 3 E 3 S 2 W 2	Semi- mature	Good	Structural Condition - Good Crown shape distorted due to group pressure Low hanging branches Minor deadwood in crown	None required at time of survey	20+	B1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
25	Flowering Cherry Prunus sp.	4	S	400	72	4.8	N 6 E 4.5 S 8 W 7	N 2 E 2 S 1.5 W 2	Early Mature	Good	Structural Condition - Fair Large buttress roots Minor deadwood in crown Crown shape distorted due to group pressure Low hanging branches Old pruning wounds Multi-stemmed at 1.5m above ground level	None required at time of survey	10+	C1+2
26	Holm Oak <i>Quercus ilex</i>	9	S	530	127	6.4	N 7 E 7 S 7 W 7	N 2 E 2 S 2 W 2	Early Mature	Good	Structural Condition - Fair Epicormics in crown Minor deadwood in crown Old pruning wounds Multi-stemmed at 4.0m above ground level	None required at time of survey	20+	B1+2
27	Red Oak Quercus rubra	15	S	830	312	10.0	N 9 E 9 S 10 W 9	N 4 E 2 S 2 W 2	Mature	Good	Structural Condition - Good Large buttress roots Old pruning wounds Minor deadwood in crown	None required at time of survey	40+	A1+2
28	Common Walnut Juglans regia	7	S	350	55	4.2	N 6 E 6 S 6.5 W 6	N 2 E 2 S 2 W 2	Semi- mature	Good	Structural Condition - Good Bifurcated at 3.0m above ground level Low hanging branches Minor deadwood in crown Old pruning wounds	None required at time of survey	20+	B1+2
29	London Plane Platanus x hispanica	22	S	1320	707	15	N 11 E 7 S 12 W 12	N 2 E 4 S 1.5 W 1.5	Mature	Good	Structural Condition - Good Major deadwood in crown Low hanging branches Old pruning wounds	Remove deadwood	40+	A1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
30	London Plane Platanus x hispanica	14	S	1220	673	14.6	N 9 E 8 S 9 W 7	N 4 E 4 S 3 W 4	Mature	Fair	Structural Condition - Fair Crown shape distorted due to group pressure Major deadwood in crown Old pruning wounds Cavity at base on east side	Full ground level inspection using decay detection equipment Remove major deadwood	20+	B1+2 Interim
31	Honey Locust Gleditsia triacanthos	14	S	570	147	6.8	N 8 E 8 S 7 W 9	N 3 E 2.5 S 2.5 W 2	Mature	Good	Structural Condition - Fair Bifurcated at 3.5m above ground level Major deadwood in crown Old pruning wounds Mechanical damage to surface roots	None required at time of survey	20+	B1+2
32	Turkey Oak <i>Quercus cerris</i>	15	S	640	185	7.7	N 7.5 E 9 S 9 W 10.5	N 3 E 4 S 2 W 3	Early Mature	Good	Structural Condition - Fair Exposed surface roots Tight forks with included bark Major deadwood in crown Crown shape distorted due to group pressure Bifurcated at 2m above ground level Bark wounds on under side of branches to west	Remove major deadwood	20+	B1+2
33	London Plane Platanus x hispanica	20	S	1750	707	15	N 11 E 9 S 11 W 10	N 2 E 4 S 3 W 5	Mature	Good	Structural Condition - Good Boundary line tree Ivy on trunk Major deadwood in crown Crown shape distorted due to group pressure	Remove major deadwood	40+	A1+2
34	London Plane Platanus x hispanica	22	S	1650	707	15	N 17 E 14 S 11 W 6	N 3 E 3 S 4 W 3	Mature	Good	Structural Condition - Fair Crown shape distorted due to group pressure Epicormics in crown Minor deadwood in crown Old pruning wounds Leans and weighted east	None required at time of survey	40+	B1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
35	Common Ash Fraxinus excelsior	20	S	1190	641	14.3	N 8 E 11.5 S 11 W 7	N 4 E 3 S 2 W 6	Mature	Good	Structural Condition - Fair Boundary line tree Previously pollarded Minor deadwood in crown Crown shape distorted due to group pressure Branch tears in crown Cavities in crown	None required at time of survey	20+	B1+2
36	London Plane Platanus x hispanica	16	S	2000	707	15	N 17 E 15 S 14 W 13	N 0 E 1 S 2 W 0	Mature	Good	Structural Condition - Good Minor deadwood in crown Low hanging branches Boundary line tree	None required at time of survey	40+	A1+2
37	Silver Maple Acer saccharinum	18	S	1210	662	14.5	N 15 E 16 S 5 W 9	N 0 E 2 S 3 W 2	Mature	Good	Structural Condition - Fair Trunk and crown shape distorted Low hanging branches Ganoderma fungal fruiting body at base on south-east side Bifurcated at 3m above ground level	Full ground level inspection using decay detection equipment	20+	B1+2 Interim
38	London Plane Platanus x hispanica	18	S	1650	707	15	N 13 E 13 S 12 W 16	N 2 E 2 S 2 W 1.5	Mature	Good	Structural Condition - Good Major deadwood in crown Low hanging branches Old pruning wounds Dead hanging branch over footpath on south-east side	Remove major deadwood	40+	A1+2
39	Black Walnut Juglans nigra	25	S	1900	707	15	N 18 E 18 S 14 W 17	N 0.5 E 0.5 S 0.5 W 1.5	Over Mature	Good	Structural Condition - Fair Branch tearout wound Old pruning wounds Major deadwood in crown Fenced off area around tree Cavities in crown Cobra bracing in crown	None required at time of survey	40+	A1+3

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
40	Common Lime <i>Tilia europaea</i>	8	S	310	43	3.7	N 5 E 3 S 4 W 4.5	N 1 E 1.5 S 2 W 1.5	Semi- mature	Good	Structural Condition - Fair Bifurcated at 3.0m above ground level Epicormics in crown Low hanging branches Minor deadwood in crown	None required at time of survey	10+	C1+2
41	Common Lime <i>Tilia europaea</i>	21	S	700	222	8.4	N 9 E 5 S 6 W 7	N 1 E 1 S 3 W 2	Early Mature	Good	Structural Condition - Fair Bifurcated at 5.0m above ground level Epicormics on trunk and in crown Crown shape distorted due to group pressure Previously crown reduced Old pruning wounds Minor deadwood in crown Low hanging branches	None required at time of survey	20+	B1+2
42	Common Lime <i>Tilia europaea</i>	21	S	810	297	9.7	N 10 E 6 S 8 W 9	N 1.5 E 2 S 2 W 1.5	Mature	Good	Structural Condition - Good Crown shape distorted due to group pressure Minor deadwood in crown Low hanging branches Old pruning wounds Previously crown reduced Epicormics on trunk Branch tears in crown Dead hanging branch in crown on east side over footpath	Remove major deadwood	20+	B1+2
43	Pedunculate Oak <i>Quercus robur</i>	21	S	1470	707	15	N 8 E 8 S 12.5 W 10	N 0 E 0.5 S 0 W 0	Mature	Good	Structural Condition - Fair Major deadwood in crown Branch tear Old pruning wounds Low hanging branches Large cavity at base on south-east side Wildlife holes throughout Dessicated fungi in crown to south around wildlife holes	Full ground level inspection using decay detection equipment	40+	A1 Interim

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
44	Common Lime <i>Tilia europaea</i>	15	S	470	100	5.6	N 5 E 5 S 5 W 5.5	N 1.5 E 1 S 1.5 W 1.5	Early Mature	Good	Structural Condition - Fair Epicormics on trunk and in crown Bifurcated at 5.0m above ground level Low hanging branches Minor deadwood in crown Old pruning wounds	None required at time of survey	20+	B1+2
45	Common Ash Fraxinus excelsior	14	S	480	104	5.8	N 6 E 6 S 6 W 7	N 2 E 2 S 2 W 2	Early Mature	Good	Structural Condition - Fair Bifurcated at 4.0m above ground level Epicormics in crown Minor deadwood in crown Low hanging branches Old pruning wounds	None required at time of survey	20+	B1+2
46	Birch 'Youngii' <i>Betula youngii</i>	-	-	-	-	-	-	-	-	-	Tree has been removed since original survey	-	-	-
47	Common Yew Taxus baccata	7	MS	200 170 250 200 190	78	5.0	N 5 E 5 S 3 W 4	N 2 E 2 S 3 W 1.5	Early Mature	Good	Structural Condition - Fair Multi stemmed at ground level Epicormics on trunk and in crown Old pruning wounds Minor deadwood in crown Low hanging branches Wall to south	None required at time of survey	10+	C1+2
48	Holm Oak <i>Quercus ilex</i>	20	S	820	304	9.8	N 8 E 6 S 11 W 6	N 3 E 5 S 4 W 4	Mature	Good	Structural Condition - Good Crown shape distorted Minor deadwood in crown Old pruning wounds Multi-stemmed at 4.0m above ground level Previously crown reduced on east side away from main house	None required at time of survey	40+	B1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
49	Birch 'Youngii' <i>Betula youngii</i>	3	S	340	52	4.1	N 3.5 E 6.5 S 5 W 4.5	N 0 E 0 S 0 W 0	Early Mature	Good	Structural Condition - Good Crown shape distorted Low hanging branches Old pruning wounds Multi-stemmed at 2.0m above ground level	None required at time of survey	20+	C1
50	Common Elder Sambucas nigra	4	MS	120 100 100 160 130	35	3.3	N 3 E 5 S 2 W 1	N 2 E 2 S 2 W 2	Semi- mature	Fair	Structural Condition - Fair Minor deadwood in crown Poor quality tree Poor shape and form Multi-stemmed at ground level Growing in car park from base of wall Stem and crown shape distorted Biased to east	None required at time of survey	10+	C1
51*	Common Yew Taxus baccata	7	S	240	26	2.9	N 3 E 3 S 3 W 3	N 2 E 2 S 2 W 2	Semi- mature	Good	Structural Condition - Good Offsite tree Old pruning wounds Crown shape distorted due to group pressure Epicormics on trunk and in crown Low hanging branches Minor deadwood in crown	None required at time of survey	20+	B1+2
52*	Sycamore Acer pseudoplatanus	10	S	550	137	6.6	N 4 E 4 S 4 W 4	N 4 E 4 S 3 W 3	Early Mature	Good	Structural Condition - Fair Offsite tree Unable to verify health and safety due to no access Boundary line tree Minor deadwood in crown Old pruning wounds Previously crown reduced Wall between tree and site	Gain access and resurvey within 1 month	20+	C1+2 Interim

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
53	Common Hornbeam <i>Carpinus betulus</i>	13	S	490	109	5.9	N 6.5 E 4 S 4.5 W 8	N 4.5 E 4 S 3 W 4	Early Mature	Good	Structural Condition - Fair Crown shape distorted due to group pressure Epicormics on trunk and in crown Low hanging branches Major deadwood in crown Bifurcated at 4.5m above ground level Old pruning wounds Weighted west	Remove major deadwood	20+	C1+2
54	Common Hornbeam <i>Carpinus betulus</i>	18	S	620	174	7.4	N 6 E 2 S 8 W 7	N 6 E 5 S 5 W 5	Early Mature	Good	Structural Condition - Good Ivy on trunk Crown shape distorted due to group pressure Minor deadwood in crown Old pruning wounds Previously crown reduced	None required at time of survey	40+	B1+2
55	Common Hornbeam <i>Carpinus betulus</i>	18	S	570	147	6.8	N 7 E 7 S 4 W 4	N 6 E 4 S 5 W 4	Early Mature	Good	Structural Condition - Good Epicormics on trunk Old pruning wounds Crown shape distorted due to group pressure Minor deadwood in crown Multi-stemmed at 5.0m above ground level	None required at time of survey	40+	B1+2
56	Common Hornbeam <i>Carpinus betulus</i>	9	S	330	49	4.0	N 4 E 4 S 3 W 5	N 4 E 3 S 3 W 3	Semi- mature	Fair	Structural Condition - Fair Crown shape distorted due to group pressure Epicormics on trunk and in crown Previously crown reduced Old pruning wounds	None required at time of survey	10+	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
57	Common Hornbeam <i>Carpinus betulus</i>	17	S	550	137	6.6	N 6 E 6 S 6 W 5	N 5 E 2.5 S 4 W 5	Early Mature	Good	Structural Condition - Fair Bifurcated at 4.5m above ground level Tight forks with included bark Old pruning wounds Minor deadwood in crown	None required at time of survey	20+	B1+2
58	Common Horse Chestnut <i>Aesculus</i> <i>hippocastanum</i>	18	S	760	261	9.1	N 5 E 7 S 8 W 7	N 2 E 2 S 2 W 2	Early Mature	Fair	Structural Condition - Fair Part of linear group Crown shape distorted due to group pressure Old pruning wounds Bleeding canker on stem Guignadia and camararia on foliage	None required at time of survey	20+	B1+2
59	Common Horse Chestnut <i>Aesculus</i> <i>hippocastanum</i>	19	S	1110	557	13.3	N 6 E 8 S 9 W 9	N 5 E 4 S 3 W 4	Mature	Fair	Structural Condition - Fair Bifurcated at 5.0m above ground level Epicormics on trunk and in crown Old pruning wounds Previously crown reduced Tight forks with included bark Minor deadwood in crown	None required at time of survey	10+	C1+2
60	Common Horse Chestnut Aesculus hippocastanum	16	S	580	152	7.0	N 3 E 5 S 6 W 5	N 4 E 2 S 2 W 2	Early Mature	Fair	Structural Condition - Fair Part of linear group Old pruning wounds Crossing branches Crown shape distorted due to group pressure Minor deadwood in crown Multi-stemmed at 2m above ground level	None required at time of survey	20+	B1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
61	Common Walnut <i>Juglans regia</i>	17	S	580	152	7.0	N 10 E 12 S 11 W 5	N 1 E 1 S 1 W 1	Early Mature	Good	Structural Condition - Good Crown shape distorted due to group pressure Low hanging branches Minor deadwood in crown Suppressed by T39	None required at time of survey	40+	A1+2
62	Common Lime <i>Tilia europaea</i>	12	S	500	113	6.0	N 6 E 5 S 6 W 3	N 2 E 2 S 2 W 2	Early Mature	Good	Structural Condition - Good Epicormics on trunk and in crown Crown shape distorted due to group pressure Minor deadwood in crown Old pruning wounds Car park edge tree	None required at time of survey	20+	B1+2
63	Common Lime <i>Tilia europaea</i>	14	S	570	147	6.8	N 5 E 3 S 5 W 5	N 3 E 2 S 2 W 2	Early Mature	Good	Structural Condition - Good Epicormics on trunk and in crown Major deadwood in crown Car park edge tree	Remove major deadwood	40+	B1+2
64	Norway Maple Acer platanoides	12	S	540	132	6.5	N 4 E 5 S 5.5 W 5	N 5 E 4 S 3 W 3	Early Mature	Fair	Structural Condition - Fair Bark wound Old pruning wounds Previously crown reduced Growing within car park Roots lifting tarmac Bifurcated at 4.0m above ground level Top previously removed	None required at time of survey	10+	C1
65	Turkey Oak <i>Quercus cerris</i>	20	S	1480	707	15	N 13 E 12 S 13 W 13	N 1 E 1 S 1 W 1	Mature	Good	Structural Condition - Good Large buttress roots Major deadwood in crown Low hanging branches Old pruning wounds Epicormics in crown	Remove major deadwood	40+	A1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
66	Common Lime <i>Tilia europaea</i>	24	S	1070	518	12.8	N 7 E 9 S 7 W 8	N 4 E 5 S 5 W 4	Mature	Good	Structural Condition - Fair Basal suckers Epicormics on trunk and in crown Low hanging branches Minor deadwood in crown Old pruning wounds	None required at time of survey	20+	B1+2
Grp 1	Lime Pedunculate Oak Ash Holly Tree of Heaven Hornbeam False Acacia Beech	15	S	See below	See below	See below	N - E - S - W -	N - E - S - W -	Early Mature	Good	Structural Condition - Fair Crown shape distorted due to group pressure Epicormics on trunk and in crown Low hanging branches Minor deadwood in crown Old pruning wounds Tall and etiolated due to group pressure Trunk shape distorted due to group pressure	None required at time of survey	20+	B1+2
G1.1	Ash	-	S	390	69	4.7	-	-	Semi- mature	-	Major deadwood	-	-	B1+2
G1.2	Common Horse Chestnut	-	S	820	304	9.8	-	-	Early Mature	-	Guignadia and Camararia on foliage Old pruning wounds in crown Crown shape distorted	-	-	B1+2
G1.3	Common Hornbeam	-	S	530	127	6.4	-	-	Early Mature	-	Trunk and crown shape distorted Minor deadwood Low hanging branches	-	-	B1+2
G1.4	Common Hornbeam	-	S	430	84	5.2	-	-	Early Mature	-	Bark wounds on trunk Crown shape distorted Low hanging branches	-	-	B1+2
G1.5	Manna Ash	-	S	420	80	5.0	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G1.6	Lombardy Poplar	-	S	590	157	7.1	-	-	Early Mature	-	-	-	-	B1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G1.7	Lombardy Poplar	-	S	270	33	3.2	-	-	Semi- mature	-	-	-	-	C1+2
G1.8	Norway Maple	-	S	240	26	2.9	-	-	Semi- mature	-	Low hanging branches	-	-	C1+2
G1.9	Sweet Chestnut	-	S	1270	707	15	-	-	Mature	-	Previously topped Basal suckers and epicormic growth form crown Major bark wounds on trunk	Reduce canopy spread within 3 years	-	C1+2+ 3
G1.10	Pedunculate Oak	-	S	610	168	7.3	-	-	Early Mature	-	-	-	-	B1+2
G1.11	Pedunculate Oak	-	S	510	118	6.1	-	-	Early Mature	-	Low hanging branches Multi-stemmed at 3.0m above ground level m	-	-	B1+2
G1.12	Sycamore	-	S	560	142	6.7	-	-	Early Mature	-	Root severance on north side Previously pollarded	-	-	C1+2
G1.13	Holm Oak	-	S	470	100	5.6	-	-	Early Mature	-	Trunk and crown shape distorted Exudate on trunk to south side	-	-	B1+2
G1.14	Sycamore	-	S	570	147	6.8	-	-	Mature	-	-	-	-	C1+2
G1.15	Sycamore	-	S	590	157	7.1	-	-	Early Mature	-	Crown shape distorted	-	-	C1+2
G1.16	Common Holly	-	S	270	33	3.2	-	-	Early Mature	-	Leans east Bifurcated at 2.1m above ground level	-	-	C1+2
G1.17	Common Holly	-	MS	310 360	102	5.7	-	-	Mature	-	Bifurcated at ground level Tight forks with included bark	-	-	C1+2
G1.18	Common Horse Chestnut	-	S	760	261	9.1	-	-	Early Mature	-	Exuate on trunk Bifurcated at 2.5m Guignadia and camararia on foliage	-	-	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G1.19	Common Ash	-	S	460	96	5.5	-	-	Early Mature	-	Branch tears in crown Low hanging branches Minor deadwood Old pruning wounds	-	-	C1+2
G1.20	Pedunculate Oak	-	S	760	261	9.1	-	-	Mature	-	Major deadwood in crown	Remove deadwood	-	B1+2
G1.21	Sycamore	-	S	680	209	8.2	-	-	Early Mature	-	Large buttress roots Cavities in trunk at 5.0m, 7.0m and 9.0m above ground level on north-west side Previously topped	-	-	C1+2
G1.22	Common Horse Chestnut	-	S	680	209	8.2	-	-	Early Mature	-	Branch tear on trunk Desire line under canopy Guignadia and camararia on foliage	-	-	C1+2
G1.23	Common Horse Chestnut	-	S	570	147	6.8	-	-	Early Mature	-	Guignadia and camararia on foliage Low hanging branches	-	-	B1+2
G1.24	Common Horse Chestnut	-	S	800	290	9.6	-	-	Early Mature	-	Bifurcated at 3.0m above ground level Guignadia and camararia on foliage	-	-	C1+2
G1.25	Common Horse Chestnut	-	S	740	248	8.9	-	-	Early Mature	-	Guignadia and camararia on foliage	-	-	C1+2
G1.26	Flowering Cherry	-	S	230	24	2.8	-	-	Semi- mature	-	-	-	-	B1+2
G1.27	Common Lime	-	S	910	375	10.9	-	-	Mature	-	Basal suckers Epicormics on trunk and in crown Old pruning wounds on trunk Deadwood in crown	Remove deadwood	-	C2+1
G1.28	Ash	-	S	300	41	3.6	-	-	Semi- mature	-	Bifurcated at 7.0m above ground level	-	-	B1+2
G1.29	Ash	-	S	460	96	5.5	-	-	Early Mature	-	Bifurcated at 2m above ground level Old pruning wounds on trunk Deadwood in crown	-	-	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G1.30	Common Ash	-	S	280	35	3.4	-	-	Semi- mature	-	Desire line to north-east Bifurcated at 2.0m above ground level Low hanging branches	-	-	C1+2
G1.31	Variegated Holly	-	S	400	72	4.8	-	-	Mature	-	Bifurcated at 5.0m above ground level	-	-	C1+2
G1.32	Common Yew	-	S	680	209	8.2	-	-	Semi- mature	-	Mechanical damage to exposed surface roots Bark wound on trunk Bifurcated at 1.6m above ground level Low hanging branches	-	-	B1+2
G1.33	Common Yew	-	S	340	52	4.1	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G1.34	Sycamore	-	S	670	203	8.0	-	-	Early Mature	-	Large buttress roots Desire line to south Low hanging branches	-	-	B1+2
G1.35	Sycamore	-	S	370	62	4.4	-	-	Early Mature	-	Low hanging branches	-	-	C1+2
G1.36	Common Beech	-	S	930	391	11.2	-	-	Mature	-	Low hanging branches Old pruning wounds in crown Bifurcated at 8.0m above ground level	-	-	B1+2
G1.37	Sycamore	-	S	760	261	9.1	-	-	Early Mature	-	Trunk and crown shape distorted Bifurcated at 4m above ground level Cavities in crown	-	-	B1+2
G1.38*	Sweetgum	-	S	310	43	3.7	-	-	Semi- mature	-	Trunk shape distorted Low hanging branches	-	-	C1+2
G1.39	Whitebeam	-	S	400	72	4.8	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G1.40	Pedunculate Oak	-	S	100	5	1.2	-	-	Young	-	Developing tree	-	-	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G1.41	Sycamore	-	MS	90 70	6	1.4	-	-	Young	-	Basal suckers Low hanging branches Bifurcated at 1.2m above ground level Squirrel damage in crown	-	-	C1+2
G1.42	Highclere Holly	-	S	240	26	2.9	-	-	Semi- mature	-	-	-	-	C1+2
G1.43	Robinia	-	S	230	24	2.8	-	-	Semi- mature	-	Trifurcated at 4.5m above ground level	-	-	C1+2
G1.44*	Robinia	-	S	310	43	3.7	-	-	Semi- mature	-	Trifurcated at 1.6m above ground level Low hanging branches	-	-	C1+2
G1.45	Common Hornbeam	-	S	510	118	6.1	-	-	Mature	-	Low hanging branches Leans north-east Bark wound at base on north- west side	-	-	C1+2
G1.46	Common Holly	-	S	440	88	5.3	-	-	Mature	-	-	-	-	C1+2
G1.47	Common Lime	-	S	770	268	9.2	-	-	Mature	-	Low hanging branches Epicormics on trunk and in crown Large old pruning wounds on trunk	-	-	B1+2
G1.48	Common Holly	-	MS	320 200	64	4.5	-	-	Mature	-	Bifurcated at 1m above ground level Low hanging branches	-	-	C1+2
G1.49*	Robinia	-	MS	30 40	1	0.6	-	-	Young	-	Bifurcated at ground level Natural regeneration	-	-	C1
G1.50	Tree of Heaven	-	S	80	3	1.0	-	-	Young	-	Developing tree	-	-	C1
G1.51	Robinia	-	S	100	5	1.2	-	-	Young	-	Bifurcated at 2.5m above ground level Tight forks with included bark	-	-	C1
G1.52	Common Elder	-	MS x 7	120	46	3.8	-	-	Semi- mature	-	Multi-stemmed at ground level	-	-	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G1.53	Robinia	-	MS	380 400	138	6.6	-	-	Early Mature	-	Young developing trees at base, Bifurcated at ground level South-east side stem has cavity at base on north side	-	-	C1+2
G1.54	Common Elder	-	MS x 6	190	98	5.6	-	-	Semi- mature	-	Multi-stemmed at ground level	-	-	C1+2
G1.55	Sycamore	-	S	120	-	-	-	-	Young	-	Trunk and crown shape distorted Squirrel damage on trunk	Advise removal	-	U
G1.56	Robinia	-	S	230	24	2.8	-	-	Semi- mature	-	-	-	-	C1+2
G1.57	Common Yew	-	MS	100 100	9	1.7	-	-	Young	-	Bifurcated at ground level Low hanging branches	-	-	C1+2
G1.58	Вау	-	S	100	5	1.2	-	-	Young	-	Trunk and crown shape distorted Low hanging branches	-	-	C1+2
G1.59	Common Elder	-	MS x 9	190	-	-	-	-	Early Mature	-	Multi-stemmed at ground level Major deadwood	Advise removal	-	U
G1.60	Common Yew	-	S	80	3	1.0	-	-	Young	-	Developing tree	-	-	C1+2
G1.61	Common Lime	-	S	1060	508	12.7	-	-	Mature	-	Basal suckers Bifurcated at 2.5m above ground level Major deadwood in crown	Remove deadwood	-	B1+2
G1.62	Common Holly	-	S	450	92	5.4	-	-	Early Mature	-	Low hanging branches	-	-	C1+2
G1.63	Sycamore	-	S	540	132	6.5	-	-	Early Mature	-	Cavities in trunk Exudate on trunk Previously topped	-	-	C1+2
G1.64	Common Hornbeam	-	S	560	142	6.7	-	-	Mature	-	Low hanging branches	-	-	B1+2
G1.65	Manna Ash	-	S	320	46	3.8	-	-	Semi- mature	-	Multi-stemmed at 2m above ground level	-	-	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G1.66	Common Ash	-	S	240	26	2.9	-	-	Semi- mature	-	Low hanging branches	-	-	C1+2
G1.67	Tree of Heaven	-	S	660	197	7.9	-	-	Mature	-	Bifurcated at 8m above ground level Low hanging branches	-	-	B1+2
G1.68	Common Horse Chestnut	-	S	820	304	9.8	-	-	Mature	-	Roots lifting tarmac to south- west Exudate on trunk Multi-stemmed at 2m above ground level	-	-	B1+2
G1.69	Common Hornbeam	-	S	110	5	1.3	-	-	Young	-	Developing tree Low hanging branches	-	-	C1+2
G1.70	Common Lime	-	S	560	142	6.7	-	-	Early Mature	-	Large buttress roots	-	-	A1+2
Grp 2	Killarney Strawberry Tree Sweet Chestnut Tree of Heaven Pedunculate Oak Red Oak Pin Oak Rowan Elm Common Lime Holm Oak Hornbeam Hawthorn Robinia	3	S	90	4	1.1	N - E - S - W -	N - E - S - W -	Young	Good	Structural Condition - Good Newly planted trees Stakes and ties still in place Some dead trees Some memorial trees	Remove dead trees	40+	C2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
Grp 3	Holly Cherry Laurel Sycamore Horse Chestnut Yew Elder	15	S	See below	See below	See below	N - E - S - W -	N - E - S - W -	Mature	Good	Structural Condition - Fair Branch tearout wounds Crown shapes distorted due to group pressure Trunk shapes distorted due to group pressure Old pruning wounds Minor deadwood in crowns Low hanging branches Ivy on trunks Epicormics on trunks and in crowns	None required at time of survey	20+	B1+2
G3.1*	Pedunculate Oak	-	S	500	113	6.0	-	-	Early Mature	-	lvy on trunk and in crown Crown shape distorted Previously crown reduced	-	-	B1+2
G3.2	Sycamore	-	S	690	215	8.3	-	-	Early Mature	-	Bifurcated at 8m above ground level	-	-	B1+2
G3.3	Common Horse Chestnut	-	S	600	163	7.2	-	-	Early Mature	-	Trunk and crown shape distorted Leans to north-west	-	-	C1+2
G3.4*	Common Horse Chestnut	-	S	860	335	10.3	-	-	Mature	-	Possible lightning strike running down trunk	-	-	C1+2
G3.5*	Sycamore	-	S	570	147	6.8	-	-	Early Mature	-	Squirrel damage in crown	-	-	C1+2
G3.6*	Sycamore	-	S	300	41	3.6	-	-	Semi- mature	-	Tall and etiolated due to group pressure Bifurcated at 7m above ground level	-	-	C1+2
G3.7*	Common Horse Chestnut	-	S	370	62	4.4	-	-	Early Mature	-	-	-	-	C1+2
G3.8*	Sycamore	-	S	560	142	6.7	-	-	Mature	-	Bifurcated at 7m above ground level	-	-	C1+2
G3.9*	Common Horse Chestnut	-	S	590	157	7.1	-	-	Early Mature	-	Poor quality tree Branch tears in crown Previously crown reduced	-	-	C1+2

CBA10677_2017-05-09 v3 TS

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m ²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G3.10*	Common Horse Chestnut	-	S	410	76	4.9	-	-	Early Mature	-	Poor quality tree Branch tears in crown	-	-	C1+2
G3.11*	Common Horse Chestnut	-	S	790	282	9.5	-	-	Mature	-	Minor deadwood Old pruning wounds	-	-	B1+2
G3.12	Common Lime	-	S	350	55	4.2	-	-	Early Mature	-	Apical dieback Major deadwood in crown Basal suckers	Remove major deadwood	-	C1+2
G3.13	Common Lime	-	S	770	268	9.2	-	-	Mature	-	Trunk shape distorted	-	-	B1+2
G3.14	Sycamore	-	S	600	163	7.2	-	-	Early Mature	-	Exudate on trunk Appears as though main trunk has previously failed at 4m above ground level Two lateral branches grow from side of old pruning wound	Aerial inspection of old wound – within 1 month	-	C1+2 Interim
G3.15	Common Yew	-	S	370	62	4.4	-	-	Early Mature	-	Leans west	-	-	C1+2
G3.16	Sycamore	-	S	670	203	8.0	-	-	Early Mature	-	Crown shape distorted	-	-	B1+2
G3.17	Sycamore	-	S	610	168	7.3	-	-	Mature	-	Basal decay on west side Cavity at 1.5m above ground level on east side of trunk	-	-	C1+2
G3.18*	Sycamore	-	S	700	222	8.4	-	-	Early Mature	-	Trunk and crown shape distorted	-	-	B1+2
G3.19	Common Horse Chestnut	-	S	360	-	-	-	-	Early Mature	-	Longditudinal decay down trunk	Advise removal	-	U
G3.20	Common Horse Chestnut	-	S	520	122	6.2	-	-	Early Mature	-	Leans north	-	-	C1+2
G3.21	Sycamore	-	S	540	-	-	-	-	Mature	-	Topped standing stump	Advise removal	-	U

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G3.22*	Sycamore	-	S	450	92	5.4	-	-	Early Mature	-	Trunk and crown shape distorted	-	-	C1+2
G3.23*	Common Hornbeam	-	S	480	104	5.8	-	-	Early Mature	-	Bifurcated at 5m above ground level	-	-	B1+2
G3.24	Common Horse Chestnut	-	S	640	185	7.7	-	-	Mature	-	-	-	-	B1+2
G3.25	Common Horse Chestnut	-	S	750	-	-	-	-	Dead	-	Topped at 11m above ground level Wildlife holes in trunk	Advise removal	-	U
G3.26	Common Horse Chestnut	-	S	600	163	7.2	-	-	Mature	-	-	-	-	C1+2
G3.27	Common Horse Chestnut	-	S	480	104	5.8	-	-	Early Mature	-	Trunk and crown shape distorted	-	-	C1+2
G3.28*	Common Horse Chestnut	-	S	980	-	-	-	-	Dead	-	Standng stump approximately 14m tall	Advise removal	-	U
G3.29	Common Horse Chestnut	-	S	900	366	10.8	-	-	Mature	-	lvy on trunk Major deadwood in crown In decline	-	-	C1+2
G3.30*	Common Horse Chestnut	-	S	870	-	-	-	-	Mature	-	Standing stump	Advise removal	-	U
G3.31	Common Horse Chestnut	-	S	670	203	8.0	-	-	Mature	-	Topped standing stump with epicormic growth forming canopy Ivy on trunk limits survey	None required at time of survey	10+	C1
G3.32	Norway Maple	-	S	220	22	2.6	-	-	-	-	-	-	-	С
G3.33	Holly	-	S	190	16	2.3	-	-	-	-	-	-	-	С

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G3.34	Holly	-	S	310	44	3.7	-	-	-	-	-	-	-	С
G3.35	Holly	-	S	230	24	2.8	-	-	-	-	-	-	-	С
G3.36*	Acacia	-	S	250	28	3.0	-	-	-	-	-	-	-	С
G3.37*	Acacia	-	S	450	92	5.4	-	-	-	-	-	-	-	С
G3.38*	Oak	-	S	320	46	3.8	-	-	-	-	-	-	-	С
G3.39*	Irish Yew	-	S	150	10	1.8	-	-	-	-	-	-	-	С
G3.40*	Strawberry Tree	-	S	120	7	1.4	-	-	-	-	-	-	-	С
G3.41*	Sycamore	-	S	240	26	2.9	-	-	-	-	-	-	-	С
G3.42*	Acacia	-	S	310	44	3.7	-	-	-	-	-	-	-	С
G3.43*	Yew	-	MS	200 210	38	3.5	-	-	-	-	-	-	-	В
G3.44*	Acacia	-	S	170	13	2.1	-	-	-	-	-	-	-	С
G3.45*	Yew	-	S	120	6.5	1.4	-	-	-	-	-	-	-	С
G3.46*	Acacia	-	S	270	33	3.2	-	-	-	-	-	-	-	С
G3.47*	Acacia	-	S	180	15	2.2	-	-	-	-	-	-	-	С

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G3.48*	Acacia	-	S	260	31	3.1	-	-	-	-	-	-	-	С
G3.49*	Hemlock	-	S	220	22	2.6	-	-	-	-	-	-	-	С
G3.50*	Cherry	-	S	280	35	3.4	-	-	-	-	-	-	-	С
G3.51*	Yew	-	S	130	8	1.6	-	-	-	-	-	-	-	С
G3.52*	Yew	-	MS	160 100	16	2.3	-	-	-	-	-	-	-	С
G3.53*	Cypress	-	S	130	8	1.6	-	-	-	-	-	-	-	С
G3.54*	Cypress	-	S	180	15	2.2	-	-	-	-	-	-	-	С
Grp 4	Poplar Oak Willow Sycamore Horse Chestnut Box Elder Tree of Heaven	15	S	See below	See below	See below	N - E - S - W -	N - E - S - W -	Early Mature	Good	Structural Condition - Fair Crown shapes distorted due to group pressure Epicormics on trunks and in crowns Low hanging branches Major deadwood in crowns Old pruning wounds Trunk shapes distorted due to group pressure	None required at time of survey	20+	B1+2
G4.1	Hybrid Black Poplar	-	S	880	350	10.6	-	-	Mature	-	Numerous branches previously reduced Low hanging branches	-	-	C1+2
G4.2	Turkey Oak	-	S	640	185	7.7	-	-	Early Mature	-	Fused branches in crown Low hanging branches	-	-	B1+2
G4.3	Common Beech	-	S	770	268	9.2	-	-	Early Mature	-	Tight fork at 3m above ground level Major deadwood Low hanging branches	-	-	B1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G4.4	Pedunculate Oak	-	S	990	443	11.9	-	-	Mature	-	Low hanging branches Major deadwood in crown Leans west	Remove major deadwood	-	C1+2
G4.5	Pedunculate Oak	-	S	590	157	7.1	-	-	Early Mature	-	Trunk and crown shape distorted Major deadwood Low hanging branches	-	-	B1+2
G4.6	Pedunculate Oak	-	S	500	113	6.0	-	-	Early Mature	-	Major deadwood High canopy	-	-	B1+2
G4.7	Common Lime	-	S	800	290	9.6	-	-	Mature	-	Low hanging branches Basal suckers	-	-	B1+2
G4.8	Common Horse Chestnut	-	S	1330	707	15	-	-	Mature	-	Large buttress roots Low hanging branches Deadwood Guignadia and camararia on foliage	-	-	B1+2
G4.9	Common Horse Chestnut	-	S	370	62	4.4	-	-	Semi- mature	-	-	-	-	C1+2
G4.10	Common Horse Chestnut	-	S	700	222	8.4	-	-	Early Mature	-	Bifurcated at 2m above ground level with tight fork and reaction wood Minor deadwood Low hanging branches Guignadia and camararia on foliage	-	-	C1+2
G4.11	Hybrid Black Poplar	-	S	760	261	9.1	-	-	Mature	-	Bifurcated at 7m above ground level Appears to have have been historically topped Storm damage in crown Branch tear out wounds Hung up branch in crown	Remove major deadwood Tidy storm damage and remove hung up branch	-	C1+2
G4.12	Ashleaf Maple	-	S	230	24	2.8	-	-	Semi- mature	-	Crown shape distorted Low hanging branches Minor deadwood	-	-	C1+2
G4.13	Swedish Whitebeam	-	S	310	43	3.7	-	-	Semi- mature	-	Trunk and crown shape distorted Leans to south-east	-	-	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G4.14	Common Horse Chestnut	-	S	240	26	2.9	-	-	Semi- mature	-	Crown shape distorted	-	-	C1+2
G4.15	Ashleaf Maple	-	S	340	52	4.1	-	-	Early Mature	-	Bifurcated at 5m above ground level Major deadwood in crown	Remove major deadwood	-	B1+2
G4.16	Ashleaf Maple	-	S	360	59	4.3	-	-	Semi- mature	-	Crown shape distorted Low hanging branches Minor deadwood	-	-	C1+2
G4.17	Common Horse Chestnut	-	S	370	-	-	-	-	Semi- mature	-	Bark wounds on trunk	Advise removal	-	U
G4.18	Hybrid Black Poplar	-	S	780	275	9.4	-	-	Early Mature	-	Bifurcated at 4m above ground level Minor deadwood	-	-	B1+2
G4.19	Common Lime	-	S	450	92	5.4	-	-	Early Mature	-	Low hanging branches Bifurcated at 4.5m above ground level	-	-	B1+2
G4.20	Mountain Ash	-	S	280	35	3.4	-	-	Early Mature	-	Multi-stemmed at 2m above ground level Low hanging branches	-	-	B1+2
G4.21	Western Balsam Poplar	-	S	650	191	7.8	-	-	Early Mature	-	Previously crown reduced Old pruning wounds Low hanging branches	-	-	C1+2
G4.22	Western Balsam Poplar	-	S	560	142	6.7	-	-	Mature	-	Bifurcated at 6m above ground level	-	-	C1+2
G4.23	Common Lime	-	S	400	72	4.8	-	-	Semi- mature	-	Low hanging branches	-	-	B1+2
G4.24	Western Balsam Poplar	-	S	580	152	7.0	-	-	Mature	-	Bifurcated at 2.5m above ground level	-	-	C1+2
G4.25	Common Lime	-	S	440	88	5.3	-	-	Semi- mature	-	Low hanging branches	-	-	B1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G4.26	Crack Willow	-	S	680	209	8.2	-	-	Mature	-	Multi-stemmed at 4m above ground level	-	-	C1+2
G4.27	Lombardy Poplar	-	S	980	434	11.8	-	-	Mature	-	Major deadwood	-	-	B1+2
G4.28	Common Lime	-	S	530	127	6.4	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G4.29	Common Lime	-	S	490	109	5.9	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G4.30	Lombardy Poplar	-	S	740	248	8.9	-	-	Early Mature	-	Major deadwood	-	-	B1+2
G4.31	Lombardy Poplar	-	S	830	312	10.0	-	-	Early Mature	-	Major deadwood in crown	Remove major deadwood	-	B1+2
G4.32	Lombardy Poplar	-	S	900	366	10.8	-	-	Early Mature	-	Major deadwood	-	-	B1+2
G4.33	Lombardy Poplar	-	S	780	275	9.4	-	-	Early Mature	-	Major deadwood	-	-	B1+2
G4.34	Lombardy Poplar	-	S	770	268	9.2	-	-	Early Mature	-	Major deadwood in crown	Remove major deadwood	-	B1+2
G4.35	Common Lime	-	S	550	137	6.6	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G4.36	Tree of Heaven	-	S	350	55	4.2	-	-	Semi- mature	-	Crown shape distorted	-	-	C1+2
G4.37	Crack Willow	-	S	1120	567	13.4	-	-	Mature	-	Major deadwood in crown	Remove major deadwood	-	C1+2
G4.38	Crack Willow	-	S	900	366	10.8	-	-	Mature	-	Cavity in trunk to east Major deadwood Crown shape distorted	Full ground level inspection with Decay detection equipment – within 1 month	-	C1+2 Interim

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G4.39	Crack Willow	-	S	1070	518	12.8	-	-	Mature	-	Young fungal fruiting body at base on south side Trifurcated at ground level Major deadwood in crown	Remove major deadwood	-	C1+2
G4.40*	Crack Willow	-	S	970	426	11.6	-	-	Mature	-	Crown shape distorted Major deadwood	-	-	B1+2
G4.41	Sycamore	-	S	460	96	5.5	-	-	Early Mature	-	Bifurcated at 3.5m above ground level	-	-	C1+2
G4.42	Common Ash	-	S	730	241	8.8	-	-	Early Mature	-	Major deadwood	-	-	B1+2
G4.43	Sycamore	-	S	440	88	5.3	-	-	Early Mature	-	Bifurcated at 4m above ground level Weighted south Major deadwood in crown	-	-	C1+2
G4.44	Sycamore	-	S	440	88	5.3	-	-	Semi- mature	-	Bifurcated at 2m above ground level Old pruning wounds Crown shape distorted	-	-	C1+2
Grp 5	Elder Sycamore Ash Holly	9	S	300	41	3.6	N - E - S - W -	N - E - S - W -	Early Mature	Good	Structural Condition - Fair Offsite trees Crown shapes distorted due to group pressure Epicormics on trunks and in crowns Basal suckers Low hanging branches Minor deadwood in crowns Trunk shape distorted due to group pressure	None required at time of survey	10+	C1+2
G5.1	Common Ash	-	S	440	88	5.3	-	-	Early Mature	-	Offsite tree Trunk shape distorted due to group pressure Weighted south-east	-	-	C1+2
G5.2	Common Ash	-	S	600	163	7.2	-	-	Early Mature	-	Offsite tree Weighted south Major deadwood in crown	Remove major deadwood	-	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G5.3	Common Ash	-	S	450	92	5.4	-	-	Early Mature	-	Offsite tree Trunk shape distorted due to group pressure Major deadwood in crown	Remove major deadwood	-	C1+2
G5.4	Common Ash	-	MS	340 320	99	5.6	-	-	Early Mature	-	Offsite tree Trunk shape distorted due to group pressure Major deadwood in crown Bifurcated at ground level	Remove major deadwood	-	C1+2
G5.5	Sycamore	-	MS	300 290	79	5.0	-	-	Early Mature	-	Offsite tree Trunk shape distorted due to group pressure Major deadwood in crown	Remove major deadwood	-	C1+2
G5.6	Common Ash	-	S	490	109	5.9	-	-	Early Mature	-	Offsite tree Trunk shape distorted due to group pressure Major deadwood in crown Weighted south-east	Remove major deadwood	-	C1+2
G5.7	Common Ash	-	S	390	-	-	-	-	Early Mature	-	Offsite tree Trunk shape distorted due to group pressure Major deadwood in crown Decay at base	Advise removal	-	U
G5.8	Sycamore	-	S	540	132	6.5	-	-	Early Mature	-	Offsite tree	-	-	C1+2
Grp 6		18	S	See below	See below	See below	N - E - S - W -	N - E - S - W -	Early Mature	Good	Structural Condition - Good Crown shapes distorted due to group pressure Minor deadwood in crowns Low hanging branches Linear group of trees lining footpath Provides good landscape feature Mixed species	None required at time of survey	40+	B2
G6.1	Sycamore	-	S	740	248	8.9	-	-	Early Mature	-	Bifurcated at 4m above ground level Cavity at base on north-west side Crown density reduced	Full ground level inspection with Decay detection equipment – within 1 month	-	B1+2 Interim

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G6.2	Turkish Hazel	-	S	620	174	7.4	-	-	Mature	-	Low hanging branches	-	-	B1+2
G6.3	Common Walnut	-	S	530	127	6.4	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G6.4	Common Lime	-	S	680	209	8.2	-	-	Early Mature	-	Epicormics in crown Low hanging branches	-	-	B1+2
G6.5	Common Lime	-	S	640	185	7.7	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G6.6	Common Lime	-	S	780	275	9.4	-	-	Early Mature	-	Bifurcated at 2m above ground level Minor deadwood	-	-	B1+2
G6.7	Common Lime	-	S	630	180	7.6	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G6.8	Common Lime	-	S	640	185	7.7	-	-	Early Mature	-	Epicormics in crown Low hanging branches	-	-	B1+2
G6.9	Common Lime	-	S	520	122	6.2	-	-	Early Mature	-	Low hanging branches Storm damage in north of crown	-	-	B1+2
G6.10	Common Lime	-	S	590	157	7.1	-	-	Early Mature	-	Bifurcated at 2m above ground level Low hanging branches	-	-	B1+2
G6.11	Common Lime	-	S	530	127	6.4	-	-	Early Mature	-	Low hanging branches Multi-stemmed at 4.5m above ground level	-	-	B1+2
G6.12	Common Lime	-	S	510	118	6.1	-	-	Early Mature	-	Bifurcated at 2m above ground level with tight fork Low hanging branches	-	-	B1+2
G6.13	Common Lime	-	S	590	157	7.1	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G6.14	Turkish Hazel	-	S	390	69	4.7	-	-	Early Mature	-	Bifurcated at 4m above ground level Low hanging branches	-	-	B1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G6.15	Common Lime	-	S	560	142	6.7	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G6.16	Common Lime	-	S	590	157	7.1	-	-	Early Mature	-	Previously pollarded at 4m above ground level	-	-	B1+2
G6.17	Common Ash	-	S	690	215	8.3	-	-	Early Mature	-	Low hanging branches Weighted east Major deadwood in crown	Remove major deadwood	-	B1+2
G6.18	Common Lime	-	S	640	185	7.7	-	-	Early Mature	-	Bifurcated at 4m above ground level Low hanging branches Minor deadwood	-	-	B1+2
G6.19	Common Lime	-	S	870	342	10.4	-	-	Early Mature	-	Previously topped Basal suckers	-	-	C1+2
G6.20	Common Lime	-	S	580	152	7.0	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G6.21	Common Lime	-	S	540	132	6.5	-	-	Early Mature	-	Basal suckers Low hanging branches	-	-	B1+2
G6.22	Common Lime	-	S	590	157	7.1	-	-	Early Mature	-	Cavity at base on south-west side Previously topped at 8m above ground level	-	-	C1+2
G6.23	Common Lime	-	S	530	127	6.4	-	-	Early Mature	-	Bifurcated at 3.5m above ground level Low hanging branches	-	-	B1+2
G6.24	Common Lime	-	S	460	96	5.5	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G6.25	Common Yew	-	S	580	152	7.0	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G6.26	Common Lime	-	S	700	222	8.4	-	-	Early Mature	-	Estimatd data Basal suckers Low hanging branches	Clear around base and re-survey within 1 month	-	B1+2 Interim

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G6.27	Common Lime	-	S	670	203	8.0	-	-	Early Mature	-	Basal suckers Low hanging branches	-	-	B1+2
G6.28	Common Lime	-	S	700	222	8.4	-	-	Early Mature	-	Basal suckers Low hanging branches Minor deadwood	-	-	B1+2
G6.29	Common Ash	-	S	410	76	4.9	-	-	Semi- mature	-	Crown shape distorted Minor deadwood	-	-	B1+2
G6.30	Norway Maple	-	S	500	113	6.0	-	-	Early Mature	-	Bifurcated at 2m above ground level	-	-	B1+2
Grp 7	Pedunculate Oak Ash Yew Robinia Field Maple Sycamore Holm Oak Hawthorn Dogwood Holly Cherry Laurel Portugal Laurel Spotted Laurel Elm Snowberry Norway Maple	14	S	See below	See below	See below	N - E - S - W -	N - E - S - W -	Early Mature	Good	Structural Condition - Fair Crown shapes distorted due to group pressure Trunk shapes distorted due to group pressure Branch tears Epicormics on trunks and in crowns Low hanging branches Major deadwood in crowns Old pruning wounds Some trees multi-stemmed at various heights	None required at time of survey	20+	B1+2
G7.1	Common Yew	-	S	590	157	7.1	-	-	Early Mature	-	Low hanging branches	-	-	B1+2
G7.2	Common Ash	-	S	450	92	5.4	-	-	Early Mature	-	lvy on trunk	-	-	B1+2
G7.3	Common Ash	-	S	470	100	5.6	-	-	Early Mature	-	Trunk and crown shape distorted	-	-	B1+2
G7.4	Wild Cherry	-	S	350	55	4.2	-	-	Early Mature	-	Canker on trunk	-	-	C1+2
G7.5	Sycamore	-	S	310	43	3.7	-	-	Semi- mature	-	Trunk and crown shape distorted Minor deadwood	-	-	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.6	Sycamore	-	S	350	55	4.2	-	-	Semi- mature	-	lvy on trunk and in crown Major deadwood in crown	Sever ivy Remove major deadwood	-	C1+2
G7.7	Common Ash	-	S	490	109	5.9	-	-	Early Mature	-	Trunk and crown shape distorted Bifurcated at 4m above ground level Minor deadwood	-	-	B1+2
G7.8	Common Lime	-	S	360	-	-	-	-	Early Mature	-	Decay in trunk Previously topped	Advise removal	<10	U
G7.9	Common Yew	-	S	760	-	-	-	-	Mature	-	Chicken of the woods at base on south side of dead stem Tree was bifurcated at 1.3m above ground level but southern stem removed	Advise removal	<10	U
G7.10	Common Ash	-	S	540	132	6.5	-	-	Early Mature	-	Exposed surface roots Trunk and crown shape distorted	-	-	B1+2
G7.11	Common Ash	-	S	400	72	4.8	-	-	Semi- mature	-	Bifurcated at 5m above ground level	-	-	B1+2
G7.12*	Common Yew	-	S	540	132	6.5	-	-	Early Mature	-	Bifurcated at 1.6m above ground level	-	-	C1+2
G7.13	Common Ash	-	S	520	122	6.2	-	-	Early Mature	-	Trunk and crown shape distorted	-	-	B1+2
G7.14	Pedunculate Oak	-	S	790	282	9.5	-	-	Mature	-	Ivy on trunk Large wounds in crown Major deadwood in crown	Sever ivy	-	B1+2
G7.15	Common Ash	-	S	550	137	6.6	-	-	Early Mature	-	Trunk and crown shape distorted Ivy on trunk and in crown	-	-	B1+2
G7.16	Common Lime	-	S	800	290	9.6	-	-	Early Mature	-	Ivy on trunk and in crown Minor deadwood	-	-	B1+2
G7.17	Common Yew	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G7.18	English Elm	-	MS	140 170	22	2.6	-	-	Semi- mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m ²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.19	Field Maple	-	MS	120 120	7	1.4	-	-	Young	-	-	None required at time of survey	10+	C1
G7.20	Field Maple	-	S	130	8	1.6	-	-	Young	-	-	None required at time of survey	10+	C1
G7.21*	Field Maple	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.22	Field Maple	-	S	300	41	3.6	-	-	Early Mature	-	-	None required at time of survey	10+	C1
G7.23*	Field Maple	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.24	Common Hawthorn	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	10+	C1
G7.25	Norway Maple	-	MS	110 80	8	1.6	-	-	Young	-	-	None required at time of survey	10+	C1
G7.26	Sycamore	-	MS	300 370 180	117	6.1	-	-	Early Mature	-	-	None required at time of survey	10+	C1
G7.27	Privet	-	S	220	22	2.6	-	-	Mature	-	-	None required at time of survey	10+	C1
G7.28	Field Maple	-	MS	230 230	48	3.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.29	Field Maple	-	S	240	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.30	Field Maple	-	MS	110 120	12	2.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.31	Common Ash	-	S	200	18	2.4	-	-	Young	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.32	Sweet Chestnut	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	20+	C1
G7.33	Sycamore	-	S	140	9	1.7	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.34	Sweet Chestnut	-	S	210	20	2.5	-	-	Young	-	-	None required at time of survey	20+	C1
G7.35	Common Hawthorn	-	MS x6	40	4	1.2	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.36	Common Holly	-	S	120	7	1.4	-	-	Dead	-	-	None required at time of survey	N/A	U
G7.37	Field Maple	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.38	Common Holly	-	S	140	9	1.7	-	-	Dead	-	-	None required at time of survey	N/A	U
G7.39	Common Ash	-	S	160	12	1.9	-	-	Young	-	-	None required at time of survey	10+	C1
G7.40	Field Maple	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.41	Field Maple	-	S	120	7	1.4	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.42	Field Maple	-	S	250	28	3.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.43	Field Maple	-	S	260	31	3.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.44*	Common Hawthorn	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.45	Pedunculate Oak	-	S	350	55	4.2	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G7.46	Pedunculate Oak	-	MS	150 170	23	2.7	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.47	Field Maple	-	S	170	13	2.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.48	Field Maple	-	S	150	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.49	Common Ash	-	S	130	8	1.6	-	-	Young	-	-	None required at time of survey	20+	C1
G7.50	Common Ash	-	S	240	26	2.9	-	-	Young	-	-	None required at time of survey	20+	C1
G7.51	Field Maple	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.52	Field Maple	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G7.53*	Common Ash	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G7.54	English Elm	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.55	Common Ash	-	MS	160 230 230 260 240	116	6.1	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G7.56	Field Maple	-	MS	100 100	9	1.7	-	-	Young	-	-	None required at time of survey	10+	C1
G7.57	Common Hawthorn	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.58	Pedunculate Oak	-	S	240	26	2.9	-	-	Young	-	-	None required at time of survey	20+	C1
G7.59	Field Maple	-	S	240	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.60	Field Maple	-	S	190	16	2.3	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.61	Field Maple	-	S	160	12	1.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.62*	Field Maple	-	S	160	12	1.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.63	English Elm	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.64	Common Ash	-	S	170	13	2.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.65	Field Maple	-	S	170	13	2.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.66	Field Maple	-	S	160	12	1.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.67	Pedunculate Oak	-	S	250	28	3.0	-	-	Young	-	-	None required at time of survey	20+	C1
G7.68	Field Maple	-	S	170	13	2.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.69	Field Maple	-	S	170	13	2.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.70	Holm Oak	-	S	170	13	2.0	-	-	Young	-	-	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.71	Holm Oak	-	MS	110 90	9	1.7	-	-	Young	-	-	None required at time of survey	10+	C1
G7.72	Pedunculate Oak	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.73	Common Ash	-	S	190	16	2.3	-	-	Young	-	-	None required at time of survey	10+	C1
G7.74	Holm Oak	-	MS x12	160	139	6.7	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G7.75	Holm Oak	-	MS x6	20	1	0.6	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.76	Holm Oak	-	MS	110 40	6	1.4	-	-	Young	-	-	None required at time of survey	10+	C1
G7.77	Holm Oak	-	S	200	18	2.4	-	-	Young	-	-	None required at time of survey	20+	C1
G7.78	Holm Oak	-	S	170	13	2.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.79	Holm Oak	-	MS	90 80 80 60	11	1.9	-	-	Young	-	-	None required at time of survey	10+	C1
G7.80	Holm Oak	-	S	170	13	2.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.81	English Elm	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.82	English Elm	-	S	80	3	1.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.83	Holm Oak	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m ²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.84	Holm Oak	-	MS	170 200	31	3.1	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G7.85	Holm Oak	-	S	190	16	2.3	-	-	Young	-	-	None required at time of survey	10+	C1
G7.86	Holm Oak	-	S	160	12	1.9	-	-	Young	-	-	None required at time of survey	10+	C1
G7.87	Holm Oak	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.88	Holm Oak	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	10+	C1
G7.89	Holm Oak	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.90	Common Hawthorn	-	S	190	16	2.3	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.91	Holm Oak	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	10+	C1
G7.92	English Elm	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.93	Dogwood	-	MS	40	2.9	1.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.94	Holm Oak	-	S	110	5	1.3	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.95	Robinia	-	S	260	31	3.1	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G7.96	Robinia	-	MS	260 270	64	4.5	-	-	Early Mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.97	Robinia	-	S	260	31	3.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.98	Robinia	-	MS	190 270	49	4.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.99	Robinia	-	MS	240 260	57	4.2	-	-	Early Mature	-	-	None required at time of survey	10+	C1
G7.100 *	Common Hawthorn	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.101	English Elm	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.102	Common Holly	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.103	Field Maple	-	S	130	8	1.6	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.104	Field Maple	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G7.105	Wild Cherry	-	S	340	52	4.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.106	Field Maple	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	10+	C1
G7.107	Field Maple	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	10+	C1
G7.108	Field Maple	-	MS	130 110	13	2.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.109	Field Maple	-	S	160	12	1.9	-	-	Young	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.110	Common Ash	-	S	310	43	3.7	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.111	Field Maple	-	S	140	9	1.7	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.112	Common Lime	-	S	80	3	1.0	-	-	Young	-	-	None required at time of surve	20+	C1
G7.113	Field Maple	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.114	Field Maple	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.115	Common Yew	-	S	280	35	3.4	-	-	Young	-	-	None required at time of survey	20+	C1
G7.116	Common Lime	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	10+	C1
G7.117	Common Ash	-	S	370	62	4.4	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G7.118	Field Maple	-	MS	110 80	8	1.6	-	-	Young	-	-	None required at time of survey	10+	C1
G7.119	Common Lime	-	MS	120	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.120	Common Lime	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G7.121	Wild Cherry	-	S	220	22	2.6	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.122	Common Hawthorn	-	S	110	5	1.3	-	-	Semi- mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.123	Common Hornbeam	-	S	300	41	3.6	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.124	Wild Cherry	-	S	210	20	2.5	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.125	Common Hawthorn	-	S	140	9	1.7	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.126	Common Hawthorn	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.127	Common Holly	-	MS	130 80	11	1.8	-	-	Young	-	-	None required at time of survey	10+	C1
G7.128	Common Holly	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.129 *	Whitebeam	-	S	200	18	2.4	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.130 *	English Elm	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.131 *	Common Holly	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.132 *	Common Holly	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	С
G7.133	English Elm	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.134	English Elm	-	S	180	15	2.2	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.135	Common Hawthorn	-	MS	110 140	14	2.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.136	Common Ash	-	S	190	16	2.3	-	-	Young	-	-	None required at time of survey	10+	C1
G7.137	Norway Maple	-	S	310	43	3.7	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G7.138	Common Holly	-	MS	90 110	9	1.7	-	-	Young	-	-	None required at time of survey	<10	U
G7.139	Cherry Laurel	-	MS	100 80	7	1.5	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.140 *	Cherry Laurel	-	MS	80 60	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.141	Cherry Laurel	-	MS x4	120	39	3.5	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.142 *	Cherry Laurel	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.143	Common Hawthorn	-	S	100	-	-	-	-	Dead	-	-	Advise removal	N/A	U
G7.144	Portugal Laurel	-	MS	190 170	29	3.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.145	Common Holly	-	MS	210 220	42	3.6	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.146	Common Holly	-	MS	170 180	28	3.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.147	Common Holly	-	S	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.148	Common Ash	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.149	Norway Maple	-	S	140	-	-	-	-	Young	-	-	None required at time of survey	<10	U
G7.150	Common Holly	-	S	290	38	3.5	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.151	Robinia	-	S	340	52	4.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.152 *	English Elm	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	С
G7.153	Wild Cherry	-	S	160	12	1.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.154	Wild Cherry	-	S	230	24	2.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.155	Common Holly	-	MS	200 180	33	3.2	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.156	Common Hawthorn	-	MS	200 130	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.157	Common Holly	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.158	English Elm	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.159	Common Holly	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.160	Common Holly	-	MS	80 100	7	1.5	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.161	Holm Oak	-	MS	150 150 150 150	41	3.6	-	-	Semi- mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.162	Norway Maple	-	S	210	20	2.5	-	-	Young	-	-	None required at time of survey	10+	C1
G7.163	Common Horse Chestnut	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	10+	C1
G7.164	Field Maple	-	MS	150 130 160	29	3.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.165	Robinia	-	S	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.166	Robinia	-	S	260	31	3.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.167	Norway Maple	-	S	150	10	1.8	-	-	Young	-	-	None required at time of survey	10+	C1
G7.168	Common Holly	-	S	200	18	2.4	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.169	Common Holly	-	S	250	28	3.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.170	English Elm	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.171	English Elm	-	S	95	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.172	Common Holly	-	S	260	31	3.1	-	-	Early Mature	-	-	None required at time of survey	10+	C1
G7.173	Common Holly	-	S	230	24	2.8	-	-	Early Mature	-	-	None required at time of survey	10+	C1
G7.174	Common Holly	-	S	160	12	1.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.175	Common Holly	-	S	190	16	2.3	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.176	Norway Maple	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G7.177	Sycamore	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.178	Common Holly	-	s	210	20	2.5	-	-	Young	-	-	None required at time of survey	10+	C1
G7.179	Norway Maple	-	S	180	15	2.2	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.180	Common Holly	-	S	260	31	3.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.181	Field Maple	-	S	160	12	1.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.182	Field Maple	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	10+	C1
G7.183	Common Holly	-	S	170	13	2.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.184	Common Hawthorn	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.185	Robinia	-	S	260	31	3.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.186	Wild Cherry	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.187	Robinia	-	S	180	15	2.2	-	-	Semi- mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.188	Common Hawthorn	-	MS	80 80 80	9	1.7	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.189	Common Hawthorn	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G7.190	Holm Oak	-	S	290	38	3.5	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.191	Robinia	-	MS	330 370	111	5.9	-	-	Early Mature	-	-	None required at time of survey	10+	C1
G7.192	Cherry Laurel	-	MS	140 120 160 100	32	3.2	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.193	Wild Cherry	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	10+	C1
G7.194	Holm Oak	-	S	200	18	2.4	-	-	Young	-	-	None required at time of survey	10+	C1
G7.195	English Elm	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G7.196	Holm Oak	-	MS	100 100	9	1.7	-	-	Young	-	-	None required at time of survey	10+	C1
G7.197	Holm Oak	-	MS	160 240	38	3.5	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.198	Pedunculate Oak	-	S	130	8	1.6	-	-	Young	-	-	None required at time of survey	10+	C1
G7.199	Common Holly	-	S	160	12	1.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G7.200	Common Holly	-	MS x6	80	17	2.4	-	-	Semi- mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G7.201	Wild Cherry	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G7.202	Common Yew	-	S	160	12	1.9	-	-	Young	-	-	None required at time of survey	10+	C1
G7.203	Common Yew	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	10+	C1
G7.204	Common Yew	-	S	130	8	1.6	-	-	Young	-	-	None required at time of survey	10+	C1
G7.205	Wild Cherry	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
Grp 8	Yew Sycamore Ash Oak Hornbeam Elm, Hazel, Laurel, Ivy, Butchers Broom	14	S	350	55	4.2	N - E - S - W -	N - E - S - W -	Early Mature	Good	Structural Condition - Good Crown shapes distorted due to group pressure Major deadwood in crowns Low hanging branches Ivy on trunks and in crowns Small wooded area Mixed species Variety of habitats (fallen deadwood, standing deadwood, ivy, cavities)	None required at time of survey	40+	B2
G8.1	Common Hornbeam	-	S	700	222	8.4	-	-	Early Mature	-	Multi-stemmed at 1.9m above ground level Ivy on trunk and in crown Minor deadwood	-	-	B1+2
G8.2	Common Yew	-	S	630	180	7.6	-	-	Early Mature	-	Minor deadwood Crown shape distorted	-	-	B1+2
G8.3	Common Yew	-	S	670	203	8.0	-	-	Early Mature	-	Leans south-east	-	-	C1+2
G8.4	Common Yew	-	S	550	137	6.6	-	-	Early Mature	-	Cavity in trunk on south side	-	-	C2+1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m ²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G8.5	Sycamore	-	S	560	142	6.7	-	-	Early Mature	-	lvy on trunk and in crown Crown shape distorted	-	-	B1+2
G8.6	Common Ash	-	S	560	142	6.7	-	-	Early Mature	-	Broken hanging branch on south-east side Minor deadwood	-	-	B1+2
G8.7	Common Lime	-	S	530	127	6.4	-	-	Early Mature	-	Leans west	-	-	B1+2
G8.8	Common Ash	-	-	-	-	-	-	-	-	-	Tree has been removed since original survey	-	-	-
G8.9	Common Yew	-	S	340	52	4.1	-	-	Semi- mature	-	Wall to north	-	-	C1+2
G8.10	Common Yew	-	S	460	96	5.5	-	-	Semi- mature	-	Wall to north House to west	-	-	C1+2
G8.11	Common Yew	-	S	190	16	2.3	-	-	Young	-	Wall to north House to west	-	-	C1+2
G8.12	Common Holly	-	S	350	55	4.2	-	-	Early Mature	-	Trunk and crown shape distorted Leans to north	-	-	C1+2
G8.13	Common Yew	-	S	320	46	3.8	-	-	Semi- mature	-	-	None required at time of survey	40+	C1
G8.14	Common Lime	-	MS	190 160	28	3.0	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.15	Common Hawthorn	-	S	240	26	2.9	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G8.16*	Common Ash	-	S	130	8	1.6	-	-	Young	-	-	None required at time of survey	20+	C1
G8.17	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.18	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G8.19	Common Box	-	MS	80 60 60 50	7	1.5	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G8.20*	Common Box	-	S	75	3	0.9	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.21*	Common Hawthorn	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.22	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.23	English Elm	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	10+	C1
G8.24	Common Hornbeam	-	S	200	18	2.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.25	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.26	English Elm	-	S	150	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.27	English Elm	-	S	100	5	1.2	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.28	English Elm	-	S	150	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.29	Common Ash	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	20+	C1
G8.30	Common Holly	-	MS	80 80 80	9	1.7	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.31	Wild Cherry	-	S	260	-	-	-	-	Dead	-	-	None required at time of survey	N/A	U

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G8.32	English Elm	-	S	150	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.33	English Elm	-	S	150	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.34	English Elm	-	S	150	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.35*	English Elm	-	MS	130 150	18	2.4	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.36	Field Maple	-	S	90	4	1.1	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.37*	English Elm	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G8.38	English Elm	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G8.39	English Elm	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G8.40	Common Ash	-	MS	200 190	34	3.3	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.41	Common Holly	-	S	320	46	3.8	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G8.42*	Sycamore	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.43	Common Ash	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G8.44*	English Elm	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G8.45*	English Elm	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G8.46*	English Elm	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G8.47*	English Elm	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G8.48*	English Elm	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G8.49	Griselinia littoralis	-	MS	220 240 280	83	5.2	-	-	Mature	-	-	None required at time of survey	10+	C1
G8.50	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.51	Common Ash	-	MS	160 160	23	2.7	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.52*	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.53	Sycamore	-	S	120	-	-	-	-	Dead	-	-	Advise removal	N/A	U
G8.54*	Sycamore	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	20+	C1
G8.55	Common Holly	-	MS	220 280	57	4.3	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G8.56	Common Holly	-	MS	270 390	102	5.7	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G8.57	Common Elder	-	MS	120 130	14	2.1	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.58	Common Holly	-	S	250	28	3.0	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G8.59	Common Beech	-	S	240	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G8.60	Common Yew	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	20+	C1
G8.61	Highclere Holly	-	S	260	31	3.1	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G8.62*	Common Elder	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.63	English Elm	-	S	220	22	2.6	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.64*	Common Ash	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.65	Common Holly	-	S	160	12	1.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.66	Common Holly	-	S	160	-	-	-	-	Dead	-	-	None required at time of survey	N/A	U
G8.67	Common Holly	-	MS	140 150	19	2.5	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.68*	English Elm	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	10+	C1
G8.69	Common Holly	-	S	150	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.70	Holm Oak	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	20+	C1
G8.71*	Common Yew	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	20+	C1
G8.72	Griselinia littoralis	-	S	150	10	1.8	-	-	Young	-	-	None required at time of survey	20+	C1
G8.73	Common Holly	-	MS	310 330	93	5.4	-	-	Early Mature	-	-	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G8.74	Common Holly	-	S	200	18	2.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.75*	Sycamore	-	MS	90 70	6	1.4	-	-	Young	-	-	None required at time of survey	20+	C1
G8.76*	English Elm	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G8.77	Common Holly	-	S	190	16	2.3	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.78	Common Holly	-	S	210	20	2.5	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.79	English Elm	-	S	140	9	1.7	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.80	English Elm	-	S	150	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.81	Common Yew	-	S	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.82	English Elm	-	S	190	16	2.3	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.83	English Elm	-	S	180	15	2.2	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.84	Common Yew	-	S	260	31	3.1	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.85*	Common Ash	-	S	130	8	1.6	-	-	Young	-	-	None required at time of survey	20+	C1
G8.86	Common Ash	-	MS	190 170	29	3.1	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.87	Common Lime	-	S	140	9	1.7	-	-	Semi- mature	-	-	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m ²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G8.88	Common Holly	-	MS	200 200	36	3.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.89	English Elm	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G8.90	Sycamore	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	20+	C1
G8.91	English Elm	-	s	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.92	English Elm	-	s	150	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.93*	English Elm	-	s	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.94*	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.95*	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.96	Common Holly	-	s	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G8.97	Common Holly	-	s	120	7	1.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.98	Common Hornbeam	-	S	240	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G8.99	Common Ash	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	10+	C1
G8.100	Pedunculate Oak	-	s	90	4	1.1	-	-	Young	-	-	None required at time of survey	20+	C1
G8.101	Common Ash	-	s	100	5	1.2	-	-	Young	-	-	None required at time of survey	20+	C1
G8.102	Common Lime	-	MS x6	120	39	3.5	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G8.103	Common Holly	-	s	240	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
Grp 9	Sycamore Lime Oak Yew Holly Cherry Laurel Elder Ash Rhododendron Portugal Laurel Snowberry Hornbeam	12	S	300	41	3.6	N - E - S - W -	N - E - S - W -	Early Mature	Good	Structural Condition - Fair Crown shapes distorted due to group pressure Epicormics on trunks and in crowns Low hanging branches Major deadwood in crowns Old pruning wounds Trunk shapes distorted due to group pressure	None required at time of survey	20+	B1+2
G9.1	Common Lime	-	S	590	157	7.1	-	-	Early Mature	-	Basal suckers limit survey Historically lost top	-	-	C1+2
G9.2	Common Ash	-	S	460	96	5.5	-	-	Early Mature	-	Trunk and crown shape distorted Trifurcated at 5m	-	-	B1+2
G9.3	Common Yew	-	S	530	127	6.4	-	-	Early Mature	-	Bifurcated at 4m with tight fork Minor deadwood	-	-	B1+2
G9.4	Common Yew	-	S	390	69	4.7	-	-	Early Mature	-	-	-	-	C1+2
G9.5	Pedunculate Oak	-	S	960	417	11.5	-	-	Early Mature	-	Polyporous squimosus fungal fruiting body on trunk to west at 2m above ground level Topped at 9m Decay present in upper stem Lateral branches taking over apical dominance Habitat value	-	-	C1+2
G9.6	Common Beech	-	S	910	375	10.9	-	-	Mature	-	Trunk shape distorted Leans and weighted east	-	-	C1+2
G9.7	Pedunculate Oak	-	S	790	-	-	-	-	Dead	-	Dead tree Potential habitat	-	-	U
G9.8	Pedunculate Oak	-	S	360	59	4.3	-	-	Semi- mature	-	Trunk shape distorted due to group pressure Weighted south	-	-	C1+2

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G9.9	Pedunculate Oak	-	S	460	96	5.5	-	-	Early Mature	-	Bifurcated at 5m above ground level Weighted west	-	-	C1+2
G9.10	Pedunculate Oak	-	S	850	-	-	-	-	Dead	-	Dead tree	Advise removal	-	U
G9.11	Pedunculate Oak	-	S	850	327	10.2	-	-	Mature	-	Topped at 10m	-	-	C1+2
G9.12	Common Horse Chestnut	-	S	800	290	9.6	-	-	Mature	-	Exudate on trunk to south Minor deadwood	-	-	C1+2
G9.13	Sycamore	-	S	520	122	6.2	-	-	Early Mature	-	Cavity in south-east side of trunk at ground level Trunk shape distorted Historically lost top	-	-	C1+2
G9.14	Common Ash	-	S	370	-	-	-	-	Semi- mature	-	Cavity at base on east side Innonotus hispidus fungal fruiting body on floor at base of tree Bifurcated at 4m with cavity present	Advise removal	-	U
G9.15*	Common Lime	-	S	390	69	4.7	-	-	Semi- mature	-	Growing on bank of ice house Bird box on trunk Bifurcated at 4m	-	-	C1+2
G9.16	Sycamore	-	S	460	96	5.5	-	-	Early Mature	-	Ivy on trunk	-	-	C1+2
G9.17	Common Lime	-	S	1100	-	-	-	-	Mature	-	Previously topped Major decay in base	Advise removal	-	U
G9.18	Common Ash	-	-	-	-	-	-	-	-	-	Tree has been removed since original survey	-	-	-
G9.19	Common Holly	-	MS	160 170 180	39	3.5	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.20	Common Holly	-	MS	280 210	55	4.2	-	-	Semi- mature	-	-	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G9.21	Common Ash	-	S	370	62	4.4	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G9.22	Common Ash	-	S	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.23	Robinia	-	S	240	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.24	Common Holly	-	S	310	43	3.7	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G9.25	Common Holly	-	S	170	13	2.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.26	Robinia	-	S	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.27	Common Holly	-	MS	250 140	37	3.4	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G9.28	Common Hawthorn	-	MS	140 180 190	40	3.6	-	-	Early Mature	-	-	None required at time of survey	10+	C1
G9.29*	Common Holly	-	MS x6	60	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.30	Sycamore	-	S	130	8	1.6	-	-	Young	-	-	None required at time of survey	20+	C1
G9.31	Sycamore	-	MS	120 140	15	2.2	-	-	Young	-	-	None required at time of survey	10+	C1
G9.32	Common Lime	-	MS	160 120	18	2.4	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.33	Common Lime	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G9.34	Common Ash	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G9.35	Cherry Laurel	-	S	130	8	1.6	-	-	Semi- mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G9.36	Common Holly	-	MS	140 110	14	2.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.37	Common Holly	-	S	120	7	1.4	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.38	Common Holly	-	S	240	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.39	Common Yew	-	S	350	55	4.2	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.40	Common Holly	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	10+	C1
G9.41	Common Hornbeam	-	S	160	12	1.9	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.42	Common Yew	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	20+	C1
G9.43	Common Hawthorn	-	S	100	5	1.2	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.44	Common Yew	-	S	180	15	2.2	-	-	Young	-	-	None required at time of survey	20+	C1
G9.45	Common Ash	-	S	210	20	2.5	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.46	Common Yew	-	S	330	49	4.0	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.47	Common Holly	-	MS	70 80 100	10	1.8	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.48	Common Holly	-	S	160	12	1.9	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.49	Common Elder	-	MS	40 40 40 40	3	1.0	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.50	Common Ash	-	S	340	52	4.1	-	-	Semi- mature	-	-	None required at time of survey	10+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G9.51	Common Ash	-	MS	100 90	8	1.6	-	-	Young	-	-	None required at time of survey	10+	C1
G9.52	Common Holly	-	S	180	15	2.2	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.53	Common Ash	-	S	130	8	1.6	-	-	Young	-	-	None required at time of survey	20+	C1
G9.54	Common Holly	-	S	220	22	2.6	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.55	Sycamore	-	S	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.56	Pedunculate Oak	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	20+	C1
G9.57	Common Holly	-	MS	130 140	16	2.3	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.58	Common Lime	-	S	390	69	4.7	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G9.59	Common Hornbeam	-	S	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.60	Common Beech	-	s	370	62	4.4	-	-	Early Mature	-	-	None required at time of survey	20+	C1
G9.61	Common Yew	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	20+	C1
G9.62	Common Ash	-	s	250	28	3.0	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.63	Common Lime	-	s	190	16	2.3	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.64	Sycamore	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	С
G9.65	Common Ash	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G9.66	Sycamore	-	S	240	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G9.67	Common Lime	-	S	310	43	3.7	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.68	Common Ash	-	S	200	18	2.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.69*	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G9.70*	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G9.71*	Common Ash	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	10+	C1
G9.72	Common Ash	-	S	170	13	2.0	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.73	Common Hawthorn	-	MS	60 80	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G9.74	Common Hawthorn	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G9.75	Common Yew	-	S	310	43	3.7	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.76	Common Yew	-	S	320	46	3.8	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.77	Common Ash	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	20+	C1
G9.78	Common Ash	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	10+	C1
G9.79	Common Ash	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	10+	C1
G9.80	Common Ash	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	10+	C1
G9.81	Holm Oak	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	20+	C1
G9.82	Common Ash	-	S	270	33	3.2	-	-	Semi- mature	-	-	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G9.83	Common Horse Chestnut	-	S	160	12	1.9	-	-	Young	-	-	None required at time of survey	10+	C1
G9.84	Common Yew	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	20+	C1
G9.85	Common Yew	-	S	90	4	1.1	-	-	Young	-	-	None required at time of survey	20+	C1
G9.86	Common Yew	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	20+	C1
G9.87	Holm Oak	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	20+	C1
G9.88	Common Yew	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	20+	C1
G9.89	Common Yew	-	S	270	33	3.2	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.90	Sycamore	-	S	240	26	2.9	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.91	Holm Oak	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	20+	C1
G9.92	English Elm	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	10+	C1
G9.93	Common Yew	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	20+	C1
G9.94	English Elm	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G9.95	Sycamore	-	S	130	8	1.6	-	-	Young	-	-	None required at time of survey	20+	C1
G9.96	Common Ash	-	S	75	3	0.9	-	-	Young	-	-	None required at time of survey	10+	C1
G9.97	Common Yew	-	S	270	33	3.2	-	-	Young	-	-	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m ²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G9.98	Common Yew	-	S	270	33	3.2	-	-	Young	-	-	None required at time of survey	20+	C1
G9.99	English Elm	-	S	80	3	1.0	-	-	Young	-	-	None required at time of survey	10+	C1
G9.100	Common Yew	-	S	230	24	2.8	-	-	Young	-	-	None required at time of survey	20+	C1
G9.101	English Elm	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	10+	C1
G9.102	Duplicate tree	-	-	-	-	-	-	-	-	-	-	-	-	-
G9.103	Common Ash	-	S	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.104	Common Ash	-	S	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.105	Pedunculate Oak	-	S	170	13	2.0	-	-	Young	-	-	None required at time of survey	20+	C1
G9.106	Pedunculate Oak	-	S	260	31	3.1	-	-	Young	-	-	None required at time of survey	20+	C1
G9.107	Pedunculate Oak	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	20+	C1
G9.108	English Elm	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	10+	C1
G9.109	Pedunculate Oak	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	20+	C1
G9.110	Pedunculate Oak	-	S	130	8	1.6	-	-	Young	-	-	None required at time of survey	10+	C1
G9.111	Pedunculate Oak	-	S	330	49	4.0	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.112	Pedunculate Oak	-	S	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.113	Pedunculate Oak	-	s	280	35	3.4	-	-	Semi- mature	-	-	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi- Stemmed (S or MS)	Stem Diam (mm)	Root Protection Area (m²)	Root Protection Distance (m)	Branch Spread (m)	H't of Crown AGL (m)	Life Stage	Physio- logical Condition	Structural Condition and General Observations	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
G9.114	Sycamore	-	S	200	18	2.4	-	-	Young	-	-	None required at time of survey	20+	C1
G9.115	Common Yew	-	MS	130 120 140 130 130	38	3.5	-	-	Young	-	-	None required at time of survey	20+	C1
G9.116	Common Hawthorn	-	MS	60 60 60	5	1.2	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.117	Common Hawthorn	-	S	110	5	1.3	-	-	Semi- mature	-	-	None required at time of survey	10+	C1
G9.118	Pedunculate Oak	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	10+	C1
G9.119	Common Yew	-	MS	270 220	55	4.2	-	-	Young	-	-	None required at time of survey	20+	C1
G9.120	Common Yew	-	S	100	5	1.2	-	-	Young	-	-	None required at time of survey	20+	C1
G9.121	Sycamore	-	S	140	9	1.7	-	-	Young	-	-	None required at time of survey	20+	C1
G9.122	Sycamore	-	S	160	12	1.9	-	-	Young	-	-	None required at time of survey	10+	C1
G9.123	Sycamore	-	S	230	24	2.8	-	-	Semi- mature	-	-	None required at time of survey	20+	C1
G9.124	Sycamore	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	20+	C1
G9.125	Sycamore	-	S	120	7	1.4	-	-	Young	-	-	None required at time of survey	10+	C1
G9.126	Sycamore	-	S	110	5	1.3	-	-	Young	-	-	None required at time of survey	10+	C1
G9.127	Sycamore	-	s	140	9	1.7	-	-	Young	-	-	None required at time of survey	10+	C1
G9.128	Common Yew	-	s	80	3	1.0	-	-	Young	-	-	None required at time of survey	20+	C1