

tree:fabrik/ar/tf913/01

14th July 2017

Berkeley Homes (West London) Ltd FAO Mr H Sharma Latchmere House Latchmere Close Richmond TW10 5HH

Dear Hemant,

LATCHMERE HOUSE, RICHMOND SYCAMORE – T65

I refer to my recent site visit and subsequent inspection of the above tree due to identification of basal fungi.

The purpose of this letter is to provide an assessment of the tree following visual inspection and provide recommendations on management options.

Sycamore T65

The mature tree, approximately 17m in height, is located to the north of Latchmere Close and set approximately 1.5m from the kerbline. The tree is formed of a single trunk supporting a full crown of 8m radius.

Outwardly, the tree appears to be of fair health with minor upper crown die-back and occasional squirrel damage on lateral branches. However, on detailed inspection fungi is noted at the base of the tree between the buttress roots at the south east and northeast cardinal points. The fungi is identified as perfect stage **Kretzschmaria deusta**.

This fungi causes decay that compromises the structural integrity of the wood leading to brittle fracture. The importance of this fungi is that the tree displays no other indications prior to fracture.

A photographic record and location plan is attached for ease of reference.

Conclusion

The tree was previously assessed as 'U' category in accordance with BS 5837 (2012) Trees in relation to Design, Demolition and Construction as part of the original planning submission in 2014.

As such, the tree was assessed with less than 10 years life expectancy regardless of future

development.

The tree is located directly adjacent to an area of public activity and as such high target risk. This risk

will be increased by the introduction of a footway adjacent to Latchmere Close and completion of the

Latchmere House development.

The tree is located within a soft ground area with other mature trees in close proximity. The tree is not

therefore individually of visual amenity or prominent within the local or wider street scene.

Recommendation

Whilst the extent of decay and/or delignification of the wood cannot be accurately assessed, the

positive identification of the fungi and its characteristics indicate potential for failure. Given the

commencement of highway works and increased target risk, I recommend that the tree be felled to

ground level and the stump ground out at the earliest opportunity and within three months of this

letter.

Other Considerations

The tree is located within the Ham Conservation Area. However, given the trees condition and that

the site is subject to active development, written consent must be obtained from Richmond Borough

Council prior to removal in accordance with Planning Conditions. A replacement tree must be planted


in a similar position and I suggest that this be of comparative species ie. English Oak, Holm Oak or

Scots Pine and included within the proposed landscaping in mitigation.

Yours sincerely,

Alan Richardson

For and on behalf of tree:fabrik Limited



Sycamore T65



Sycamore T65 Detailed view of fungi Kretzschmaria deusta (southeast of trunk)



Sycamore T65 Detailed view of fungi Kretzschmaria deusta (northeast of trunk)

