## Floor Plan General Notes

**HAZARD** 

**Asbestos** 


Asbestos is present within this building

I. Limited area of floorvoid within FII was found to contain asbestos residue, this is be environmentally cleaned.

13. Remove the existing modern timber framed rooflight. Refer to Drawing 211.

DO NOT SCALE THIS DRAWING USE DIMENSIONS ONLY VERIFY ALL DIMENSIONS ON SITE BEFORE COMMENCING ANY WORK OR SHOP DRAWINGS INFORM THE ARCHITECT BEFORE ANY WORK STARTS IF THIS DRAWING EXCEEDS THE QUANTITIES IN ANY WAY

Date 8th May 2017 31st August 2017



RISK ASSESSMENT UNDERTAKEN	
PLANNING APPLICATION N° 1	
PLANNING APPLICATION N° 2	
PLANNING CONSENT	
LISTED BLDG APPLICATION	
LISTED BLDG CONSENT	
DAC APPROVAL	
BLDG CONTROL APPLICATION	
BLDG CONTROL APPROVAL	
TENDER DOCUMENT	
CONTRACT DOCUMENT	

English Heritage

Marble Hill House

First Floor Plan; as existing (showing demolition & stripout)

	October 2016	DRAWN HS
0 000000 2010	October 2016	HS

Clews architects

Acanthus House 57 Hightown Road Banbury • Oxfordshire OX16 9BE Tel: 01295 702600 Fax: 01295 702601 architects@acanthusclews.co.uk www.acanthusclews.co.uk