

11. Existing cementitious render including Architectural features, remove paint where it has failed to

14. Repoint open crack between the western wing wall and nib wall with lime mortar refer to

drawing for crack details

allow the existing 'alkyd resin' masonry paint to be overpainted with new masonry paint. Prepare surface by rubbing back loose paint, filling any cracks with natural hydraulic lime mortar. Paint colour to match existing; British Standard BS 4800 '00 E 55 White'.

17. Replace the lower portion of door; this will include the bottom rail and the lower 400 mm of the

- 19. Rear of wing walls, these are pointed in a cement mortar, where cement is failed or loose remove cement pointing and repoint wall with lime putty mortar.
- 21. Repoint masonry plinth course and other Architectural features with lime putty mortar. Note percentages where provided.
- 23. Fully repaint all doors as indicated by hatch.

DO NOT SCALE THIS DRAWING USE DIMENSIONS ONLY VERIFY ALL DIMENSIONS ON SITE BEFORE COMMENCING ANY WORK OR SHOP DRAWINGS INFORM THE ARCHITECT BEFORE ANY WORK STARTS IF THIS DRAWING EXCEEDS THE QUANTITIES IN ANY WAY

Revision	Date	Description
A	11th January 2017	Notes 3 & 11 changed & 14, 15, 16 & 17 added.
В	11th May 2017	All notes amended
С	4th September 2017	Notes amended for planning submission

DRAWING ISSUE STATUS	REVISION N°	DATE	SIGNE
RISK ASSESSMENT UNDERTAKE	EN		
PLANNING APPLICATION N° 1			
PLANNING APPLICATION N° 2			
PLANNING CONSENT			
LISTED BLDG APPLICATION			
LISTED BLDG CONSENT			
DAC APPROVAL			
BLDG CONTROLAPPLICATION			
BLDG CONTROLAPPROVAL			
TENDER DOCUMENT			
CONTRACT DOCUMENT			

CLIENT English Heritage

PROJECT

Marble Hill House

TITLE

Main House: Elevation of Wing Walls; repairs

16 132

JOB N°	DRAWING N°
December 2016	HS
DATE	DRAWN
I:100 @ A3	
SCALE	

Acanthus House 57 Hightown Road Banbury • Oxfordshire OX16 9BE

Clews

architects