



CCTV KEY

ABBREVIATIONS

B	Seew broken at this point	NCA	No camera access
BU	Broken joint	NA	Not a manhole
CC	Cumulative crack	OJ	Open joint medium
CCU	Cumulative crack on joint	OR	Obstruction (internal pipe or cable)
CP	Cast in place repair	ORC	General obstruction at the point with explanation
CPR	Crack in place repair	RFZ	Roots thru pipe
CM	Multiple cracks	RM	Root mass at joint
CM	Crack multiple on joint	RE	Reading eye
CM	Crack	RT	Root tie
CO	Loss of cover (off)	SW	Surface Water
CO	Loss of cover (under water)	SA	Survey Abandoned
CO	Crack	UTL	Unable to locate
CO	Crack	UTR	Unable to trace
CO	Crack	UTS	Unable to survey
CO	Crack	WLC	Water level
CO	Crack	XP	Collapse to pipe
DC	Diameter of pipe changes		
DEC	Sealed inspection hole or compressed		
DEE	Excavation scale light		
DEE	Excavation light at joint		
DEF	Defect findings		
DES	Defect notes		
DES	Defect list		
DEX	Distorted deposits		
DEZ	One structure deposits		
FC	Fracture circumferential		
FCJ	Fracture circumferential at joint		
FL	Fracture longitudinal		
FM	Fracture multiple		
FW	Food waste		
GA	Gas at joint		
H	High		
HU	High at joint		
HPH	High pressure water piping		
IS	Infiltration running		
IS	Infiltration weeping		
J	Joint inspection medium		
JN	Joint		
JND	Joint detection		
LD	Line down		
LL	Line left		
LR	Line right		
LU	Line up		

DISCLAIMER

Whilst every effort has been taken in the preparation of this drawing, the original land marks/appearance configuration may have been altered since the survey/drawing was produced. The user shall make further enquiries and investigations to verify himself as to the accuracy of this drawing and position of the apparatus. The exact positions of the apparatus should be verified by the use of suitable detecting devices and safe digging practices in accordance with HSG47. Further advice on the location of apparatus should be recommended by the owner. No representation is made by Greenhatch Group, its agents or servants as to the accuracy, completeness, or sufficiency or otherwise of this drawing and the position of the apparatus. All apparatus shall be treated as live unless proved otherwise by the owner. It is the users responsibility to ensure that the information on this drawing or otherwise is provided to all persons (either direct labour or contractors) working in proximity to the apparatus.

Rev	Date	Description	Drawn	IC Ref.



Rowan House
Duffield Road
Little Eaton
Derby
DE21 5DR
Tel (01332) 830044 Fax (01332) 830055
admin@greenhatch-group.co.uk
www.greenhatch-group.co.uk

St Albans Unit 8, The Courtyard Alban Park Hertsfordshire AL4 0UA T: (01272) 954881	Newcastle 24 Riverside Studios Newcastle Bus Park Newcastle Upon Tyne NE4 7YL T: (01912) 736391	Poland ul. Piłsudskiego 91 40-763 Katowice Poland NE4 7YL T: (01912) 736391 www.greenhatch.pl
----------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------

CLIENT
Pick Everard

PROJECT
Thames Young Mariners
Richmond

TITLE
CCTV
Survey

SCALE A1@ 1: 250	DATE 08/07/2022
DRAWN AB	QUALITY REF SB

Level datum	Drawing supplied by client
Grid orientation	Drawing supplied by client

Job number	43456
Drawing No.	43456 CCTV
Rev.	0

Comments
This plan should only be used for its original purpose. Greenhatch Group accepts no responsibility for this plan if supplied to any party other than the original client.
All dimensions should be checked on site prior to design and construction.
Drainage information (where applicable) has been visually inspected from the surface and therefore should be treated as approximate only.

