


RUSTON & WARD

ELEVATION 5 - EXISTING





Outline of Brick Chimney (In background)

01 WT-13

RUSTON & WARD

ELEVATION 1 - EXISTING

SCALE 1:200

WT-24

02 WT-13

WT-24

畢


03 WT-13


Render


SCALE 1:25 TYPE 22 (WT-22)


SCALE 1:25 TYPE 23 (WT-23)

W 04 WT-14













SCALE 1:25 TYPE 14 (WT-14)




SCALE 1:25 TYPE 13 (WT-13)










scale 1:25 TYPE 15 (WT-15)















ELEVATION 3 - EXISTING

靈


ELEVATION 7 - EXISTING








SCALE 1:25

770











SCALE 1:25 TYPE 05 (WT-05)








scale 1:25 TYPE 18 (WT-18)


SCALE 1:25 TYPE 19 (WT-19)



USE OF DRAWINGS

DO NOT SCALE FROM THIS DRAWING. USE WRITTEN DIMENSIONS AND CHECK ON SITE. THIS DRAWING IS BASED ON SITE INFORMATION SUPPLIED BY THIRD PARTIES AND ACCURACY OF EXISTING FEATURES IS NOT GUARANTEED. ANY ERROR, OMISSION OR DISCREPANCY NOTED ON OR BETWEEN DRAWINGS AND OTHER DOCUMENTS MUST BE REPORTED IN WRITING IMMEDIATELY. ALL MECHANICAL, ELECTRICAL AND STRUCTURAL LAYOUTS / COMPONENTS ARE INDICATIVE AND MUST BE DESIGNED AND CHECKED BY SPECIALISTS. DO NOT START WORK ON SITE BEFORE CONFIRMING THAT ALL NECESSARY STATUTORY AND OTHER CONSENTS HAVE BEEN OBTAINED. THIS DRAWING IS COPYRIGHT AND MUST NOT BE DISTRIBUTED WITHOUT PERMISSION. ELECTRONIC CAD FILES MUST NOT BE ALTERED OR COPIED

REVISIONS			Op CHE	Op CHE	
REV	DATE	DESCRIPTION	ORSUN CA	\$	
-	02.09.2022	INITIAL ISSUE	OC	JF	
А	26.05.2023	HISTORIC ENGLAND FOR COMMENT	JF	JF	



SCALE 1:25 TYPE 20 (WT-20)

LAND SURVEYORS WINDOW & DOOR CONDITION LEGEND CODE REF. CONDITION REQUIRED ACTION Minimal defects, preventative maintenance, GOOD little/no work required GOOD Minor deterioration, condition based naintenance and repair in-situ possible. Fair deterioration, material function impaire epair in-situ possible or offsite unit repairs POOR Critical deterioration over a large portion o components, part replacement required RGEN Extreme failure has occurred throughout, replacement replicated to match.

SURVEY INFORMATION BY M.J. REES AND COMPANY LID, CHARTERED

NOTE:


NOTE:

THIS DOCUMENT IS TO BE READ IN CONJUNCTION WITH THE FOLLOWING CONDITION SURVEY PHOTO RECORD 1685-A-606 RUSTON & WARD WINDOW PHOTO RECORD

intervention proposed

No restoration works required as new





WATERFALL PLANNING LTD

project HAMPTON WATERWORKS

drawing title EXISTING WINDOW TYPES **RUSTON & WARD**

sheet size A1 status

20

Scale 1:200

1:200 & 1:25 @ A1 PRELIMINARY

scale

drawing no.



1685-A-P049 LOM architecture and design

The Glass House 5 Sclater Street London E1 6JY UK **Phone** +44(0)20 8444 2999 **Email** mail@lom-fdp.com **Web** www.lom-architecture.com