



RIDGE

ST MARY'S UNIVERSITY R BUILDING

SUSTAINABLE DRAINAGE STRATEGY

OCTOBER 2024



St Mary's
University
Twickenham
London

SUSTAINABLE DRAINAGE STRATEGY REPORT

STMA-RDG-XX-XX-T-C-300001

Prepared for

St Mary's University Twickenham
Strawberry Hill Campus
Waldegrave Road
Strawberry Hill
TW1 4SX

Prepared by

Ridge and Partners LLP
3 Valentine Place
London
SE1 8QH

Tel: +44 (0) 207 593 3400

Contact

Tom Wong MEng
Civil Engineer
Email: tomwong@ridge.co.uk
Mob: +44 (0) 7825 905 089

Paul Chance CEng MICE
Senior Associate (Civil Engineering)
Email: paulchance@ridge.co.uk
Mob: +44 (0) 7425 411 592

VERSION CONTROL

| VERSION | DATE | DESCRIPTION | CREATED BY | REVIEWED BY |
|---------|------------|---------------------|------------|-------------|
| P01 | 30/10/2024 | Issued for Planning | TW | PCh |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

CONTENTS

| | |
|--|-----------|
| 1. INTRODUCTION | 6 |
| 2. EXISTING SITE | 6 |
| 2.1. Site Location and existing development | 6 |
| 2.2. Existing Development | 7 |
| 2.3. Land use and Topography | 8 |
| 2.4. Hydrology | 8 |
| 2.5. Geological Records | 9 |
| 2.6. Ground Investigation | 10 |
| 2.7. Infiltration Testing | 10 |
| 2.8. Hydrogeology | 10 |
| 2.9. Flood Risk Review | 11 |
| 2.9.1. Flooding from Rivers or the Sea (Fluvial / Tidal) | 11 |
| 2.9.2. Surface Water (Pluvial) Flood Risk | 11 |
| 2.9.3. Flooding from Artificial Sources | 12 |
| 2.9.4. Flooding from Groundwater | 12 |
| 3. DEVELOPMENT PROPOSALS | 12 |
| 4. EXISTING DRAINAGE | 13 |
| 4.1. Thames Water Sewers | 13 |
| 4.2. Existing Private Drainage | 13 |
| 4.3. Existing Surface Water Discharge Rate | 14 |
| 5. PROPOSED DRAINAGE STRATEGY | 14 |
| 5.1. Proposed Drained Areas | 14 |
| 5.2. Surface Water Drainage Strategy | 15 |
| 5.2.1. Sustainable Drainage Hierarchy | 15 |
| 5.2.2. Green / Blue Roods | 16 |
| 5.2.3. Rainwater Re-use | 17 |
| 5.2.4. Permeable Surfaces | 17 |
| 5.2.5. Infiltration Devices | 17 |
| 5.2.6. Basins and Ponds | 18 |
| 5.2.7. Filter Strips and Swales | 18 |
| 5.2.8. Tanked Systems | 18 |
| 6. POLLUTION MANAGEMENT | 18 |
| 7. PROTECTION OF DRAINAGE DURING CONSTRUCTION | 20 |
| 7.1. General | 20 |
| 8. MAINTENANCE PLAN | 20 |
| 8.1. Responsibilities | 20 |
| 8.2. Health and Safety | 20 |
| 8.3. Operation and Maintenance Plan | 21 |
| 8.3.1. Construction Phase | 21 |
| 8.4. Operational Phase | 21 |
| 8.4.1. Soakaways | 23 |

| | | |
|------------|---|-----------|
| 8.4.2. | Permeable Paving | 23 |
| 8.4.3. | Green Roofs | 24 |
| 8.4.4. | Silt Traps and Catchpits | 25 |
| 8.4.5. | Gullies / Linear Drainage Channels | 26 |
| 8.4.6. | Drainage pipes, manholes and silt traps | 26 |
| 9. | EXCEEDANCE ROUTES | 26 |
| 10. | APPENDICES | 27 |

1. INTRODUCTION

Ridge and Partners LLP have been commissioned by St Mary's University to prepare a Sustainable Drainage Strategy Report in support of a planning application for the redevelopment of the Centenary R Block Building.

The scope of this report is to review data in relation to the existing drainage regime and consider the suitability of sustainable drainage (SuDS) for the disposal of surface water runoff.

This report has been carried out in accordance with the National Planning Policy Framework (NPPF), The London Borough of Richmond SuDS Guidance Document, The London Plan and the DEFRA Non-technical Standards for SuDS.

2. EXISTING SITE

2.1. Site Location and existing development

Site Name: St Mary's University, R Building

Site Address: St Mary's University, Waldegrave Road, Strawberry Hill, Twickenham, TW1 4SX

Site Location: Easting: 515859, Northing: 171946

National Grid Reference: TQ158719

Site Planning Boundary: Approx. 0.146 ha

The site is located to the east of Waldegrave Road, to the north of Waldegrave Park towards the southern end of the university campus.

The university campus consists of a numerous teaching blocks and sports pitches with the proposed site of the replacement teaching building as highlighted in red within Figure 1.



Figure 1 - Site Location Plan (Imagery ©2024 Airbus, Maxar Technologies, Map data ©2024)

2.2. Existing Development

The existing site consists of an existing two storey teaching block, which is no longer considered fit for purpose or in keeping within the growth aspirations of the university.

The existing teaching block building is shown in Figure 2 and Figure 3.



Figure 2 – GA plan of the Existing teaching block



Figure 3 – Photo of the existing teaching block to be redeveloped

2.3. Land use and Topography

A topographical survey was undertaken by Greenhatch Group on 16/12/2016. The survey shows the site to vary in levels generally between approximately 8.10m AOD and 11.04m AOD

A copy of the topographic survey can be found in **Appendix A**.

2.4. Hydrology

The site is located within the Colne GW Operational Catchment area as shown in Figure 4.




Figure 4 - Water bodies operational catchment plan.

The nearest watercourses are the Lower Duke of Northumberland's and the Crane rivers. Both situated approximately 3 to 4km north-west of the site - their locations are indicated in Figure 5.




Figure 5 - Watercourses relative to site location

A utility survey was also undertaken by Greenhatch group and a CCTV survey of the existing below ground drainage was undertaken by G.O. Drainage Services Ltd on 16th July 2024 which show surface water for the site drains to private manhole soakaways close to the building.

An extract of the utility survey and CCTV drainage survey can be found in **Appendix A**.

2.5. Geological Records

Reference to the British Geological Survey (BGS) online mapping shows the site is likely to be underlain by a bedrock of London Clay Formation. Superficial geology is comprised of Kempton Park Gravel Member which consists of sand and gravel, locally with lenses of silt, clay or peat. The BGS bedrock and superficial geology records pertaining to the site are illustrated in Figure 6 and Figure 7.



Figure 6 – BGS Bedrock geology Extract




Figure 7 – BGS Superficial deposits extract

There are no historic borehole records available for the site, however the nearest borehole is mapped to be circa 400m east of the site situated along the A310, next to the River Thames. The borehole, referenced TQ17SE129, was drilled to 9m bgl and showed circa 2.8m of made ground overlying clay, overlying Kempton Park gravel to 8m bgl overlying London Clay.

2.6. Ground Investigation

A ground investigation was conducted by Paddock Geo Engineering Limited dated September 2024. The findings are within the ground investigation report P24-234 - Strawberry Hill Campus, St Mary's University, Waldegrave Road, Strawberry Hill, Twickenham, TW1 4SX, which is included in **Appendix B**.

The investigation works showed the ground to be:

- Topsoil: 0.15mbgl to 0.30mbgl
- Made ground: 0.20-0.70mbgl
- Kempton Park Gravel Formation: 0.10-3.00mbgl (the extents of the trial pit samples)
- No tree roots were present in any of the test locations
- No groundwater was encountered in any of the test locations

2.7. Infiltration Testing

Infiltration testing was conducted following the principles of BRE 365 Soakaway Design (2016) in two locations at depths around 1m and 1.75m

The results of the soakage tests gave an estimated infiltration rate of 5.6×10^{-6} m/s, however additional testing will be required to verify the infiltration rate. The ground investigation report confirmed the level of permeability to be adequate and therefore suitable for use of infiltration.

The results of the infiltration tests can be found in **Appendix B**.

2.8. Hydrogeology

The groundwater vulnerability maps for the site and the surrounding areas indicates that the underlying superficial deposits represent a Principal aquifer. These are aquifers that provide significant quantities of drinking water, and water for business needs. They may also support rivers, lakes and wetlands.

The underlying London Clay bedrock strata is designated as an Unproductive Strata. Unproductive strata are largely unable to provide usable water supplies and are unlikely to have surface water and wetland ecosystems dependent on them.

The site is not situated within a Groundwater Source Protection Zone (SPZ), and none are mapped within 1km of the site.

Given the hydrogeological status of the site, the groundwater in the Kempton Park Gravel Member Deposits could be considered to be of moderate sensitivity.

2.9. Flood Risk Review

2.9.1. Flooding from Rivers or the Sea (Fluvial / Tidal)

The Environment Agency (EA) Flood Map for Planning (extract provided below in Figure 8) indicates the site is located within Flood Zone 1 (Very Low risk of fluvial flooding). Very Low fluvial flood risk is a probability of less than 1 in 1000 year, or an annual probability of less than 0.1%. Given the fluvial flood mapping, the site is not considered to be at risk of fluvial flooding




Figure 8 – Extract of Flood Map for Planning

2.9.2. Surface Water (Pluvial) Flood Risk

Surface water flooding may occur during intense or prolonged rainfall events where there is insufficient capacity within the drainage infrastructure, or saturated ground which leads to overland flows. The GOV.UK Surface Water Flood Risk Maps shows the development boundary is low or very low risk of surface water flooding – refer to Figure 9 .




Figure 9 – Extract of Surface Water Flood Map for Planning

2.9.3. Flooding from Artificial Sources

The site is not located within an area which is expected to be affected by reservoir flooding and there are no canals or other blue infrastructure which pose a flood risk in the vicinity of the site.

2.9.4. Flooding from Groundwater

Following review of the UK.gov website for long term flood risk, the site is considered to be in an area which is unlikely to experience flooding from groundwater.

3. DEVELOPMENT PROPOSALS

The proposed development consists of the demolition of existing R Block and the erection of a replacement teaching block (Use Class F1) comprising 1419m² of floorspace to provide facilities appropriate for the operation of a new School of Medicine at the Strawberry Hill Campus, with associated landscaping.

The planning boundary for the application is approximately 0.146Ha.

An extract of the proposed site plan is shown in Figure 10, for full drawings refer to the architect and landscape architect drawings submitted with the planning application.




Figure 10 - Extract of Site Plan

4. EXISTING DRAINAGE

4.1. Thames Water Sewers

Thames Water sewer records have been obtained and they show sewers within the local area is separated foul and surface water.

Sewers can be found within the roads to the east, west, south of the site summarised as follows:

- Within Clive Road to the east and Waldegrave Park Road to the south are 225mm \varnothing foul and surface water sewers that run from west to east.
- Within Waldegrave Road to the west are 225mm \varnothing foul and surface water sewers that run south to north.

An extract of the Thames Water records is presented in Figure 11 and full copy can be found in **Appendix C**.



Figure 11 - Extract of Thames sewer records

4.2. Existing Private Drainage

According to the CCTV drainage survey and utilities plan, there are existing foul and surface water private drains serving the existing teaching block.

The foul water drainage for the existing teaching block drains to the south via 100mm \varnothing and 150mm \varnothing pipes, which it is understood connects onto the foul sewer in Waldegrave Park. Surface water from the existing building is collected below ground and discharges via a series of soakaways which are located close to the perimeter of the existing building.

Refer to **Appendix A** for a copy of the below ground drainage survey.

4.3. Existing Surface Water Discharge Rate

An assessment of the existing impermeable areas has been undertaken – refer to **Appendix D**.

The existing site drains to via infiltration through a series of soakaways, there is no positive drainage connection from the existing building to the offsite surface water sewers.

Table 1 – Existing Building Area Breakdown

| AREA | M ² | HECTARES (HA) | % OF SITE |
|---------------------------|----------------|---------------|-----------|
| Roof Area | 1100 | 0.1100 | 75 |
| Existing drains to ground | 360 | 0.0036 | 25 |
| Total | 1460 | 0.1460 | 100 |

Greenfield runoff rates have also been calculated in line with the SuDS Manual C753 and the non-statutory standards for SuDS using the IH124 approach. The results are shown in Table 2 with calculations found in **Appendix E**.

Table 2 - Greenfield Runoff Rate HR Wallingford – Greenfield runoff tool) using an area of 1100m²

| STORM RETURN PERIOD | L/S |
|---------------------|------|
| Qbar | 0.20 |
| 1yr | 0.10 |
| 30yr | 0.40 |
| 100yr | 0.50 |

5. PROPOSED DRAINAGE STRATEGY

5.1. Proposed Drained Areas

An assessment of the proposed areas has been undertaken as shown in Table 3

Table 3 - Proposed Area Breakdown

| AREA | M ² | HECTARES | % OF SITE |
|--------------------------------|----------------|----------|-----------|
| Proposed Roof (other) | 434 | 0.0434 | 30 |
| Proposed Green Roof | 385 | 0.0385 | 26 |
| Proposed Externals (to ground) | 641 | 0.0641 | 44 |
| Total | 1460 | 0.1460 | 100 |

5.2. Surface Water Drainage Strategy

The proposed surface water scheme consists of the inclusion of a green roof which is connected below ground into a geocellular soakaway, located within the sports pitch to the north of the building. New external areas are proposed to be constructed with permeable materials allowing water to locally drain into the ground.

Further details on the proposed SuDS are outlined in the following sections of the report. A copy of the proposed drained area take-off drawing can be found in **Appendix D**. The proposed surface water general arrangement can be found in **Appendix F** and the proposed surface water calculations can be found in **Appendix G**.

5.2.1. Sustainable Drainage Hierarchy

The inclusion of Sustainable Drainage (SuDS) has been considered for the management of surface water for this development, in line with the following:

1. Rainwater harvesting
2. Infiltration techniques and green roofs
3. Rainwater attenuation in open water features for gradual release
4. Rainwater discharge direct to a watercourse (unless not appropriate)
5. Rainwater attenuation above ground (including blue roofs)
6. Rainwater attenuation below ground
7. Rainwater discharge to a surface water sewer or drain.
8. Rainwater discharge to a combined sewer.

Table 4 – SuDS Evaluation

| SUDS | VIABLE | COMMENT |
|-----------------------------|----------|---|
| Green / blue roof | Y | A green roof is proposed covering as much as possible of the new teaching block – refer to Architects information for details. |
| Rainwater reuse | N | It is not proposed to incorporate rainwater harvesting within the building. |
| Permeable surfaces | Y | Where any new external paving is proposed, this is of permeable construction design to infiltrate into the ground. |
| Infiltration Devices | Y | A geocellular soakaway is proposed to infiltrate rainwater from the new roof to ground. A small lower section of roof to the rear of the building is to discharge via an existing soakaway as root protection zones prevent connection to the new soakaway at the front of the building. |
| Basins and ponds | N | Due to insufficient space basins and ponds are not proposed. |
| Filters strips and swales | N | Due to insufficient space and preference given to SuDS, filter strips and swales are not proposed. |
| Tanked System | N | Below ground attenuation tanks are not proposed as part of the drainage scheme. |

5.2.2. Green / Blue Roofs

Green roofs consist of a multi-layered system that cover roofs and podiums on buildings. Typically, there is drainage layer below a growing medium. Green roofs intercept and hold rainwater, reducing the volume of runoff and restricting the peak rate of discharge for the short durations and lower intensity rainfall. Blue roofs have similar functionality but do not typically have vegetation and instead consist of a geo-composite system which stores water and restricts flow via restrictor chamber.




Figure 12 – Green roof four pillar of sustainability assessment

Performance (based on Ciria SuDS Manual)

Peak flow reduction: Medium/Good

Volume reduction: Medium

Water quality treatment: Good

Amenity potential: Good

Ecological potential: Good

It is proposed to incorporate a green roof over as much of the roof area as possible. The green roof is proposed to be a Bauder Biodiverse system with 150mm substrate. (Refer to the architects’ drawings for details).

5.2.3. Rainwater Re-use

Rainwater harvesting systems (RWH) have been considered, however are not being proposed for the building. The inclusion of a RWH system would be extremely complex and would offer limited benefits due to the limited water usage within the building.

The treatment systems for a RWH system typically involve filters and possibly UV and these have high embodied energy and can perform poorly in terms of their Life Cycle Analysis. In addition, the quoted lifespan for many rainwater harvesting systems is approximately 10 years after which they may require significant repairs or will result in an inefficient system.

We therefore consider it to be more sustainable to use less water through water efficient appliances.

5.2.4. Permeable Surfaces

New surfaces external to the building are limited, however where they are provided it is proposed that they will be of permeable construction including permeable block pavers or resin bound gravel.



Figure 13 – Permeable surfaces four pillar of sustainability assessment

Performance (based on Ciria SuDS Manual)

- Peak flow reduction: Good
- Volume reduction: Good
- Water quality treatment: Good
- Amenity potential: Poor
- Ecological potential: Poor

5.2.5. Infiltration Devices

Based on the ground investigation and infiltration testing, infiltration devices are viable. It is proposed to drain surface water for the new building roof to a new geocellular soakaway located beneath the sports pitch to the north of the building. The soakaway has been sized based on the initial infiltration testing result with an infiltration rate of 5.6×10^{-6} m/s for all rainfall events up to an including the 100yr +40%cc event.

Infodrainage calculations can be found in **Appendix G**.

There is a lowered section of the proposed roof (circa 56m²) which is to accommodate plant towards the rear of the building. It is not possible to drain this portion of roof to the north (due to tree root protection zones), as such it is proposed to re-use a section of existing surface water drainage which discharges to the southwest via an existing soakaway.




Figure 14 – Infiltration devices four pillar of sustainability assessment

5.2.6. Basins and Ponds

Due to the spatial configuration on site the use of retention/detention basins and/or ponds is not possible and therefore has not been included as part of the drainage strategy.

5.2.7. Filter Strips and Swales

Due to the spatial configuration on site the use of filter strips and swales is not considered suitable and therefore has not been included as part of the drainage strategy.

5.2.8. Tanked Systems

Tanks are not proposed as part of the drainage scheme as other SuDS are being provided.

6. POLLUTION MANAGEMENT

The development has been assessed in line with Table 26.2 of the SuDS Manual for the pollution hazard indices for different land use classifications – refer to Figure 15.

The roof area is considered to have a “low” pollution hazard, generating 0.3 total suspended solids, 0.2 metals and 0.05 hydrocarbons. The existing development currently has a single SuDS feature installed, represented as soakaway manholes.

The external footpaths are non-vehicle accessible, therefore the pollution hazard index is also considered to be low.

Table 26.4 of C753 shown in Figure 16 sets out the mitigation indices provided by SuDS features for discharge to groundwater.

TABLE 26.2 Pollution hazard indices for different land use classifications

| Land use | Pollution hazard level | Total suspended solids (TSS) | Metals | Hydrocarbons |
|--|------------------------|------------------------------|--|------------------|
| Residential roofs | Very low | 0.2 | 0.2 | 0.05 |
| Other roofs (typically commercial/ industrial roofs) | Low | 0.3 | 0.2 (up to 0.8 where there is potential for metals to leach from the roof) | 0.05 |
| Individual property driveways, residential car parks, low traffic roads (eg cul de sacs, homezones and general access roads) and non-residential car parking with infrequent change (eg schools, offices) ie < 300 traffic movements/day | Low | 0.5 | 0.4 | 0.4 |
| Commercial yard and delivery areas, non-residential car parking with frequent change (eg hospitals, retail), all roads except low traffic roads and trunk roads/motorways ¹ | Medium | 0.7 | 0.6 | 0.7 |
| Sites with heavy pollution (eg haulage yards, lorry parks, highly frequented lorry approaches to industrial estates, waste sites), sites where chemicals and fuels (other than domestic fuel oil) are to be delivered, handled, stored, used or manufactured; industrial sites; trunk roads and motorways ¹ | High | 0.8 ² | 0.8 ² | 0.9 ² |

Figure 15 - Extract of Table 26.2 from the SuDS Manual

TABLE 26.4 Indicative SuDS mitigation indices for discharges to groundwater

| Characteristics of the material overlying the proposed infiltration surface, through which the runoff percolates ¹ | TSS | Metals | Hydrocarbons |
|---|---|--------|--------------|
| A layer of dense vegetation underlain by a soil with good contaminant attenuation potential ² of at least 300 mm in depth ³ | 0.6 ⁴ | 0.5 | 0.6 |
| A soil with good contaminant attenuation potential ² of at least 300 mm in depth ³ | 0.4 ⁴ | 0.3 | 0.3 |
| Infiltration trench (where a suitable depth of filtration material is included that provides treatment, ie graded gravel with sufficient smaller particles but not single size coarse aggregate such as 20 mm gravel) underlain by a soil with good contaminant attenuation potential ² of at least 300 mm in depth ³ | 0.4 ⁴ | 0.4 | 0.4 |
| Constructed permeable pavement (where a suitable filtration layer is included that provides treatment, and including a geotextile at the base separating the foundation from the subgrade) underlain by a soil with good contaminant attenuation potential ² of at least 300 mm in depth ³ | 0.7 | 0.6 | 0.7 |
| Bioretention underlain by a soil with good contaminant attenuation potential ² of at least 300 mm in depth ³ | 0.8 ⁴ | 0.8 | 0.8 |
| Proprietary treatment systems ^{5, 6} | These must demonstrate that they can address each of the contaminant types to acceptable levels for inflow concentrations relevant to the contributing drainage area. | | |

Figure 16 - SuDs Mitigation Methods

The proposed drainage scheme incorporates a green roof where possible prior to discharge into a soakaway, with the new external areas are proposed to be permeable paving. The proposed solutions provide mitigation indices which exceed the pollution hazard indices, therefore are considered to be suitable.

7. PROTECTION OF DRAINAGE DURING CONSTRUCTION

7.1. General

Appropriate measures will be taken to protect the surface water drainage system during construction and the surface water runoff. These measures will be developed by the contractor, but we would expect to include:

- All foul water and surface water drains downstream of the site works as well as the relevant water authority will be identified;
- Underground services will be investigated and identified to avoid damage to them;
- All containers and tanks will have clear notices of their contents and how to handle them;
- Stockpiled material will be protected to reduce rainwater infiltration.
- In the event of a spillage causing pollution to water (i.e., discharged into drains) or land, the source will be contained, and the Environment Agency will be notified.
- All works should be in constructed in accordance with Best Practice, British Standards and CIRIA documents C753 and C768.

8. MAINTENANCE PLAN

All below ground drainage systems require regular maintenance to ensure they operate correctly. The drainage networks should be regularly inspected for blockages and cleared of unwanted debris/silt which will ensure performance and decrease the likelihood of future repairs.

This schedule details the following:

- Maintenance requirements and a suggested maintenance record.
- Explanation of the consequences of not carrying out the maintenance that is specified.
- Identification of areas where certain activities are prohibited (for example stockpiling materials on pervious surfaces).
- An action plan for dealing with accidental spillages

8.1. Responsibilities

During the construction phase of the development, the contractor is responsible for protecting the drainage system and undertaking any maintenance as needed.

Post construction, St Mary's University has responsibility for ensuring the below ground drainage system is maintained.

Any new drainage associated with the development will remain within private ownership.

8.2. Health and Safety

To comply with the Construction (Design and Management) Regulations (CDM) 2015, designers must assess all foreseeable risks during construction and maintenance and the designer must minimise them by the following (in order of preference):

1. Avoid.
2. Reduce.
3. Identify and mitigate residual risks.

8.3. Operation and Maintenance Plan

8.3.1. Construction Phase

Appropriate measures shall be taken to protect the surface water drainage system during construction and surface water runoff. These measures shall be developed by the contractor, but as a minimum shall include:

- All foul water and surface water drains downstream of the site works as well as the relevant water authority will be identified.
- Underground services will be investigated and identified to avoid damage to them.
- All containers and tanks will have clear notices of their contents and how to handle them.
- Stockpiled material will be protected to reduce rainwater infiltration.
- Materials shall not be stockpiled over permeable paving unless a suitable temporary membrane is provided to ensure materials do not block voids in the paving construction.
- In the event of a spillage, Health and safety consideration are a priority and addressing accidental spillages should only be attempted if the nature of the spillage is known and any potential hazardous properties understood. The source of the spillage should be stopped, with excess surface spillage removed by suction tank or absorption mats. Silt traps and sumps should be emptied by suction tanker. Any areas of affected permeable paving should have the surface and laying course removed with the surfacing blocks cleaned and re-laid on new bedding material. Heavy pollution of the subbase will require removal and replacement of the sub-base.
- Heavy loads shall not be permitted in areas where cellular storage crates are located.
- All works should be in constructed in accordance with Best Practice, British Standards and CIRIA documents C753 and C768.

8.4. Operational Phase

There are four categories for maintenance activities:

1. Regular maintenance.
2. Occasional maintenance.
3. Remedial maintenance.
4. Monitoring

Regular maintenance consists of basic tasks done on a frequent schedule, including vegetation management, litter and debris removal, and inspections.

Occasional maintenance comprises tasks that are likely to be required periodically, but on a less frequent basis than the regular tasks (e.g. sediment removal or filter replacement).

Remedial maintenance describes the intermittent tasks that may be required to rectify faults associated with the system, although the likelihood of faults can be minimised by good design, construction and regular maintenance activities. Where remedial work is found to be necessary, it is likely to be due to site-specific characteristics or unforeseen events, and so timings are difficult to predict. Remedial maintenance can comprise activities such as:

- inlet/outlet repairs
- erosion repairs
- reinstatement or realignment of edgings, barriers, rip-rap or other erosion control
- infiltration surface rehabilitation
- replacement of blocked filter fabrics

- construction stage sediment removal (although this activity should have been undertaken before the start of the maintenance contract)
- system rehabilitation immediately following a pollution event.

It is important to note that these remedial activities will not be required for all systems, but for the purpose of estimating whole life maintenance costs, a contingency sum of 15-20% should be added to the annual regular and occasional maintenance costs to cover the risk of these activities being required. Table 32.1 of the CIRIA SuDS Manual (C753), indicates typical key SuDS components operation and maintenance activities as shown overleaf.

Monitoring consists of inspection only to assess performance.

| TABLE 32.1 Typical key SuDS components operation and maintenance activities (for full specifications, see Chapters 11–23) | | | | | | | | | | | | | |
|--|----------------|---------|-----------------|--------------------|----------|---------------------|--------------|-----------------|-------------------|--------------------------|--------------|-------------|-------------------------------|
| Operation and maintenance activity | SuDS component | | | | | | | | | | | | |
| | Pond | Wetland | Detention basin | Infiltration basin | Soakaway | Infiltration trench | Filter drain | Modular storage | Pervious pavement | Swale/bioretention/trees | Filter strip | Green roofs | Proprietary treatment systems |
| Regular maintenance | | | | | | | | | | | | | |
| Inspection | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ |
| Litter and debris removal | ■ | ■ | ■ | ■ | □ | ■ | ■ | □ | ■ | ■ | ■ | | □ |
| Grass cutting | ■ | ■ | ■ | ■ | □ | ■ | ■ | □ | □ | ■ | ■ | | |
| Weed and invasive plant control | □ | □ | □ | □ | | □ | □ | | □ | | □ | ■ | |
| Shrub management (including pruning) | □ | □ | □ | □ | | | | | □ | □ | □ | | |
| Shoreline vegetation management | ■ | ■ | □ | | | | | | | | | | |
| Aquatic vegetation management | ■ | ■ | □ | | | | | | | | | | |
| Occasional maintenance | | | | | | | | | | | | | |
| Sediment management ¹ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | ■ | | ■ |
| Vegetation replacement | □ | □ | □ | □ | | | | | | □ | □ | ■ | |
| Vacuum sweeping and brushing | | | | | | | | | ■ | | | | |
| Remedial maintenance | | | | | | | | | | | | | |
| Structure rehabilitation /repair | □ | □ | □ | □ | □ | □ | □ | □ | □ | □ | □ | □ | |
| Infiltration surface reconditioning | | | | □ | □ | □ | □ | | □ | □ | □ | | |

Key
 ■ will be required
 □ may be required

Notes
 1 Sediment should be collected and managed in pre-treatment systems, upstream of the main device.

Figure 17 - Extract of Table 32.1 from the SuDS Manual

8.4.1. Soakaways

Regular inspection and maintenance are required to ensure the effective long-term operation of soakaways. Maintenance is typically carried out manually and undertaken by a responsible organisation.

The maintenance requirements for soakaways are described in Table 5 - Maintenance requirements for soakaways. Specific maintenance needs of the system should be monitored, and maintenance schedules adjusted to suit requirements.

Table 5 - Maintenance requirements for soakaways

| MAINTENANCE SCHEDULE | REQUIRED ACTIONS | FREQUENCY |
|------------------------|--|--|
| Regular maintenance | Inspect for sediment and debris in pre-treatment components and floor of inspection tube or chamber and inside of concrete manhole rings | Annually |
| | Cleaning of gutters and any filters on downpipes | Annually (or as required based on inspections) |
| | Trimming any roots that may be causing blockages | Annually (or as required) |
| Occasional maintenance | Remove sediment and debris from pre-treatment components and floor of inspection tube or chamber and inside of concrete manhole rings | As required, based on inspections |
| Remedial actions | Reconstruct soakaway and/or replace or clean void fill, if performance deteriorates or failure occurs | As required |
| | Replacement of clogged geotextile (will require reconstruction of soakaway) | As required |
| Monitoring | Inspect silt traps and note rate of sediment accumulation | Monthly in the first year and then annually |
| | Check soakaway to ensure emptying is occurring | Annually |

8.4.2. Permeable Paving

Regular inspection and maintenance are important for the effective operation of pervious pavements. Maintenance responsibility for a pervious pavement and its surrounding area should be placed with an appropriate responsible organisation.

The paving should be inspected regularly, preferably during and after heavy rainfall to check effective operation and to identify any areas of ponding.

Pervious surfaces need to be regularly cleaned of silt and other sediments to preserve their infiltration capability. Experience in the UK is limited, but advice issued with permeable precast concrete paving has suggested a minimum of three surface sweepings per year. Manufacturers' recommendations should always be followed.

A brush and suction cleaner, which can be a lorry-mounted device or a smaller precinct sweeper, should be used and the sweeping regime should be as follows:

- End of winter (April) – to collect winter debris.

- Mid-summer (July/August) – to collect dust, flower and grass-type deposits.
- After autumn leaf fall (November).

Care should be taken in adjusting vacuuming equipment to avoid removal of jointing material. Any lost material should be replaced.

Operation and maintenance requirements for permeable paving are described in Table 6.

Table 6 Maintenance requirements Permeable Paving

| MAINTENANCE SCHEDULE | REQUIRED ACTIONS | FREQUENCY |
|------------------------|---|--|
| Regular maintenance | Brushing and vacuuming. | Three times/year at end of winter, mid-summer, after autumn leaf fall, or as required based on site-specific observations of clogging or manufacturers' recommendations. |
| Occasional maintenance | Stabilise and mow contributing and adjacent areas. | As required. |
| | Removal of weeds. | As required. |
| Remedial actions | Remediate any landscaping which, through vegetation maintenance or soil slip, has been raised to within 50 mm of the level of the paving. | As required. |
| | Remedial work to any depressions, rutting and cracked or broken blocks considered detrimental to the structural performance or a hazard to users. | As required. |
| | Rehabilitation of surface and upper sub-structure. | As required (if infiltration performance is reduced as a result of significant clogging). |
| Monitoring | Initial inspection. | Monthly for three months after installation |
| | Inspect for evidence of poor operation and/or weed growth. If required, take remedial action. | 3-monthly, 48 h after large storms. |
| | Inspect silt accumulation rates and establish appropriate brushing frequencies. | Annually. |
| | Monitor inspection chambers. | Annually. |

8.4.3. Green Roofs

Intensive green roofs will require regular maintenance. Grass will require mowing weekly or fortnightly, plant beds may require weeding on a weekly or fortnightly basis during the growing season, and wildflower meadows may require annual mowing with the cuttings removed.

Extensive green roofs should normally only require bi-annual or annual visits to remove litter, check fire breaks and drains and, in some cases, remove unwanted colonising plants.

All maintenance shall be carried out in accordance with the specific green roof manufacturer requirements which shall as a minimum include those described in Table 7.

Table 7 Maintenance requirements for Green Roofs

| MAINTENANCE SCHEDULE | REQUIRED ACTIONS | FREQUENCY |
|----------------------|---|--|
| Regular Maintenance | Remove debris and litter to prevent clogging of inlet drains and interference with plant growth. | Six monthly/ Annually or as required. |
| | During establishment (i.e. one year), replace dead plants as required. | Monthly (but usually responsibility of manufacturer) |
| | Post establishment, replace dead plants as required. | Annually (in autumn) |
| | Remove fallen leaves and debris from deciduous plant foliage. | Six monthly or as required. |
| | Remove nuisance and invasive vegetation, including weeds. | Six monthly or as required. |
| | Mow grasses (if appropriate) as required. Clippings must be removed and not allowed to accumulate. | Six monthly or as required. |
| Remedial Actions | If erosion channels are evident, these should be stabilised with additional soil substrate similar to the original material. Sources of erosion damage must be identified and controlled. | As required. |

8.4.4. Silt Traps and Catchpits

Regular inspection and maintenance are required to ensure the effective long-term operation of the below ground silt traps and catchpits systems. Maintenance responsibility for systems should be placed with a responsible organisation.

The maintenance requirements for silt traps and catchpits are described in Table 8. Specific maintenance needs of the system should be monitored, and maintenance schedules adjusted to suit requirements.

Table 8 - Maintenance requirements for Silt Traps and Catchpits

| MAINTENANCE SCHEDULE | REQUIRED ACTIONS | FREQUENCY |
|----------------------|---|--|
| Regular maintenance | Inspect and identify any areas that are not operating correctly. If required, take remedial action. | Monthly for 3 months, then six monthly |
| | Debris removal from catchment surface (where may cause risks to performance) | Monthly |
| | Inspection of silt traps and catchpits to assess silt accumulation | Monthly (and after large storms) |
| | Removal of accumulated silt from silt trap and catchpit sumps | Annually, or as required |

| | | |
|------------------|--|---------------------------------|
| Remedial actions | Repair/rehabilitation of inlets, outlet, overflows and vents | As required |
| Monitoring | Inspect/check all inlets, outlets, vents and overflows to ensure that they are in good condition and operating as designed | Annually and after large storms |

8.4.5. Gullies / Linear Drainage Channels

Inspection and removal of debris from silt trap once a year; preferably after leaf fall in the autumn.

8.4.6. Drainage pipes, manholes and silt traps

Inspect manholes and silt traps for build-up of silt and general debris once a year; preferably after leaf fall in the autumn. If silt/debris is building up, then clean with jetting lorry / gully sucker and inspect pipe – repeat cleaning if required. If the pipes to be jetted are plastic, then a high flow, low pressure setting should be used so that the pipes are not damaged.


9. EXCEEDANCE ROUTES

If the below ground drainage system experiences a storm greater than 100yr+40%cc surface water would flow on the ground away from the proposed building. An exceedance plan is shown in **Appendix I**.

10. APPENDICES

A. TOPOGRAPHICAL SURVEY, UTILITIES SURVEY AND CCTV DRAINAGE SURVEY






Extract of Utility Survey
PCH
28.06.2024



G.O. DRAINAGE SERVICES LTD



CV.02888 ST MARYS UNIVERSITY R BUILDING



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

CCTV SURVEY HEADER SHEET

CLIENT. RIDGE

LOCATION. ST MARYS UNIVERSITY
R BUILDING
TW1 4SX

JOB NO. CV.02888

SEWER USE. FOUL + SURFACE DRAINAGE

WEATHER. DRY


DATE. 16/07/24


OPERATOR. GO

CLEANED. NO

ORDER NO. E-MAIL PAUL

TOTAL LENGTH SURVEYED. 269.2 metres









MANHOLE SURVEY

| | |
|--|--|
| CLIENT: ST MARYS UNIVERSITY R BUILDING TW1 4SX | LOCATION: ST MARYS UNIVERSITY R BUILDING TW1 4SX |
| DATE 16/07/24 | JOB. CV.02888 |

MANHOLE NO.0144
COVER 610X610 mm
CHAMBER 1500mm



MANHOLE NO.0149
COVER 610X610mm
CHAMBER 1250mm





MANHOLE SURVEY

CLIENT: ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION: ST MARYS UNIVERSITY R BUILDING TW1 4SX

DATE 16/07/24

JOB. CV.02888

MANHOLE NO.0150
COVER 610X610mm
CHAMBER 470mm

C150 PVC
DEPTH 840mm



MANHOLE NO.152
COVER 610X610mm
CHAMBER 1050mm

C100 PVC
DEPTH 840mm





MANHOLE SURVEY

CLIENT: ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION: ST MARYS UNIVERSITY R BUILDING TW1 4SX

DATE 16/07/24

JOB. CV.02888

MANHOLE NO.0162

COVER 490mm

CHAMBER 470mm

C100 PVC
DEPTH 670mm



C100 PVC
DEPTH 640m

MANHOLE NO.0164

COVER 490mm

CHAMBER 470mm



C100 PVC
DEPTH 900mm

C100 PVC
DEPTH 970mm



MANHOLE SURVEY

CLIENT: ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION: ST MARYS UNIVERSITY R BUILDING TW1 4SX

DATE 16/07/24

JOB. CV.02888

MANHOLE NO.0165

COVER 670mm

CHAMBER 1050mm

C100 PVC
DEPTH 680mm



C100 PVC
DEPTH 280mm

MANHOLE NO.0166

COVER 490mm

CHAMBER 470mm

C100 PVC
DEPTH 560mm

C100 PVC
DEPTH 660mm





MANHOLE SURVEY

CLIENT: ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION: ST MARYS UNIVERSITY R BUILDING TW1 4SX

DATE: 16/07/24

JOB: CV.02888

MANHOLE NO.0173

COVER 660X660mm

CHAMBER 1000X700mm

C150 VC
DEPTH 870mm

C150 VC
DEPTH 880mm

C100 VC
DEPTH 770mm



MANHOLE NO.175

COVER 660X660mm

CHAMBER 1000X700mm

C100 VC
DEPTH 860mm

C150 VC
DEPTH 950mm

C150 VC
DEPTH 940mm

C100 VC
DEPTH 860mm





MANHOLE SURVEY

CLIENT: ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION: ST MARYS UNIVERSITY R BUILDING TW1 4SX


DATE: 16/07/24

JOB: CV.02888

MANHOLE NO.176

COVER 660X660mm


CHAMBER 900X700mm



MANHOLE NO.177

COVER 660X660mm

CHAMBER 900X700mm







MANHOLE SURVEY

| | |
|--|--|
| CLIENT: ST MARYS UNIVERSITY R BUILDING TW1 4SX | LOCATION: ST MARYS UNIVERSITY R BUILDING TW1 4SX |
| DATE 16/07/24 | JOB. CV.02888 |

MANHOLE NO.178
COVER 660X660mm
CHAMBER 900X700mm



MANHOLE NO.179
COVER 660X660mm
CHAMBER 800X600mm





MANHOLE SURVEY

CLIENT: ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION: ST MARYS UNIVERSITY R BUILDING TW1 4SX

DATE 16/07/24

JOB. CV.02888

MANHOLE NO.219

COVER 490mm

CHAMBER 470mm

C100 VC
DEPTH 820mm



C100 VC
DEPTH 810mm

C100 VC
DEPTH 670mm

MANHOLE NO.223

COVER 490mm

CHAMBER 470mm

C100 VC
DEPTH 720mm



C100 VC
DEPTH 770mm

C100 VC
DEPTH 760mm



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 01 | 16/07/24 | SURFACE | 600mm | DOWNSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

| START | FINISH |
|--------------------|--------------------|
| ST. MANHOLE No.166 | FH. MANHOLE NO.223 |

| CHAINAGE | CODE | OBSERVATION |
|----------|------|-------------|
|----------|------|-------------|



| | | |
|----------|-----|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 000.3 S1 | DES | SETTLED DEPOSITS COARSE 10% START |
| 002.5 | JN | JUNCTION AT 03 O'CLOCK,DIAMETER 100mm |
| 002.5 F1 | DES | SETTLED DEPOSITS COARSE 10% END |
| 000.3 S2 | DES | SETTLED DEPOSITS COARSE 05% START |
| 011.0 | JN | JUNCTION AT 03 O'CLOCK,DIAMETER 100mm |
| 012.6 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 012.6 F2 | DES | SETTLED DEPOSITS COARSE 10% END |
| 013.5 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 014.8 | MH | MANHOLE NO.223 |
| 014.8 | FH | FINISH OF SURVEY |

END OF RUN NO.01





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 02 | 16/07/24 | SURFACE | 720mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

| START | FINISH |
|-----------------------------------|---------|
| ST. MANHOLE No. 223 CONNECTION- 1 | FH. RWP |



| CHAINAGE | CODE | OBSERVATION |
|----------|------|--------------------------------------|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 000.3 | LU | LINE OF DRAIN DEVIATES UP (SLIGHT) |
| 001.4 | LU | LINE OF DRAIN DEVIATES UP (SHARP) |
| 001.4 | FH | FINISH OF SURVEY RWP |

END OF RUN NO.02





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 03 | 16/07/24 | SURFACE | 770mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

| START | FINISH |
|--------------------|--------------------|
| ST. MANHOLE No.223 | FH. MANHOLE NO.219 |



| CHAINAGE | CODE | OBSERVATION |
|----------|------|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 000.3 | DES | SETTLED DEPOSITS FINE 05% |
| 000.3 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 004.4 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 008.3 | MH | MANHOLE NO.219 |
| 008.3 | FH | FINISH OF SURVEY |

END OF RUN NO.03





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX


| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 04 | 16/07/24 | SURFACE | 820mm | DOWNSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START FINISH
 ST. MANHOLE No. 219 CONNECTION- X FH. DOWNSTREAM



| CHAINAGE | CODE | OBSERVATION |
|----------|------|---------------------------------------|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 005.2 | LD | LINE OF DRAIN DEVIATES DOWN (SHARP) |
| 005.8 | FH | FINISH OF SURVEY SOAKAWAY |

END OF RUN NO.04





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com


INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|--------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 05 | 16/07/24 | SURFACE | 1250mm | DOWNSTREAM | 150mm | V/CLAY | DRY | NO | GO | 1 |

| START | FINISH |
|---------------------|----------------|
| ST. MANHOLE No. 211 | FH. DOWNSTREAM |



END OF RUN NO.05



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 06 | 16/07/24 | FOUL | 870mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |


| START | FINISH |
|---------------------|--------------|
| ST. MANHOLE No. 173 | FH. UPSTREAM |

| CHAINAGE | CODE | OBSERVATION |
|----------|------|-------------|
|----------|------|-------------|



| | | |
|-------|-----|-------------------------------------|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 001.5 | SC | DIMENSION OF DRAIN CHANGES TO 100mm |
| 013.6 | MH | MANHOLE NO.173A |
| 014.4 | REM | GENERAL REMARK (END OF CHAMBER) |
| 016.6 | MH | MANHOLE NO.173B |
| 017.8 | REM | GENERAL REMARK (END OF CHAMBER) |
| 029.4 | MH | MANHOLE NO.173C |
| 029.4 | FH | FINISH OF SURVEY |

END OF RUN NO.06





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 07 | 16/07/24 | FOUL | 770mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START

FINISH

ST. MANHOLE No. 173 CONNECTION- 2

FH. MANHOLE NO.189

| CHAINAGE | CODE | OBSERVATION |
|----------|------|-------------|
|----------|------|-------------|



| | | |
|-------|-----|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 001.8 | MH | MANHOLE NO.172 |
| 002.4 | REM | GENERAL REMARK (END OF CHAMBER) |
| 002.4 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 011.8 | MH | MANHOLE NO.189 |
| 011.8 | FH | FINISH OF SURVEY |

END OF RUN NO.07





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 08 | 16/07/24 | FOUL | 880mm | DOWNSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START FINISH

ST. MANHOLE No. 173 CONNECTION- X FH.

| CHAINAGE | CODE | OBSERVATION |
|----------|------|-----------------------------------|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 006.3 | MH | MANHOLE NO.175 |
| 007.2 | REM | GENERAL REMARK (END OF CHAMBER) |
| 013.5 | MH | MANHOLE NO.178 |
| 013.5 | FH | FINISH OF SURVEY |



END OF RUN NO.08



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 09 | 16/07/24 | FOUL | 480mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

| START | FINISH |
|-----------------------------------|--------------|
| ST. MANHOLE No. 177 CONNECTION- 1 | FH. UPSTREAM |



| CHAINAGE | CODE | OBSERVATION |
|----------|------|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 001.7 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 002.6 | LU | LINE OF DRAIN DEVIATES UP (SHARP) |
| 002.6 | FH | FINISH OF SURVEY |

END OF RUN NO.09





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 10 | 16/07/24 | FOUL | 710mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |


| START | FINISH |
|---------------------|--------------|
| ST. MANHOLE No. 177 | FH. UPSTREAM |

| CHAINAGE | CODE | OBSERVATION |
|----------|------|-------------|
|----------|------|-------------|



| | | |
|-------|-----|-------------------------------------|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 001.6 | DES | SETTLED DEPOSITS FINE % |
| 002.0 | DES | SETTLED DEPOSITS FINE % |
| 002.0 | LU | LINE OF DRAIN DEVIATES UP (SHARP) |
| 002.0 | FH | FINISH OF SURVEY |

END OF RUN NO.10





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 11 | 16/07/24 | FOUL | 710mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

| START | FINISH |
|---------------------|-----------|
| ST. MANHOLE No. 177 | FH. GULLY |

| CHAINAGE | CODE | OBSERVATION |
|----------|------|-------------|
|----------|------|-------------|



| | | |
|-------|----|--|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 001.0 | LL | LINE OF DRAIN DEVIATES LEFT (SLIGHT) |
| 001.4 | LD | LINE OF DRAIN DEVIATES DOWN (SHARP) |
| 001.4 | FH | FINISH OF SURVEY (GULLY) |

END OF RUN NO.11





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX


| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 12 | 16/07/24 | FOUL | 710mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

| START | FINISH |
|-----------------------------------|--------------|
| ST. MANHOLE No. 177 CONNECTION- 4 | FH. UPSTREAM |



| CHAINAGE | CODE | OBSERVATION |
|----------|------|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 000.3 | LU | LINE OF DRAIN DEVIATES UP (SHARP) |
| 001.1 | FC | FRACTURE, CIRCUMFERENTIAL FROM 12 TO 12 O'CLOCK |
| 001.1 | DES | SETTLED DEPOSITS FINE 30% |
| 001.6 | LU | LINE OF DRAIN DEVIATES UP (SHARP) |
| 001.6 | FH | FINISH OF SURVEY |

END OF RUN NO.12





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX


| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 13 | 16/07/24 | FOUL | 860mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START FINISH
 ST. MANHOLE No. 177 CONNECTION- 5 FH. UPSTREAM



| CHAINAGE | CODE | OBSERVATION |
|----------|------|---------------------------------------|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 001.2 | DES | SETTLED DEPOSITS FINE 10% |
| 001.7 | DES | SETTLED DEPOSITS FINE 20% |
| 001.8 | LD | LINE OF DRAIN DEVIATES DOWN (SHARP) |
| 001.8 | FH | FINISH OF SURVEY (GULLY) |

END OF RUN NO.13





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 14 | 16/07/24 | FOUL | 870mm | DOWNSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START

FINISH

ST. MANHOLE No. 177 CONNECTION- X

FH. MANHOLE NO.178

| CHAINAGE | CODE | OBSERVATION |
|----------|------|--|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 000.3 | LL | LINE OF DRAIN DEVIATES LEFT (SLIGHT) |
| 001.0 | MH | MANHOLE NO.178 |
| 001.0 | FH | FINISH OF SURVEY |



END OF RUN NO.14



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|--------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 15 | 16/07/24 | FOUL | 1070mm | DOWNSTREAM | 150mm | V/CLAY | DRY | NO | GO | 1 |

| START | FINISH |
|-----------------------------------|----------------|
| ST. MANHOLE No. 178 CONNECTION- X | FH. DOWNSTREAM |

| CHAINAGE | CODE | OBSERVATION |
|----------|------|-------------|
|----------|------|-------------|

MH-178



| | | |
|-------|-----|--|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 015.0 | DES | SETTLED DEPOSITS COARSE 20% |
| 016.3 | MH | MANHOLE NO.181 |
| 017.4 | REM | GENERAL REMARK (END OF CHAMBER) |
| 024.4 | MH | MANHOLE NO.183 |
| 025.0 | REM | GENERAL REMARK (END OF CHAMBER) |
| 034.0 | LL | LINE OF DRAIN DEVIATES LEFT (SLIGHT) |
| 035.0 | MH | MANHOLE NO.186 |
| 035.0 | FH | FINISH OF SURVEY |

END OF RUN NO.

MH-186



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX


| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 16 | 16/07/24 | FOUL | 860mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START FINISH
 ST. MANHOLE No. 175 CONNECTION- 1 FH. UPSTREAM



| CHAINAGE | CODE | OBSERVATION |
|----------|------|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 001.3 | LL | LINE OF DRAIN DEVIATES LEFT (SLIGHT) |
| 002.4 | CC | CRACK,CIRCUMFERENTIAL FROM 07 TO 05 O'CLOCK |
| 003.0 | DES | SETTLED DEPOSITS COARSE 10% |
| 003.6 | FH | FINISH OF SURVEY |

END OF RUN NO.16





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX


| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 17 | 16/07/24 | FOUL | 860mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START FINISH
 ST. MANHOLE No. 175 CONNECTION- 2 FH. UPSTREAM



| CHAINAGE | CODE | OBSERVATION |
|----------|------|--|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 001.8 | LL | LINE OF DRAIN DEVIATES LEFT (SLIGHT) |
| 003.0 | DES | SETTLED DEPOSITS FINE % |
| 003.9 | LD | LINE OF DRAIN DEVIATES DOWN (SHARP) |
| 003.9 | FH | FINISH OF SURVEY (GULLY) |

END OF RUN NO.17





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 18 | 16/07/24 | FOUL | 860mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

| START | FINISH |
|---------------------|-----------|
| ST. MANHOLE No. 175 | FH. GULLY |

| CHAINAGE | CODE | OBSERVATION |
|----------|------|-------------|
|----------|------|-------------|



| | | |
|-------|----|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 001.3 | FC | FRACTURE, CIRCUMFERENTIAL FROM 12 TO 12 O'CLOCK |
| 002.7 | LD | LINE OF DRAIN DEVIATES DOWN (SHARP) |
| 002.7 | FH | FINISH OF SURVEY (GULLY) |

END OF RUN NO.18

GULLY



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|--------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 19 | 16/07/24 | SURFACE | 1070mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START FINISH
 ST. MANHOLE No. 176 CONNECTION- 1 FH. UPSTREAM



| CHAINAGE | CODE | OBSERVATION |
|----------|------|-------------------------------------|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 000.4 | LU | LINE OF DRAIN DEVIATES UP (SHARP) |
| 000.7 | FH | FINISH OF SURVEY |

END OF RUN NO.19

U/ST



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX


| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 20 | 16/07/24 | SURFACE | 990mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START FINISH
 ST. MANHOLE No. 176 CONNECTION- 2 FH. UPSTREAM



| CHAINAGE | CODE | OBSERVATION |
|----------|------|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 001.3 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 003.4 | DES | SETTLED DEPOSITS FINE 20% |
| 003.4 | FC | FRACTURE, CIRCUMFERENTIAL FROM 12 TO 12 O'CLOCK |
| 004.6 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 004.6 | R | ROOTS FINE |
| 004.6 | FH | FINISH OF SURVEY |

END OF RUN NO.20





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|--------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 21 | 16/07/24 | SURFACE | 1080mm | DOWNSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START

FINISH

ST. MANHOLE No. 176 CONNECTION- X

FH. MANHOLE NO.179

| CHAINAGE | CODE | OBSERVATION |
|----------|------|-------------|
|----------|------|-------------|



MH-176

| | | |
|-------|----|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 004.3 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 005.5 | MH | MANHOLE NO.179 |
| 005.5 | FH | FINISH OF SURVEY |

END OF RUN NO.21

MH-179



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT: ST MARYS UNIVERSITY R BUILDING TW1 4SX LOCATION: ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|--------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 22 | 16/07/24 | SURFACE | 1150mm | DOWNSTREAM | 150mm | V/CLAY | DRY | NO | GO | 1 |

START FINISH
 ST. MANHOLE No. 179 CONNECTION- X FH. DOWN STREAM



| CHAINAGE | CODE | OBSERVATION |
|----------|------|-------------------------------|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 000.0 | WL | WATER LEVEL 30% |
| 001.1 | CU | CAMERA UNDER WATER |
| 002.0 | SA | SURVEY ABANDONED DUE TO ABOVE |

END OF RUN NO.22

D/ST



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 23 | 16/07/24 | SURFACE | N/A | DOWNSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START

FINISH

ST. RE No. 1 CONNECTION- X

FH. MANHOLE NO.166

| CHAINAGE | CODE | OBSERVATION |
|----------|------|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 000.3 | LD | LINE OF DRAIN DEVIATES DOWN (SHARP) |
| 000.6 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 002.5 | JN | JUNCTION AT 03 O'CLOCK,DIAMETER 100mm |
| 005.9 | JN | JUNCTION AT 09 O'CLOCK,DIAMETER 100mm |
| 010.2 | JN | JUNCTION AT 03 O'CLOCK,DIAMETER 100mm |
| 015.0 | JN | JUNCTION AT 03 O'CLOCK,DIAMETER 100mm |
| 021.6 | MH | MANHOLE NO.166 |
| 021.6 | FH | FINISH OF SURVEY |

RE-1



MH-166

END OF RUN NO.23



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX


| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 24 | 16/07/24 | SURFACE | 640mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

START FINISH
 ST. MANHOLE No. 162 CONNECTION- 1 FH.



| CHAINAGE | CODE | OBSERVATION |
|----------|------|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 002.0 | WL | WATER LEVEL 20% |
| 003.1 | RFJ | ROOTS FINE AT JOINT |
| 003.2 | LU | LINE OF DRAIN DEVIATES UP (SHARP) |
| 011.8 | DES | SETTLED DEPOSITS FINE 20% |
| 011.8 | WL | WATER LEVEL 20% |
| 012.2 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 012.2 | FH | FINISH OF SURVEY |

END OF RUN NO.24





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX


| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|-----------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 25 | 16/07/24 | SURFACE | 780mm | UPSTREAM | 100mm | V/CLAY | DRY | NO | GO | 1 |

| START | FINISH |
|-----------------------------------|--------------|
| ST. MANHOLE No. 152 CONNECTION- 1 | FH. UPSTREAM |



| CHAINAGE | CODE | OBSERVATION |
|----------|------|---|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 004.9 | LR | LINE OF DRAIN DEVIATES RIGHT (SLIGHT) |
| 005.5 | JN | JUNCTION AT 09 O'CLOCK,DIAMETER 100mm |
| 005.8 | LU | LINE OF DRAIN DEVIATES UP (SHARP) |
| 006.3 | FH | FINISH OF SURVEY |

END OF RUN NO.25





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 26 | 16/07/24 | SURFACE | 840mm | DOWNSTREAM | 150mm | V/CLAY | DRY | NO | GO | 1 |

START

FINISH

ST. MANHOLE No. 150 CONNECTION- X

FH. MANHOLE NO.149

| CHAINAGE | CODE | OBSERVATION |
|----------|------|---------------------------|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 009.9 | DES | SETTLED DEPOSITS FINE 10% |
| 013.7 | MH | MANHOLE NO.149 |
| 013.7 | FH | FINISH OF SURVEY |

MH-150



MH-149

END OF RUN NO.26



G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|-------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 27 | 16/07/24 | SURFACE | 900mm | DOWNSTREAM | 150mm | V/CLAY | DRY | NO | GO | 1 |

START

FINISH

ST. MANHOLE No. 149 CONNECTION- X

FH. MANHOLE NO.144

| CHAINAGE | CODE | OBSERVATION |
|----------|------|------------------|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 021.7 | MH | MANHOLE NO.144 |
| 021.7 | FH | FINISH OF SURVEY |



END OF RUN NO.27





G.O. DRAINAGE SERVICES LTD



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

INSPECTION REPORT

CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX

LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX

| JOB NO. | RUN NUMBER | DATE | SEWER USE | DEPTH | DIRECTION | PIPE SIZE | MATERIAL | WEATHER | CLEANED | OPERATOR | PAGE |
|---------|------------|----------|-----------|--------|------------|-----------|----------|---------|---------|----------|------|
| CV.2888 | 28 | 16/07/24 | SURFACE | 1210mm | DOWNSTREAM | 150mm | V/CLAY | DRY | NO | GO | 1 |

START FINISH
 ST. MANHOLE No. 144 CONNECTION- X FH. DOWNSTREAM



| CHAINAGE | CODE | OBSERVATION |
|----------|------|--|
| 000.0 | ST | START OF SURVEY |
| 000.0 | WL | WATER LEVEL 05% |
| 000.4 | R | ROOTS FINE |
| 001.3 | R | ROOTS FINE |
| 002.0 | WL | WATER LEVEL 05% |
| 007.0 | WL | WATER LEVEL 05% |
| 009.5 | LL | LINE OF DRAIN DEVIATES LEFT (SLIGHT) |
| 015.0 | DES | SETTLED DEPOSITS FINE 20% |
| 016.9 | FH | FINISH OF SURVEY |

END OF RUN NO.28





SUMMARY AND RECOMMENDATIONS

| | |
|--|--|
| CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX | LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX |
| DATE 16/07/24 | JOB. CV.2888 |

- RUN NO.01 NO WORK NEEDED**
- RUN NO.02 NO WORK NEEDED**
- RUN NO.03 NO WORK NEEDED**
- RUN NO.04 NO WORK NEEDED**
- RUN NO.05 NO WORK NEEDED**
- RUN NO.06 NO WORK NEEDED**
- RUN NO.07 NO WORK NEEDED**
- RUN NO.08 NO WORK NEEDED**
- RUN NO.09 NO WORK NEEDED**
- RUN NO.10 NO WORK NEEDED**
- RUN NO.11 NO WORK NEEDED**
- RUN NO.12 FRACTURE**
- RUN NO.13 NO WORK NEEDED**
- RUN NO.14 NO WORK NEEDED**
- RUN NO.15 NO WORK NEEDED**
- RUN NO.16 CRACK**
- RUN NO.17 NO WORK NEEDED**
- RUN NO.18 FRACTURE**
- RUN NO.19 NO WORK NEEDED**
- RUN NO.20 FRACTURE**



53 PREMIER AVENUE GRAYS RM16 2SJ TEL:01375 373302 MOB:07792 815977 E-MAIL: godrainage@aol.com

SUMMARY AND RECOMMENDATIONS

| | |
|--|--|
| CLIENT. ST MARYS UNIVERSITY R BUILDING TW1 4SX | LOCATION. ST MARYS UNIVERSITY R BUILDING TW1 4SX |
| DATE 16/07/24 | JOB. CV.2888 |

- RUN NO.21 NO WORK NEEDED**
- RUN NO.22 NO WORK NEEDED**
- RUN NO.23 NO WORK NEEDED**
- RUN NO.24 ROOTS FINE**
- RUN NO.25 NO WORK NEEDED**
- RUN NO.26 NO WORK NEEDED**
- RUN NO.27 NO WORK NEEDED**
- RUN NO.28 ROOTS FINE**

**DRAIN & PIPEWORK CCTV
SURVEYS**

-

**DRAINS
PIPEWORK
CULVERTS**

DUCTS

CHUTES

CHIMNEY FLUES

TANKS

**HIGH PRESSURE
WATER JETTING**

-

SEWER & DRAIN BLOCKAGES


DESCALING

SILT REMOVAL

ROOT CUTTING

GREASE REMOVAL

-



G.O. DRAINAGE SERVICES LTD

