

— Structure    — Existing Construction  
 - - - Boundary    ■ New Construction



Elevation 3

New double glazed timber sash window in new opening.

Rear boundary wall rebuilt. Current is toppling over.

**General Notes**  
 - All dimensions to be verified on site  
 - To be read in conjunction with all relevant documents  
 - In the event of discrepancy notify the Architect immediately  
 - All steel structural elements to be finished with intumescent coating, 30 minutes fire resistance. For all structural elements and connection see SE drawings.  
 - This document is copyright of Hugh Cullum Architects Ltd

**Issue Status**  
 - SK Sketch    - T Tender    - P Permissions  
 - D Design    - E Existing Condition    - C Contract

**Latest Revisions**

REV	NOTE	DATE	DRAWN
H	Issued for Planning	25/11/2024	TS / HC



Elevation 4

New veranda now cantilevered and supported at ends rather than new posts installed. To allow for outward-opening door swing.

New double glazed timber sash window in existing opening.

