

Twickenham Alive Ice Rink Strawberry Hill House

Tree Report

The trees around the site are under no danger from the ice rink structure and the rink will not be sited close to or under any trees. Attached is a plan of the site area listing the trees and their locations.

The nearest trees to the site equipment are T1, T3 and T5, as indicated on the map, and measures will be in place to ensure their protection. A rope barrier will be put in place by Jennifer Sarginson, the Gardener in Charge at Strawberry Hill House, as marked on the attached map. This barrier will be in place throughout the rig and de-rig processes and all activity will be confined within the barrier limits.

There will only be **one** vehicle movement on the grass during the rig process. This will deliver the generator and chiller equipment. The vehicle will enter the site by a short distance as marked by the hatched area on the map. All other vehicles will offload in the car park and equipment will then be transported on site by handcart. The above processes will be the same for the de-rig.

There will be no equipment near tree T31 and the temporary walkway will be bounded by barriers preventing public access to the trees and flowerbeds adjacent to tree T31.

None of the rink equipment or marquees are located under or close to any trees.