· RicherMap Case History Report. Dated: 09-Sep-2016 at 11:11:30 AM

Property: 63 Rectory Grove Hampton TW12 1AH (UPRN: 100022282968 - Land Parcel (Approved))

**Development Control Cases** 

DC 16/3591/PDE Officer: Not known

Single storey rear extension (6m depth, 2.7-2.9m eaves height, 2.9m overall

height)

Received: 30-Aug-2016 Valid: Unknown

Status: In Progress

DC 16/2678/HOT Officer: Mr Derek Tanner

Hip to gable and rear dormer roof extension. Rooflights to front elevation. New

front porch.

Received: 05-Jul-2016 Valid: 05-Jul-2016 Status: granted permission 08-Sep-2016

DC 93/1871/FUL Officer: Mr Dave Norris

Erection Of A Two Storey Dwelling House With Garage And Two Parking Spaces.

Received: 10-Dec-1993 Valid: 10-Dec-1993 Status: granted permission 26-Jan-1994

DC 91/1437/FUL Officer: Mr Dave Norris

Erection Of A Two Storey Detached Dwelling House With Garage.

Received: 05-Aug-1991 Valid: 05-Aug-1991 Status: Decision Unknown 18-Sep-1991

DC 91/0632/FUL Officer: Mr Dave Norris

Erection Of A Two Storey Detached Dwelling House With Garage And Two

Parking Spaces.

Received: 12-Apr-1991 Valid: 12-Apr-1991 Status: withdrawn by the applicant 31-May-1991

**Building Control Cases** 

BC 16/1623/IN Officer: Mr Gary Sumpter Ground floor rear extension and loft conversion

Received: 21-Jul-2016 Status: Decision Unknown

BC 11/FEN00662/FENSA Officer: Not known

7 Windows

Received: 28-Oct-2010

Status: Decision Unknown Completion date: 28-Oct-2010

BC 08/FEN01321/FENSA Officer: Not known

2 Windows 1 Door Received: 26-Jun-2008 Status: Decision Unknown Completion date: 26-Jun-2008

BC 06/6598/FENSA Officer: Decode not available for FENSA FENSA Notification of Replacement Glazing comprising 1 Windows and 1 Doors.Installed by Bowater Home Improvements Ltd. FENSA Member No 13992.

Installation ID 3966456. Invoice No 06B18765

Received: 12-Aug-2006

Status: Decision Unknown Completion date: 26-Jul-2006

End of case history report.

RicherMap Constraints Report. Dated: 09-Sep-2016 at 11:11:47 AM

Property: 63 Rectory Grove Hampton TW12 1AH

Number of constraints: 4

Community Infrastructure Levy Band (Low)
Land Use Past Industrial (LM/0316.LM/0268.Sewage.R/892/03.Sewage
Works.Bishops Grove, Hampton Start: 1920 End: 1950)
Village (Hampton Village)
Ward Boundary (Hampton North Ward)

End of constraints report.