

3.5 Underground Services

No evidence was seen on the surface of the sports pitches of underground service infrastructure, e.g. manholes, marker posts, valve housing etc.



Plate 1: Pitch 1 and 2, facing east




Plate 2: Pitch 3, facing north



Plate 3: Pitch 7, facing north



Plate 4: Rugby Pitch 1 – high shade levels



Plate 5: Cricket Outfield



Plate 6: Cricket wicket