Schedule of Doors Undergoing Works							
Door Number	Door Type	Drawing No.	Room No.	Standards	Summary		
DB01	Туре Х	340	В03	FD30 to BS 476: Part 22 (1987) & SR2 to LPS 1175 (Issue 7)	New louvred door and frame.		
DB02	Type X	340	BOI	SR2 to LPS 1175 (Issue 7)	New louvred panel and frame.		
DB03	Type X	339	B01/B03	FD30 to BS 476: Part 22 (1987)	New louvred door and frame.		
DB05	Type X	339	B01/B04	-	New louvred door and frame.		
DG02	Type I - FD	331	G07/G09	FD30 to BS 476: Part 22 (1987)	Door rehung to change openig and fire resistance increased in a sensitive manner.		
DG03	n/a - FD	-	G09/G10	-	Fire Reisisting Partition, refer to drawing 311		
DG07	n/a - FD	311	G01/G10	-	Fire Reisisting Partition, refer to drawing 311		
DG08	Type XI	341	G01/G02d	-	New double door set within a new frame and oper		
DGI4	Type XII	342	G04	-	Modern hardware removed and new hardware fitt		
DGI9	Type III - FD	333	G06/G06b	FD30 to BS 476: Part 22 (1987)	Existing historic door, fire resistance increased in sensitive manner.		
DG20	Type III - FD	333	G05/G06b	FD30 to BS 476: Part 22 (1987)	Existing historic door, fire resistance increased in sensitive manner.		
DG23	Type VI - FD	336	G07/G08	Fire upgraded, but not certified	Existing historic door, fire resistance increased in sensitive manner.; with works to the glass fanlight an closer.		
DG24 @	Type I - FD	331	G07/G08	FD30 to BS 476: Part 22 (1987)	Abestos panel removed and fire resistance increase		
DG25	Type VII - FD	336	G02e/G08	-	New FD60 door leaf in an existing frame.		
DF01	Type II - FD	331	FI3a/FI5	Fire upgraded, but not certified	Door rehung to change openig and fire resistance increased in a sensitive manner.		
DF02	n/a - FD	311	FI3/FI3a	-	Fire Reisisting Partition, refer to drawing 311		
DF09	Type II - FD	331	F15/F16	Fire upgraded, but not certified	Fire resistance increased in a sensitive manner.		
DFI0 a	Type II - FD	331	F14/F15	Fire upgraded, but not certified	Abestos panel removed and fire resistance increased sensitive manner.		
DFII a	Type XII - FD	342	F12/F14	Fire upgraded, but not certified	Suspected abestos panels removed and fire resistar increased in a sensitive manner.		
DF13	Type VIII - FD	338	FII/FI5	Fire upgraded, but not certified	Fire resistance increased in a sensitive manner simila Type II but without a closer		
DS01	-	-	S18/S19	-	Door retained in position unchanged		
DS04	Type III - FD	333	S19a/S20	FD30 to BS 476: Part 22 (1987)	Door adapted and fire resistance increased in a sens		
DS05	Type III - FD	333	S19/S19a	FD30 to BS 476: Part 22 (1987)	Fire resistance increased in a sensitive manner.		
DS09	Type III - FD	333	S19b/S22	FD30 to BS 476: Part 22 (1987)	Fire resistance increased in a sensitive manner.		
DS10	Type III - FD	333	S19b/S21	FD30 to BS 476: Part 22 (1987)	Fire resistance increased in a sensitive manner.		
DSII	Type III - FD	333	S19/S19	FD30 to BS 476: Part 22 (1987)	Fire resistance increased in a sensitive manner.		
DT01	Type IV - FD	334	T23/T23a	FD60 to BS 476: Part 22 (1987)	The existing historic doors are retained and a new he leaf is fitted within the existing frame.		
DT02	Type IV - FD	335	T26a/T27	FD30 to BS 476: Part 22 (1987)	The existing historic doors are retained and a new he leaf is fitted within the existing frame.		
DT03	Type IV - FD	334	T25/T26a	FD60 to BS 476: Part 22 (1987)	The existing historic doors are retained and a new he leaf is fitted within the existing frame.		
DT04	Type V - FD	335	T24b/T26a	FD30 to BS 476: Part 22 (1987)	The existing historic doors are retained and a new he leaf is fitted within the existing frame.		
DT05	Type V - FD	335	T24a/T26a	FD30 to BS 476: Part 22 (1987)	The existing historic doors are retained and a new I leaf is fitted within the existing frame.		

Schedule of Door Types						
Door Type	Doors Within This Type	Standards	Drawing			
I	DG02, DG24	FD30 to BS 476: Part 22 (1987)	331			
Ш	DF01, DF09, DF10	n/a	332			
III	DS04, DS05, DS09, DS10, DS11 (DG19 & DG20 assumed)	FD30 to BS 476: Part 22 (1987)	333			
IV	DT01, DT03	FD60 to BS 476: Part 22 (1987)	334			
٧	DT02, DT04, DT05	FD30 to BS 476: Part 22 (1987)	335			
VI	DG23	n/a	336			
VII	DF13	n/a	337			
VIII	DG25 , DFI I	FD30 to BS 476: Part 22 (1987)	338			
IX	DB04	FD60 to BS 476: Part 22 (1987)	339			
Х	DB01, DB02, DB03 & DB05	n/a	340			
ΧI	DG08	n/a	341			
XII	DFII	n/a	342			

DO NOT SCALE THIS DRAWING USE DIMENSIONS ONLY VERIFY ALL DIMENSIONS ON SITE BEFORE COMMENCING ANY WORK OR SHOP DRAWINGS $\,$ INFORM THE ARCHITECT BEFORE ANY WORK STARTS IF THIS DRAWING EXCEEDS THE QUANTITIES IN ANY WAY

A 5th September 2017 Amended for Listed Building Consent
B 7th September 2017 Door Type VII & VIII swapped.
C 5th January 2018 Door DG02 & DF01 treatment changed

DRAWING ISSUE STATUS	REVISION N°	DATE	SIGNED
RISK ASSESSMENT UNDERTAKEN			
PLANNING APPLICATION N° 1			
PLANNING APPLICATION N° 2			
PLANNING CONSENT			
LISTED BLDG APPLICATION			
LISTED BLDG CONSENT			
DAC APPROVAL			
BLDG CONTROLAPPLICATION			
BLDG CONTROLAPPROVAL			
TENDER DOCUMENT			
CONTRACT DOCUMENT			

CLIENT English Heritage

PROJECT

Marble Hill House

TITLE

Main House: Door Schedule

SCALE	
Not to Scale @ A3	
DATE	DRAWN
August 2017	HS
JOB N°	DRAWING N°
16_132	330 C



Acanthus House
57 Hightown Road
Banbury • Oxfordshire
OX16 9BE
Tel: 01295 702600
Fax: 01295 702601 architects@acanthusclews.co.uk
www.acanthusclews.co.uk
©