

LEGEND

	Existing Tree/Hedge BS 5837:2012 Category B
	Existing Tree/Hedge to be crown lifted for 2.5m to facilitate boundary fencing BS 5837:2012 Category B
	Existing Tree/Hedge BS 5837:2012 Category C
	Existing Tree/Hedge to be crown lifted for 2.5m to facilitate boundary fencing BS 5837:2012 Category C
	Existing Tree/Hedge BS 5837:2012 Category U
	Line of Root Protection Area (RPA) - calculated following guidelines set in BS 5837:2012
	Existing Tree/Hedge to be Removed BS 5837:2012 Category U
	Existing Tree/Hedge BS 5837:2012 Category U Removal recommended if agreed by owner of tree
	Existing Tree/Hedge to be removed to allow for development BS 5837:2012 Category B
	Existing Tree/Hedge to be removed to allow for development BS 5837:2012 Category C
	Existing Tree/Hedge to be removed to allow for development BS 5837:2012 Category U
	Additional feature which doesn't meet BS 5837:2012 categorisation but is included for reference
	Location of boundary fencing positioned as per discussions at meeting on 19/06/19



© HAYDEN'S 2019
 5 Moseleys Farm Business Centre
 Fornham All Saints,
 Bury St Edmunds
 Suffolk IP28 6JY
 www.treesurveys.co.uk



Client:	Bowmer and Kirkland Ltd	Drawing Title:	Tree Works Plan
Site:	Turing House, Hospital Bridge Road, Twickenham, London, TW2 6LH		
Date:	24/06/19	Drawn By:	KFJ
Scale:	1:1000 (A1)	Checked By:	NH
		Drawn No.:	6924-D-TWP
		Rev.:	-

CATEGORY AND DEFINITION

Trees unsuitable for retention	
Category U	Those in such condition that they cannot realistically be retained as living trees in the current land use for longer than 10 years
Trees to be considered for retention	
Category A	Trees of high quality with an estimated remaining life expectancy of at least 40 years
Category B	Trees of moderate quality with an estimated remaining life expectancy of at least 20 years
Category C	Trees of low quality with an estimated remaining life expectancy of at least 10 years, or young trees with a stem diameter below 150mm

NOTE:
 Hayden's Arboricultural Consultants were provided with a Topographical Survey but these do not always show the positions of all the trees/features on site. The locations of any additional features have been fixed using GPS. As such the position of the trees/landscape features should not be taken as exact but gives a fair distribution of their locations on site.

24/06/19 KFJ Based on RPS drawing no. JKK9319_01-05A
 Rev. Date: By: Revision:
 The position, condition, and dimensions of the trees are based on a site survey undertaken on 08/08/18
 "The original of this drawing was produced in colour - a monochrome copy should not be relied upon"



Existing Site Plan