




RUSTON & WARD - ELEVATION 5 - EXISTING



RUSTON & WARD - ELEVATION 6 - EXISTING



RUSTON & WARD - ELEVATION 7 - EXISTING



RUSTON & WARD - ELEVATION 8 - EXISTING

M	etres	Scale 1:10	The Glass House 5 Sclater Street London E1 6JY UK Phone +44(0)20 8444 2999 Email mail@lom-fdp.com
0	2	5	LOM architecture and design
			PRELIMINARY drawing no. revision 1685-A-P058
- -			sheet size scale A1 1:100 @ A1
<u> </u>	Repair external features Remove external lighting	Repair existing external features as per proposal. Removal of existing external features as per proposal.	ELEVATIONS 5 ,6 ,7 & 8
EXTERNAL WORKS			FABRIC CONDITION DRAWING - RUSTON & WARD
И4 	Pipe work removal	Removal of any defunct or unnecessary pipe work and make good.	drawing title
ИЗ	Discoloured signs or features	Undertake restoration works of any existing features or signage to be retained.	
M2	Flashing failure	Replace rainwater goods with new or restore if defect is only minimal.	HAMPTON WATERWORKS
M1	Defective rainwater goods	Replace rainwater goods with new or restore if defect is only minimal such as organic growth blockages.	project
/IETALV			
₹3	Extensive material failure	Substantial restoration works required such as replacing or repairing any broken tiling or roof membranes.	WATERFALL PLANNING LTD
2	Minor material failure	Re-finish any dilapidated areas of roofing	client
R1	Organic growth	Undertake cleaning and removal of any organic growth on or around any roof areas	
OOFIN			
S5 	Window cill material failure or damage	Repair or replace	
64	Defective render	Re-finish any cracked or failed render or plaster.	88
33	Minor material failure	Re-finish any dilapidated areas of stonework	
32	Organic growth	Remove any plant growth within finish material and restore any associated damage/defects.	
31	Discolouration & staining	Undertake cleaning of any stonework, render or plaster with associated defects restored as required.	
	VORK/ RENDER/ PLASTER		
35	Incorrect material from historic works	Any areas of brickwork that varies from the predominant finish type should be re-finished or replaced if required.	
34	Extensive material failure	Substantial restoration works required such as replacing or repairing any decayed bricks and re-pointing.	Area of proposed work
33	Minor material failure	Re-pointing any areas of mortar failure.	
32	Organic growth	Remove any plant growth within finish material and restore any associated damage/defects.	
81	Discolouration & staining	Undertake cleaning of any brickwork with associated defects restored as required.	
RICKW	ORK		INPROGRESS
	DESCRIPTION		INI PROGIT
F.	CONDITION	REQUIRED ACTION	SOUTHLOS

Web www.lom-architecture.com

USE OF DRAWINGS

REVISIONS

- 02.09.2022 INITIAL ISSUE

REV DATE

DO NOT SCALE FROM THIS DRAWING. USE WRITTEN DIMENSIONS AND CHECK ON SITE. THIS DRAWING IS BASED ON SITE INFORMATION SUPPLIED BY THIRD PARTIES AND ACCURACY OF EXISTING FEATURES IS NOT GUARANTEED.

ANY ERROR, OMISSION OR DISCREPANCY NOTED ON OR BETWEEN DRAWINGS AND OTHER DOCUMENTS MUST BE REPORTED IN WRITING IMMEDIATELY.

ALL MECHANICAL, ELECTRICAL AND STRUCTURAL LAYOUTS / COMPONENTS ARE INDICATIVE AND MUST BE DESIGNED AND CHECKED BY SPECIALISTS.

DO NOT START WORK ON SITE BEFORE CONFIRMING THAT ALL NECESSARY

STATUTORY AND OTHER CONSENTS HAVE BEEN OBTAINED.

A 26.05.2023 HISTORIC ENGLAND FOR COMMENT

THIS DRAWING IS COPYRIGHT AND MUST NOT BE DISTRIBUTED WITHOUT PERMISSION. ELECTRONIC CAD FILES MUST NOT BE ALTERED OR COPIED.

SURVEY INFORMATION BY M.J. REES AND COMPANY LID, CHARTERED

OC JF