15 ' 3199 ' HOT


RicherMap Constraints Report. Dated: 28-Jul-2015 at 09:22:58 AM

Property: 6 Cleveland Gardens Barnes London SW13 0AG

Number of constraints: 7

ARCHAEOLOGICAL PRIORITY (ENGLISH HERITAGE) (DLO33475. Mortlake and Barnes.)
Community Infrastructure Levy Band (Higher)
Floodzone 2 (Flood Zone 2. Tidal Models.)
Floodzone 3 (Flood Zone 3. Tidal Models.)
SFRA Zone 3a High Probability (5556)
Village (Barnes Village)
Ward (Mortlake and Barnes Common Ward. 01BDGF.)

End of constraints report.



15 3199/ HOT

RicherMap Case History Report. Dated: 28-Jul-2015 at 09:23:04 AM

Property: 6 Cleveland Gardens Barnes London SW13 0AG

(UPRN: 100022291359 - Land Parcel (Approved))

Development Control Cases

DC 15/3199/HOT Officer: Not known

Single-level basement to be excavated under footprint of building with front

lightwell in front garden.

Received: 22-Jul-2015 Valid: Unknown

Status: In Progress

DC 08/1915/HOT Officer: Ms Kate O'Regan

Demolition of the existing loft extension, construction of new loft extension with

French doors & Juliette balcony.

Received: 05-Jun-2008 Valid: 05-Jun-2008 Status: granted permission 31-Jul-2008

DC 08/1009/HOT Officer: Ms Kate O'Regan

Demolition of existing side extension on ground floor. Construction of proposed side extension with glazed roof and installation of concertina doors to rear

elevation.

Received: 25-Mar-2008 Valid: 25-Mar-2008 Status: granted permission 20-May-2008

DC 08/0998/HOT Officer: Ms Kate O'Regan

Construction of new dormer and extension over the rear addition (following removal of existing) to include French doors, Juliette balcony and 2 windows in

the dormer extension.

Received: 25-Mar-2008 Valid: 25-Mar-2008 Status: refused permission 20-May-2008

Building Control Cases

BC 11/ELE00405/ELECSA Officer: Not known

Circuit alteration or addition in a kitchen/special locationOne or more new circuits

Received: 31-Aug-2010

Status: Decision Unknown Completion date: 31-Aug-2010

BC 09/NIC00543/NICEIC Officer: Not known

Dwelling house New installation rewire or partial rewire

Received: 24-Mar-2009

Status: Decision Unknown Completion date: 24-Mar-2009

BC 08/1250/IN Officer: Mr Peter Bave

Ground floor rear/side single storey extension, dormer roof conversion, dormer

over existing back addition and internal alterations

Received: 16-Jun-2008 Status: Decision Unknown BC 00/1243/BN Officer: Mr M Jennings

First floor rear extension Received: 26-Jun-2000

Status: Building Notice Acknowledged as Valid 03-Jul-2000 Start date: 21-Jul-

2000 Completion date: 19-Sep-2000

BC 92/0126/1/FP Officer: Mr M Jennings

Loft conversion

Received: 25-Feb-1992

Status: Decided (no details) 13-Mar-1992 Start date: 31-Aug-1992 Completion

date: 18-Aug-1992

Enforcement Cases

ENF 09/0022/EN/NAP Officer: Ms Verity Humble-Crofts

Erection of a pitched roof over extension.

Received: 15-Jan-2009

Status: Case Closed Closed date: 16-Feb-2009

End of case history report.

End of ALL related items.