

notes

The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before proceeding with the works.

Where an item is covered by drawings to different scales the larger scale drawing is to be worked to.

Do not scale drawing. Figured dimensions to be worked to in all cases.

CDM Regulations 2007

ALL current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environment Assessment Record

CDM 2007



EXISTING SECTION A

1 : 100

date	rev	revision/author/checker
------	-----	-------------------------

purpose of issue  
**PLANNING**

project  
**Hampton Village**

drawing  
**EXISTING SITE SECTION A**

drawing no	rev
<b>AA5130 /2041</b>	

drawn	IFS	checked	RGH
-------	-----	---------	-----

scale @ A1	1 : 100	date	15/02/2016
------------	---------	------	------------

PRP Architects ©  
 10 Lindsey Street  
 Smithfield  
 London EC1A 9HP  
 T +44 (0)20 7653 1200  
 F +44 (0)20 7653 1201  
 ion.prp@prparchitects.co.uk

