

Revisions			
P01 24.08.16	Planning	ML	PY
P02 27.04.17	Planning	ML	LP

Revision Notes


PLANNING AMENDMENTS

- A GENERAL AMENDMENTS TO THE SOUTH END.
- A1 INCREASED SHINGLES CLADDING AREA AND CURTAIN WALL REDUCED ACCORDINGLY.
- A2 REDUCED MASSING AND REVISED INTERFACE WITH THE SOUTH STAND.
- B PPC LOUVRES LOCATED TO THE BOWL SIDE HAVE BEEN OMITTED.
- C CURTAIN WALL SETTING OUT REVISED GENERALLY. SILICON JOINTS TO TRANSOMS AND MULLION REPLACED WITH CAPPED SYSTEM. LEVEL 04 PPC LOUVRES SETTING OUT & HEIGHT REVISED. MONORAIL FOR ABSEILING REMOVED.
- D GENERAL AMENDMENTS TO THE CENTRAL ELEVATION CANOPY AT LEVEL 5A REVISED GENERALLY AND STANDING SEAM REPLACED WITH SINGLE PLY MEMBRANE. SUPPORT COLUMNS TO ROOF CANOPY REVISED. SQUARE FASCIA TO ROOF EDGE.
- D1 LEVEL 5A GLAZED SCREEN EXTENDED IN HEIGHT AND PPC LOUVRES INCLUDED AT LOW LEVEL.
- D2 INCREASED SHINGLES CLADDING AREA AND CURTAIN WALL AREA REDUCED ACCORDINGLY. FOUR VERTICAL FINES REMOVED.
- D3 PORCELAIN PANELS WITH SLOTTED HOLES FOR VENTILATION REPLACED WITH PPC LOUVRES. EXPRESSED HORIZONTAL PATTERN TO PORCELAIN PANELS OMITTED.
- E GENERAL AMENDMENTS TO THE NORTH END
- E1 PORCELAIN CLADDING REPLACED WITH PPC ALUMINIUM CLADDING.
- E2 GREEN WALL TO THE NORTH END EXTENDED AND PPC LOUVRES REMOVED.
- E3 INCREASED SHINGLES CLADDING AREA AND CURTAIN WALL REDUCED ACCORDINGLY.
- F FENCELINE, GATE AND PERIMETER COLUMNS SETTING OUT REVISED.
- F1 CANOPY TO TURNSTILES REVISED.
- G PORCELAIN PATTERN CHANGED FROM HORIZONTAL TO VERTICAL.
- H PORCELAIN PANELS TO THE SOFFIT OF THE ARCH REPLACED WITH PPC ALUMINIUM PANELS. PORCELAIN PANELS SETTING OUT REVISED.
- K ROOF TO LEVEL 5A (NORTH END) EXTENDED.
- L GLAZED SPANDREL PANELS REPLACED WITH METAL SPANDREL PANEL. PORCELAIN PANELS REPLACED WITH PPC ALUMINIUM CLADDING.
- L1 PPC LOUVRES INCLUDED FOR MECHANICAL VENTILATION.

KEY

- Existing fence & turnstile line
- Tarmac
- Existing concrete slab paving (see image 1 drawing 006)
- Proposed concrete slab paving to match existing at south stand
- Proposed small concrete block paving (similar to south stand, see image 2 drawing 006)
- Resin bonded aggregate with integrated uprights (similar to south stand, see image 3 drawing 006)
- Existing tactile paving to crossing
- Existing bollards
- Proposed bollards
- Demountable bollards for vehicle access
- Cycle Stands
- Dropped Kerb

KEY PLAN



PLANNING

Client
RFU

Project
TWICKENHAM STADIUM
EAST STAND EXTENSION

Drawing title
EXTERNAL WORKS - ZONE 4
LANDSCAPING / TURNSTILE SETTING
OUT PLANS

KSS Scale at A1
1 : 100
File ref
East Stand Extension
Drawn by
Date drawn

London		Sevenoaks		ML	
1 James Street	7 Blighs Walk	ML	23.08.16		
London W1U 10R	Sevenoaks TN13 1DB	Checked by	Date checked		
T+44(0)20 7907 2222	T+44(0)20 7907 2222	PY	27.04.17		
F+44(0)20 7907 2299	F+44(0)1732 467 841				

Doc ref	Project number	Drawing number	Revision
100-KSS-DR	15735	1003	P02

