


Richmond College


Amendments
Following Consultee
Comments

May 2022

#### **Market Sale**

- 1 Cycles increased from 32no. to 40no. (40no. required) no internal access from core.
- 2 Bins increased from 3no. to 5no. (5no. required)
- 3 Apartments adjusted to meet M4(3)(2)(a) Wheelchair Adaptable requirement.
- 4 Apartment adjusted from M4(3) to M4(2) (note: relocated to Block 5)
- > Window and door placements adjusted to suit
- > Landscape adjusted to suit









#### Market Sale

- 1 Cycles increased from 32no. to 40no. (40no. required) no internal access from core.
- 2 Bins increased from 3no. to 5no. (5no. required)
- 3 Apartments adjusted to meet M4(3)(2)(a) Wheelchair Adaptable requirement.
- 4 Apartment adjusted from M4(3) to M4(2) (note: relocated to Block 5)
- > Window and door placements adjusted to suit
- > Landscape adjusted to suit









#### **Shared Ownership**

- 1 Cycles increased from 32no. to 42no. (42no. required) no internal access from core.
- 2 Bins increased from 3no. to 5no. (5no. required)
- 3 Apartments adjusted to meet M4(3)(2)(a) Wheelchair Adaptable requirement.
- 4 Apartment adjusted from M4(3) to M4(2) (note: relocated to Block 5)
- > Window and door placements adjusted to suit
- > Landscape adjusted to suit








#### **Market Sale**

- 1 Cycles increased from 32no. to 44no. (44no. required) no internal access from core.
- 2 Bins increased from 3no. to 5no. (5no. required)
- 3 Apartments adjusted to meet M4(3)(2)(a) Wheelchair Adaptable requirement.
- 4 Apartment adjusted from M4(3) to M4(2) (note: relocated to Block 5)
- > Window and door placements adjusted to suit
- > Landscape adjusted to suit









### Block 5 - Ground Floor

#### Shared Ownership & Affordable Rent

- 1 Cycles amended from 126no. to 122no. (122no. required)
  Cycle stores separated by tenure and located by cores.
- 2 Bins increased from 13no. to 17no. (17no. required) Refuse stores separated by tenure.
- 3 Apartments adjusted to meet M4(3)(2)(a) & (b) requirements.
- 4 Apartments adjusted to meet M4(3)(a) requirement, changed from 2b3p to 1b2p.
- 5 Apartments adjusted to meet M4(3)(b) requirement, changed from 2b4p to 2b3p.
- 6 Apartments adjusted to meet M4(3)(b) requirement, changed from 3b5p to 3b4p.
- 7 Amended from 2b4p to 1b2p.
- 8 Amended from 1b2p to 2b3p.











Core F - GF

1b2p

2р3р

2b4p

3р5р

1b2p

2р3р

2b4p

3р4р

3р5р


3

### Block 5 - Floors 1st to 3rd

#### Shared Ownership & Affordable Rent

- 1 Apartment adjusted from M4(2) to M4(3)(b), changed from 2b4p to 2b3p
- 2 Core amended to incorporate two lifts to accommodate M4(3) accessibility.
- 3 Apartment form amended to relfect adjacent core.
- 4 Minor amendments to accommodate core adjustments






Key Plan (NTS)


As Submitted As Amended



#### **Shared Ownership**

- 1 Cycles increased from 38no. to 40no. (40no. required)
- 2 Apartments adjusted to meet M4(3)(2)(a) Wheelchair Adaptable requirement
- 3 Entrance redesigned following comments
- > Window and door placements adjusted to suit
- > Landscape adjusted to suit







As Amended

### **Shared Ownership**

> Entrance amended to meet design comments and make more prominent



Block 6 Entrance Study



As Amended




# Terraces 2 & 3

#### Market Sale

> Change from Buff to Red brick to meet design comments



(M1)



(B2)

(B5)





London Studio 40 Norman Road, Greenwich, London SE10 9QX t. 020 8293 5175 Midlands Studio
Alpha Works, Alpha Tower
Suffolk Street Queensway
Birmingham B1 1TT
t. 0121 667 6175