

USE OF DRAWINGS

DO NOT SCALE FROM THIS DRAWING. USE WRITTEN DIMENSIONS AND CHECK ON SITE. THIS DRAWING IS BASED ON SITE INFORMATION SUPPLIED BY THIRD PARTIES AND ACCURACY OF EXISTING FEATURES IS NOT GUARANTEED. ANY ERROR, OMISSION OR DISCREPANCY NOTED ON OR BETWEEN DRAWINGS AND OTHER DOCUMENTS MUST BE REPORTED IN WRITING IMMEDIATELY. ALL MECHANICAL, ELECTRICAL AND STRUCTURAL LAYOUTS / COMPONENTS ARE INDICATIVE AND MUST BE DESIGNED AND CHECKED BY SPECIALISTS. DO NOT START WORK ON SITE BEFORE CONFIRMING THAT ALL NECESSARY STATUTORY AND OTHER CONSENTS HAVE BEEN OBTAINED. THIS DRAWING IS COPYRIGHT AND MUST NOT BE DISTRIBUTED WITHOUT PERMISSION. ELECTRONIC CAD FILES MUST NOT BE ALTERED OR COPIED.

REVISIONS

REV	DATE	DESCRIPTION	CHECKED
-	02.09.2022	INITIAL ISSUE	OC JF
A	26.05.2023	HISTORIC ENGLAND FOR COMMENT	JF JF

NOTE: SURVEY INFORMATION BY M.J. REES AND COMPANY LTD, CHARTERED LAND SURVEYORS

CODE REF.	CONDITION	REQUIRED ACTION
1	VERY GOOD	Minimal defects, preventative maintenance, little/no work required
2	GOOD	Minor deterioration, condition based maintenance and repair in-situ possible.
3	FAIR	Fair deterioration, material function impaired, repair in-situ possible or offsite unit repairs
4	POOR	Critical deterioration over a large portion of components, part replacement required
5	URGENT	Extreme failure has occurred throughout, replacement replicated to match.
6	N/A	No restoration works required as new intervention proposed

IN PROGRESS

KARSLAKE - EXISTING WINDOW SCHEDULE																	1685 - HAMPTON WATERWORKS	
REF.	WINDOW TYPE	LOCATION	WINDOW WIDTH	WINDOW HEIGHT	STRUCTURAL OPENING Wmm x Hmm / Arch Height	FIXED OR OPENABLE	INWARD OR OUTWARD OPENING	DESCRIPTION (WOOD, ALUMINIUM, IRON, UPVC)	GLAZING TYPE	VENT (Yes/No)	CONDITION EVALUATION	DAMAGE	PROPOSAL	SECONDARY GLAZING	OTHER COMMENTS	IMAGE REFERENCE	HERITAGE CONSULTANT RATING/COMMENTS	
W-01	TYPE 01/ WT-01	ELEVATION 1	1075	1275	1075 x 1275	OPENABLE	OUTWARD	TIMBER	SINGLE	N	3	PAINT DEFECTS	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-01. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-02	TYPE 01/ WT-01	ELEVATION 1	1095	1270	1095 x 1270	OPENABLE	OUTWARD	TIMBER	SINGLE	Y	4	TIMBER, PAINT DEFECTS	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	REMOVE VENTS & RE-GLAZE TO MATCH	W-02. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-03	TYPE 01/ WT-01	ELEVATION 1	1080	1270	1080 x 1270	OPENABLE	OUTWARD	TIMBER	SINGLE	N	3	PAINT DEFECTS	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-03. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-04	TYPE 01/ WT-01	ELEVATION 1	1080	1270	1080 x 1270	OPENABLE	OUTWARD	TIMBER	SINGLE	N	3	TIMBER, PAINT DEFECTS	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-04. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-05	TYPE 01/ WT-01	ELEVATION 1	1080	1270	1080 x 1270	OPENABLE	OUTWARD	TIMBER	SINGLE	Y	4/6	TIMBER, PAINT DEFECTS	REPLACED BY PROPOSED NEW DOOR, TYPE 18, D-50	NO	-	W-05. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-06	TYPE 02/ WT-02	ELEVATION 1	1050	730 / 900	1050 x 730 / 900	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	3/6	METAL RUSTED, PAINT DEFECTS	REPLACED BY PROPOSED NEW WINDOW TYPE 26, W-100	NO	-	W-06. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-07	TYPE 03/ WT-03	ELEVATION 1	1350	1885 / 2065	1350 x 1885 / 2065	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	Y	3	METAL RUSTED, PAINT DEFECTS	RETAINED / REPAIRED	YES	VENT REMOVED & RE-GLAZED	W-07. REFER TO 1685-A-605	MID-NINETEENTH CENTURY	
W-08	TYPE 04/ WT-04	ELEVATION 1	1345	1970 / 2215	1345 x 1970 / 2215	FIXED	N/A	METAL	SINGLE	Y	3	METAL RUSTED, PAINT DEFECTS	RETAINED / REPAIRED	YES	VENT REMOVED & RE-GLAZED	W-08. REFER TO 1685-A-605	MID-NINETEENTH CENTURY	
W-09	TYPE 04/ WT-04	ELEVATION 1	1345	1970 / 2215	1345 x 1970 / 2215	FIXED	N/A	METAL	SINGLE	N	3	METAL RUSTED, PAINT DEFECTS	RETAINED / REPAIRED	YES	-	W-09. REFER TO 1685-A-605	MID-NINETEENTH CENTURY	
W-10	TYPE 05/ WT-05	ELEVATION 1	1345	890 / 1135	1345 x 890 / 1135	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	3/6	METAL RUSTED, PAINT DEFECTS	NEW DOOR TYPE 19, D-51 & NEW WINDOW TYPE 27, W-101	NO	-	W-10. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-11	TYPE 03/ WT-03	ELEVATION 1	1345	1925 / 2105	1345 x 1925 / 2105	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	Y	3	METAL RUSTED, PAINT DEFECTS	RETAINED / REPAIRED	YES	VENT REMOVED & RE-GLAZED	W-11. REFER TO 1685-A-605	MID-NINETEENTH CENTURY	
W-12	TYPE 06/ WT-06	ELEVATION 2	1350	1905 / 2150	1350 x 1905 / 2150	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	3/6	METAL RUSTED, PAINT DEFECTS	DEMOLISHED FOR PROPOSED EXTENSION	NO	-	W-12. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-13	TYPE 06/ WT-06	ELEVATION 2	1350	1905 / 2150	1350 x 1905 / 2150	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	4/6	METAL RUSTED, PAINT DEFECTS	DEMOLISHED FOR PROPOSED EXTENSION	NO	-	W-13. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-14	TYPE 07/ WT-07	ELEVATION 2	1405	1795 / 1945	1405 x 1795 / 1945	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-14. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-15	TYPE 07/ WT-07	ELEVATION 3	1405	1780 / 1940	1405 x 1780 / 1940	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-15. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-16	TYPE 07/ WT-07	ELEVATION 3	1405	1775 / 1935	1405 x 1775 / 1935	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-16. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-17	TYPE 07/ WT-07	ELEVATION 3	1405	1770 / 1935	1405 x 1775 / 1935	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-17. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-18	TYPE 08/ WT-08	ELEVATION 3	1515	2170 / 2370	1515 x 2170 / 2370	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	3	METAL RUSTED, PAINT DEFECTS	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-18. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-19	TYPE 08/ WT-08	ELEVATION 3	1515	2170 / 2370	1515 x 2170 / 2370	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	3/6	METAL RUSTED, PAINT DEFECTS	REPLACED BY PROPOSED NEW DOOR, TYPE 21, D-55	NO	-	W-19. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-20	TYPE 08/ WT-08	ELEVATION 3	1525	2170 / 2370	1525 x 2170 / 2370	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	3	METAL RUSTED, PAINT DEFECTS	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-20. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-21	TYPE 08/ WT-08	ELEVATION 3	1525	2170 / 2370	1525 x 2170 / 2370	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	3/6	METAL RUSTED, PAINT DEFECTS	REPLACED BY PROPOSED NEW DOOR, TYPE 21, D-56	NO	-	W-21. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-22	TYPE 08/ WT-08	ELEVATION 3	1525	2170 / 2370	1525 x 2170 / 2370	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	3	METAL RUSTED, PAINT DEFECTS	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-22. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-23	TYPE 08/ WT-08	ELEVATION 3	1525	2180 / 2360	1525 x 2160 / 2360	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	3	METAL RUSTED, PAINT DEFECTS	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-23. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-24	TYPE 08/ WT-08	ELEVATION 3	1525	2190 / 2350	1525 x 2150 / 2350	OPENABLE	INWARD + OUTWARD	METAL	SINGLE	N	3	METAL RUSTED, PAINT DEFECTS	REPLACED - NEW DOUBLE GLAZED ALUMINIUM	NO	-	W-24. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-25	TYPE 09/ WT-09	ELEVATION 3	1700	2665 / 2965	1700 x 2665 / 2965	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	4	METAL RUSTED, TIMBER PAINT DEFECTS	RETAINED / REPAIRED	YES	-	W-25. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-26	TYPE 09/ WT-09	ELEVATION 3	1700	2665 / 2965	1700 x 2665 / 2965	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	4	METAL RUSTED, TIMBER PAINT DEFECTS	RETAINED / REPAIRED	YES	-	W-26. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-27	TYPE 09/ WT-09	ELEVATION 3	1700	2665 / 2965	1700 x 2665 / 2965	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	4	METAL RUSTED, TIMBER PAINT DEFECTS	RETAINED / REPAIRED	YES	-	W-27. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-28	TYPE 09/ WT-09	ELEVATION 4	1700	2665 / 2965	1700 x 2665 / 2965	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	4	METAL RUSTED, TIMBER PAINT DEFECTS	RETAINED / REPAIRED	YES	-	W-28. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-29	TYPE 10/ WT-10	ELEVATION 4	1710	3050	1710 x 3050	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	4	METAL RUSTED, TIMBER PAINT DEFECTS	RETAINED / REPAIRED	YES	-	W-29. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-30	TYPE 10/ WT-10	ELEVATION 4	1710	2965	1710 x 2965	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	4	METAL RUSTED, TIMBER PAINT DEFECTS	RETAINED / REPAIRED	YES	-	W-30. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-31	TYPE 10/ WT-10	ELEVATION 4	1710	3050	1710 x 3050	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	4	METAL RUSTED, TIMBER PAINT DEFECTS	RETAINED / REPAIRED	YES	-	W-31. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-32	TYPE 11/ WT-11	ELEVATION 5	1700	1405 / 1700	1700 x 1405 / 1700	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	5/6	METAL RUSTED, TIMBER PAINT DEFECTS, GLAZED PANE MISSING	DEMOLISHED TO BECOME INTERNAL OPENING, GLAZED LINK TO EXTENSION.	NO	-	W-32. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-33	TYPE 10/ WT-10	ELEVATION 5	1710	2965	1710 x 2965	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	5	METAL RUSTED, TIMBER PAINT DEFECTS, GLAZED PANE MISSING	RETAINED / REPAIRED	YES	-	W-33. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-34	TYPE 10/ WT-10	ELEVATION 5	1710	2965	1710 x 2965	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	5	METAL RUSTED, TIMBER PAINT DEFECTS, GLAZED PANE MISSING	RETAINED / REPAIRED	YES	-	W-34. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-35	TYPE 10/ WT-10	ELEVATION 5	1710	2965	1710 x 2965	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	5	METAL RUSTED, TIMBER PAINT DEFECTS, GLAZED PANE MISSING	RETAINED / REPAIRED	YES	-	W-35. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-36	TYPE 09/ WT-09	ELEVATION 5	1700	2665 / 2965	1700 x 2665 / 2965	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	5	METAL RUSTED, TIMBER PAINT DEFECTS, GLAZED PANE MISSING	RETAINED / REPAIRED	YES	-	W-36. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-37	TYPE 12/ WT-12	ELEVATION 6	1405	3310	1405 x 3310	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	RETAINED / REPAIRED	YES	-	W-37. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-38	TYPE 12/ WT-12	ELEVATION 6	1405	3310	1405 x 3310	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	RETAINED / REPAIRED	YES	-	W-38. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-39	TYPE 12/ WT-12	ELEVATION 6	1405	3310	1405 x 3310	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2/6	NONE	REPLACED BY PROPOSED NEW WINDOW TYPE 26, W-120	NO	-	W-39. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-40	TYPE 12/ WT-12	ELEVATION 2	1380	3320	1380 x 3320	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	RETAINED / REPAIRED	YES	-	W-40. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-41	TYPE 12/ WT-12	ELEVATION 2	1405	3310	1405 x 3310	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	RETAINED / REPAIRED	YES	-	W-41. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-42	TYPE 12/ WT-12	ELEVATION 2	1405	3315	1405 x 3315	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	RETAINED / REPAIRED	YES	-	W-42. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-43	TYPE 11/ WT-11	ELEVATION 1	1695	1385 / 1680	1695 x 1385 / 1680	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	3	METAL RUSTED, TIMBER PAINT DEFECTS, GLAZED PANE MISSING	RETAINED / REPAIRED	YES	-	W-43. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-44	TYPE 11/ WT-11	ELEVATION 1	1695	1385 / 1680	1695 x 1385 / 1680	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	4	METAL RUSTED, TIMBER PAINT DEFECTS	RETAINED / REPAIRED	YES	-	W-44. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-45	TYPE 11/ WT-11	ELEVATION 1	1695	1385 / 1680	1695 x 1385 / 1680	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	4	METAL RUSTED, TIMBER PAINT DEFECTS	RETAINED / REPAIRED	YES	-	W-45. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-46	TYPE 10/ WT-10	ELEVATION 1	1725	3050	1725 x 3050	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	5	METAL RUSTED, TIMBER PAINT DEFECTS, GLAZED PANE MISSING	RETAINED / REPAIRED	YES	-	W-46. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-47	TYPE 10/ WT-10	ELEVATION 1	1725	3050	1725 x 3050	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	5	METAL RUSTED, TIMBER PAINT DEFECTS, GLAZED PANE MISSING	RETAINED / REPAIRED	YES	-	W-47. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-48	TYPE 10/ WT-10	ELEVATION 1	1725	3050	1725 x 3050	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	5	METAL RUSTED, TIMBER PAINT DEFECTS, GLAZED PANE MISSING	RETAINED / REPAIRED	YES	-	W-48. REFER TO 1685-A-605	LATE-NINETEENTH CENTURY	
W-49	TYPE 12/ WT-12	ELEVATION 3	1405	3310	1405 x 3310	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	RETAINED / REPAIRED	YES	-	W-49. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-50	TYPE 12/ WT-12	ELEVATION 3	1405	3305	1405 x 3310	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	RETAINED / REPAIRED	YES	-	W-50. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-51	TYPE 12/ WT-12	ELEVATION 3	1405	3305	1405 x 3310	OPENABLE	INWARD + OUTWARD	METAL / UPVC	SINGLE	N	2	NONE	RETAINED / REPAIRED	YES	-	W-51. REFER TO 1685-A-605	EARLY-TWENTIETH CENTURY	
W-52	TYPE 10/ WT-10	ELEVATION 3	1710	2965	1710 x 2965	OPENABLE	INWARD + OUTWARD	METAL / TIMBER	SINGLE	N	5</							