



- The contractor is responsible for checking dimensions, tolerances and references.
Any discrepancy to be verified with the Architect before proceeding with the works.

- Where an item is covered by drawings to different scales the larger scale is to be worked to - Do not scale drawing. Figured dimensions to be worked to in all cases.

- The drawing information must be read in conjunction with all relevant scheme drawings, TECHNICAL NOTES drawings, specification and/or schedules referred to or not.

- True line of boundary and ownership to be established on site. Red line boundary extent to be confirmed by client.

drawn NA	38 Grange Avenue	purpose of issue SURVEY	Giovanna Daldello ARB RIBA ARCHITECT
scale @ A3 1:100	drawing Existing Loft & Roof Plan		gdaldello@icloud.com 07736506701
date 25.04.2024		38GA_PL03	0770000701