

- Marley 'Hawkins Staffordshire Blue' Clay roof tiles- raised to suit new insulation on existing sarking boards
- 2 New matching brick on edge undercloak detail to suit new insulation over sarking (raising tiles 150mm)
- 3 New zinc cladding with welted joints to new widened / insulated cheeks
- New replacement double glazed hardwood windows dark grey paint finish (replacing UPVC) 4
- New aluminium rainwater goods dark grey / black 5
- 6 New replacement rooflights
- Red dotted line denotes bays to be demolished
- 8 New arched openining with fixed / obscured glass painted hardwood window to conference room
- 9 Back of stage windows blocked up

- 10 New painted render finish to back elevation
- 11 New crittal style aluminium glazing system
- 12 New insulated warm roof system with dark grey EPDM membrane \*raised 150mm to suit insulation
- Coxdome rooflights omitted and replaced with new flat rooflights 13

TILE SPEC CHANGED

- 14 Obscure glass to WC windows
- 15 New flat rooflight
- 16 New warm dormer roof
- Ridge raised 150mm to suit new roof insulation



?/?/24 **REV A** BUILDING CONTROL 25/9/24 **REV B** FRONT DOOR DESIGN AMENDED, W6A OMITTED, REAR ELEVATION GLAZING DESIGN AMENDED

project CHARITY JOB - 10 CHURCH GROVE, HAMPTON WICK, KT1 4AL drwg title PROPOSED ELEVATIONS

drwg no. 326/GA/04B scale 1:100 @ A3 FEBRUARY 2024

