

14 HOLMES ROAD TWICKENHAM

JPRN: 100022338171
Area: 211.706

ORN: 0000037526
Perim: 79.342

EC 06/0558/EN/UBW

Officer: Miss Kristy Plant

Received: 24/11/2006

Status: Breach: UBW Unauthorised building works. Status: PCO Pending Consideration. .

Large dormer been built to the rear of the property.

BC 06/2284/BN

Officer: Mr Malcolm Hill
Loft conversion

Received: 25/10/2006

Status: Decision: No details . Status: BCO Building Work Complete.

BC 07/94322/CORGI

Officer: Officer with initials
installed a Gas Fire

Received:

Status: Decision: No details . Status: BCO Building Work Complete.

BC 07/97422/CORGI

Officer: Officer with initials
installed a Gas Boiler

Received:

Status: Decision: No details . Status: BCO Building Work Complete.

BC 06/6577/FENSA

Officer: Officer with initials FENS

Received:

Status: Decision: No details . Status: BCO Building Work Complete.

*FENSA Notification of Replacement Glazing comprising 14 Windows and 1 Doors.
installed by JK Windows Ltd. FENSA Member
No 19153. Installation ID 3965628. Invoice No 9316*

Report Ends.

40 Holmes Road Twickenham Middlesex TW1 4RE , TW1 4RE

UPRN: 100022338167
Area: 181.406 m²

ORN: 000ZC0KAPV000
Perimeter: 81.211 m

Ward: South Twickenham
BC Area:
DC Area:

Conservation Area: None

Shopping Frontage: None

Listed Buildings & BTMs: None

Tree Preservation Orders: None

UDP Overlays and Constraints:
No designations.

Report Ends.

07 / 1770 / HOT

40 Holmes Road Twickenham Middlesex TW1 4RE

UPRN: 100022338167
Area: 181.406

ORN: 000ZC0KAPV000
Perim: 81.211

BC 04/1544/BN
Officer: Mr Malcolm Hill
Repairs to roof structure

Received: 28/07/2004
Status: Decision: No details . Status: BST Building Work Started.

Report Ends.

07/1770/HOT