



1 2
3 4



Condition:
1. roofs
2. Prior's Screen

3-4. decayed render and water ingress





1 2
3 4

1. The Library 2. Turkish Boudoir 3. China Closet 4. Round Drawing Room



1 2
3 4
1. Long Gallery
2. Tribune
3. Great North Bed-chamber
4. Edwards' Tribune 1774



1 2
3 4

Condition:
1. painted glass
2. silk damask
3. joinery
4. 18c and 19c wallpapers