



LEGEND

- - - Structure and path to be demolished.
- Trees to be removed.
- Headstones and memorials proposed to be retained in position.
- Headstones and memorials proposed to be relocated.

Tree Categories

- A : Trees of high quality
- B : Trees of moderate quality
- C : Trees of low quality
- U : Trees in such a condition that they can not realistically be retained as living trees in the context of the current land use for longer than 10 years.

○ Tree root ball protection area

Note:
Tree numbers relate to the arboriculturalist's survey.

Architects and Conservation Consultants
3 King Street Cloisters, Clifton Walk
Hammersmith, London, W6 0GY

T : 020 8748 3755 F : 020 8748 3756
www.mrda.co.uk office@mrda.co.uk