

34 RICHMOND HILL RICHMOND , TW10 6QX

UPRN: 100022314698
Area: 168.124 m²

ORN: 0000075790
Perimeter: 74.667 m

Ward: Ham, Petersham && Richmond Riv
BC Area:
DC Area:

Conservation Areas: CA5 RICHMOND HILL

Shopping Frontage: None

Listed Buildings & BTMs:

1 Listed Bldg Ref: 22-/24/100

Grade: II

LANCASTER TERRACE

Tree Preservation Orders: None

UDP Overlays and Constraints:

View 0
Past Industrial Land Use

Part Only
Partly In 10m Buffer

Report Ends.

34 RICHMOND HILL RICHMOND

UPRN: 100022314698
Area: 168.124

ORN: 0000075790
Perim: 74.667

DC 06/1473/HOT Received: 10/05/2006
Officer: Miss Amelia Smith Status: No Decision ().
Demolition of rear conservatory and replacement. Single storey double garage to rear. First floor extension infill. Refurbishment of roof and dormer casement window.

BC 05/1460/RG Received: 18/07/2005
Officer: G Sumpter Status: Decision: No details . Status: BCO Building Work Complete.
Alterations to remove internal dormer cheeks and installation of en-suite shower room in existing loft room.

BC 05/1458/RG Received: 18/07/2005
Officer: M Jennings Status: Decision: No details . Status: BST Building Work Started.
Conservatory

DC 94/1706/DD01 Received: 27/03/1996
Officer: Mr J Sperryn Status: GTD granted permission 30/05/1996 ().
Details Pursuant To Condition Lb08 (joinery Details) Of Listed Building Consent 94/1706/lbc Dated 7/9/94.

DC 95/0045/FUL Received: 10/01/1995
Officer: Mr J Sperryn Status: GTD granted permission 16/03/1995 ().
Erection Of Rear Conservatory

DC 94/1706/LBC Received: 14/07/1994
Officer: Mr Christopher Tankard Status: GTD granted permission 07/09/1994 ().
Erection Of Rear Conservatory.

DC 90/0843/FUL Received: 11/05/1990
Officer: Unknown Status: REF refused permission 29/06/1990 ().
Retention Of Satellite Dish On Rear Roof Dormer.

DC 89/1098/S94 Received: 17/05/1989
Officer: Unknown Status: UNK Unknown - historic data transfers 05/07/1989 ().
Use As Maisonette & Flat.

Report Ends.