



Plate 13: Slight wear in goal mouth – Pitch 4



Plate 14: Undulation > 25mm depth – centre circle




Plate 15: Minor undulation <5 mm



Plate 16: Patchy grass colour – cricket outfield

5.2 Pitch Maintenance

Based on our observations, evidence was seen for the following maintenance operations:

- Mowing – grass height is reasonably consistent in each area inspected
- Verti-draining/spiking – tine voids seen in rugby pitches and football pitches
- Marking-out – Measurements were being taken by groundsmen on the rugby pitches at the time of the visit



Plate 18: Verti-drain holes



Plate 19: Measured depth of vert-drain hole 210mm