
Site +6.42 +4.97 Existing Ditch Retained **Existing Bund** Riverside Reprofiled Existing Soil Walkway Retained Thames Imported Topsoil Over Subsoil

Section A indicating imported top soil over existing site soil. Red line indicates existing site levels.



B 06.03.2019 SC

Revised tree proposals Additional bicycle parking Upper BulldIng Level Reduced

Bicycle racks path extended

A APPROVED

B - APPROVED WITH COMMENTS
C-DOING USE

Red and Yellow

Red
Wellow

Red
Wellow

Red
CHION RED

Wilder associates
URBAN & ENVIRONMENTAL LAND PLANNING
7th Roor, Book 2, Etisbeeth House
T,020,0503,2260