



CATEGORY AND DEFINITION	
Trees unsuitable for retention	
Category U	Trees in such condition that they cannot realistically be retained as living trees in the current land use for longer than 10 years
Trees to be considered for retention	
Category A	Trees of high quality with an estimated remaining life expectancy of at least 40 years
Category B	Trees of moderate quality with an estimated remaining life expectancy of at least 20 years
Category C	Trees of low quality with an estimated remaining life expectancy of at least 10 years, or young trees with a stem diameter below 150mm
NOTE:	
Hayden's Arboricultural Consultants were provided with a Topographical Survey but these do not always show the positions of all the trees/features on site. The locations of any additional features have been fixed using GPS. As such the position of the trees/landscape features should not be taken as exact but gives a fair distribution of their locations on site.	
The position, condition, and dimensions of the trees are based on a site survey undertaken on 08/08/18	
"The original of this drawing was produced in colour - a monochrome copy should not be relied upon"	
Scale 1:1000	
0m 20m 40m 60m 80m	
Rev:	Date: By: Revision:
-	14/02/20 KFH Based on RPS drawing no. JK03019_01-05A and ALA46L001H Construction PLANNING
A	30/04/20 KFH Drawing updated to omit 'No Dig' details. Method Statement Flow Chart updated to include 'Critical Monitoring Point' for installation of root barrier at edge of the MUGA and within the RPA of T021
B	29/06/20 DH Drawing updated to show progress of tree works

LEGEND	
	Existing Tree/Hedge BS 5837:2012 Category B
	Existing Tree/Hedge BS 5837:2012 Category C
	Existing Tree/Hedge BS 5837:2012 Category U
	Line of Root Protection Area (RPA) - calculated following guidelines set in BS 5837:2012
	Existing Tree/Hedge to be Removed BS 5837:2012 Category U
	Existing Tree/Hedge BS 5837:2012 Category U Removal recommended if agreed by owner of tree
	Existing Tree/Hedge to be removed to allow for development BS 5837:2012 Category C
	Existing Tree/Hedge to be crown lifted to allow for development
	Additional feature which doesn't meet BS 5837:2012 categorisation but is included for reference
	Location of boundary fencing positioned as per discussions at meeting on 19/06/19

