Spatial Search Report Generated on 10/10/06 at 16:20:13 by REBECCA SHILSTONE

HMOND HILL RICHMOND, 1W10 6QX

UPRN: 100022314698 Area: 168,124 m²

ORN: 0000075790 Perimeter: 74.667 m

Ward:

Ham, Petersham & Richmond Rive

BC Area: DC Area:

Conservation Areas:

CA5 RICHMOND HILL

Shopping Frontage:

None

Listed Buildings & BTMs:

Ref: 22-/24/100 Listed Bldg

Grade: II

LANCASTER TERRACE

Tree Preservation Orders: None

UDP Overlays and Constraints:

Past Industrial Land Use

0

Part Only Partly In 10m Buffer

Report Ends.



34 RICHMOND HILL RICHMOND

UPRN: 100022314698

Area: 168.124

ORN: 0000075790 Perim: 74.667

DC 06/2589/HOT

Received: 07/08/2006 Status: No Decision ().

Officer: Not Assigned Replacement of rear conservatory, rear double garage, infill to 1st floor, refurbish roof, dormer and casement window.

Received: 16/05/2006

Officer: Miss Astra Spyrou

Status: WDN withdrawn by the applicant 26/09/2006 (WDN).

Demolition of rear conservatory and replacement. Single storey double garage to rear. First floor etension infill.

Refurbishment of roof and dormer casement window.

DC 06/1473/HOT

DC 06/1553/LBC

Received: 10/05/2006

Officer: Miss Astra Spyrou

Status: WDN withdrawn by the applicant 26/09/2006 (WDN).

Demolition of rear conservatory and replacement. Single storey double garage to rear. First floor etension infill.

Refurbishment of roof and dormer casement window.

BC 05/1460/RG

Received: 18/07/2005

Officer: G Sumpter

Status: Decision: No details . Status: BCO Building Work Complete.

Alterations to remove internal dormer cheeks and installation of en-suite shower room in existing loft room.

BC 05/1458/RG

Received: 18/07/2005

Officer: M Jennings

Status: Decision: No details . Status: BST Building Work Started.

Conservatory

DC 94/1706/DD01

Received: 27/03/1996

Status: GTD granted permission 30/05/1996 ().

Officer: Mr J Sperryn Details Pursuant To Condition Lb08 (joinery Details) Of Listed Building Consent 94/1706/lbc Dated 7/9/94.

DC 95/0045/FUL

Received: 10/01/1995

Officer: Mr J Sperryn

Status: GTD granted permission 16/03/1995 ().

Erection Of Rear Conservatory

Officer: Mr Christopher Tankard

DC 94/1706/LBC

Received: 14/07/1994

Status: GTD granted permission 07/09/1994 ().

Erection Of Rear Conservatory.

DC 90/0843/FUL

Received: 11/05/1990

Officer: Unknown

Status: REF refused permission 29/06/1990 ().

Retention Of Satellite Dish On Rear Roof Dormer.

DC 89/1098/S94

Received: 17/05/1989

Officer: Unknown

Status: UNK Unknown - historic data transfers 05/07/1989 ().

Use As Maisonette & Flat.

Report Ends.