



Figure 84 to 87: Cast-iron columns, entablature and metal staircases (all medium significance)



Figure 90: Re-located primary door on middle mezzanine (cylinder) floor (see Figure 81 above)



Figures 88 to 89: Beam loft floor and spring beams, gantry and cast-iron windows (all high significance)





Figures 91 to 94: Cast-iron Blakesborough level indicators (two of, ex-situ) (high significance)



Figures 95 to 97: Beam loft floor and spring beams, cast-iron windows, gantry and roof (all high significance)





Figure 98: Hand-cranked gantry traveller (high significance)



Figures 99: Header tank on welded steel supports (no significance)



Figures 101: Stencilled "Large Condenser Tubes" (one of two) (high significance)



Figures 100: Header tank on welded steel supports (no significance)