



Figure 144: Storehouse exterior with cottage roof and chimney pots evident behind.



Figure 145: Ridge detail on Store house






Figure 146: Brick piers showing principal vehicle and pedestrian entrance adjacent to Cottages and Ruston Boiler House, (high significance)



Figure 147: Detail of listed railings on Upper Sunbury (high significance)



Figure 147: Historical photo showing arrangement of main entry to the site.



Figure 146: Timber fence to be reinstated to match historic precedent.