



Figures 147-149: Painted, cast iron piers of medium - high heritage interest. Palisade fence considered to be intrusive and later brick wall considered to be of neutral heritage value. The smaller size of these piers demonstrates the historic hierarchy of circulation in to and out of the site.