


© David Morley Architects  
 Do not scale off drawing.  
 Check all dimensions on site and advise any discrepancies before commencing work.  
 All dimensions in millimetres unless otherwise noted.



Key  
 Tree survey information provided by Canopy Consultancy and dated 22/09/20. Refer to tree survey for full information.

- Category A Tree Excellent/ Very Good
- Category B Tree Good
- Category C Tree Average or Poor
- Category U Tree Unsuitable/ Dying/ Dangerous
- Root Protection Zone
- Site Boundary

Rev.	Date	Description
P5	09/04/24	Tree Survey Updated
P4	01/02/23	Site Boundary Updated
P3	17/01/23	Site Boundary Updated
P2	10/05/21	Site Boundary Updated
P1	28/01/21	First Issue

**DavidMorleyArchitects**

5 Clarendon Road London N22 6XJ  
 T +44 (0)20 7430 2444  
 davidmorleyarchitects.co.uk

Project  
 Roehampton Gate, Richmond Park  
 Client  
 The Royal Parks

Title  
 Roehampton Restoration Project - Tree Survey Plan

Project / Drawing No	Revision
732-00-006	P5
Date	Scale
09/04/2024	1:1000 @ A3

Richmond Park  
 Golf Course